Models LD - Defender

Title Defender Front and Rear Propshaft Grease Points

Last Modified 30-MAR-2009 08:27

Category Noise/ Vibration

Symptom 703000 Vibration Concerns

<u>Issue:</u> Loose or missing front / rear propshaft grease nipples for Defender 07 MYonward vehicles.

Action: If any propshafts are identified where the grease nipples are missing, then the propshaft should be replaced.

Any cases where the grease nipples are in place but loose should be torqued to:

8Nm + 45degrees.