SUBROUTINE: GET NEXT CHARACTER (420 CODE VERSION)

CTECH ENTRY

(BUE) - PICK UP CHARACTER FROM BUFFER
FOR CURRENT OUTPUT DEVICE.

STORE IN NEXT CH.

BUFLAG TRUE" 64A

YES

(INPUT BUFFER EMPTY)

GECH3&

BUFLAG = "FALSE"

ERROR NUMBER = O

HALTMK := "CLEAR".

SET STURAGE AUBRESSES FOR INPUT
BUFFER TO INITIAL VALUES (FOR
STORING AND RETRIEVING).

SET POSITION COUNTS FOR
STORING AND RETRIEVING.

61N







