## COLLAPSE FORMAL PARAMETERS (FCLAPS)

This subroutine is called from the delimiter;, such as in the following example:

At this stage the name list will look like this block stopper

P <-- value of NLP (which was stacked with proc begin)

a

b

C

The block stopper is erased, and for type procedures a check made that an assignment has been made to the procedure identifier during the procedure body.

The V bit in the procedure name list entry is cleared, as we are now no longer in the procedure body and recursion cannot occur. WM is set and a warning message is given for every parameter not used, as these parameters are inspected and condensed to one-word entries containing type and whether by value or not.

## ERRORS

FAIL 16; No assignment to type procedure identifier.