Part 4)

idea: Joyetick controlled servo w/ active/inactive indication LED. Sytem turned on & off via pushbutton


volatile slobal variables for: main in cog &

Joystick in cog 1

servo in cog 2

LED in cog 3

Push butten in cog 4



Joystick range 0-5V, serve range 0-180 degrees (0-1800) \Rightarrow degrees (0-1800)