Calibrating Span Pressure Gauge measured pressure [bar] p meas = (0.7+/-0.08)*p + 0.14+/-0.46data 0 actual pressure [bar]