ε	2	Black	еир	pu၅	еир	В GN	еир	18	8
9	ı	Red	οοV	οοV	οοV	οοV	nIA	Bt / Mh	L
				-Λ	-soj	B-	-soɔ	ЯĐ	9
L	9	Brwn	1	+M		+Z	+ì9A	BI/MP	9
Þ	9	Blue	2	-W		-Z	-ìəЯ	ВІ	Þ
				+Λ	+so3	B+	+so3	Gr/Wh	3
				-O	-ni2	-A	-ni2	6O	2
				+0	+ui2	+A	+ui2	чм/60	ŀ
Omron	Yask	Sanyo	e JiM	WVU	qq√r	Enc	Res	Colour	niq
Feedback Connectors									

GND T.IN

LBO

FB1

CWD

 $\verb|www.github.com/rene-dev/stmbl|$

STMBL GGSZZSZZ

N2B

GND 24V OUT0 **24V** OUT1 **24V** OUT2 **24V**

30-350V MOTOR + - W V U

Command Connector								
Pin	Colour	Smart-Serial	Step-Dir	Quadrature				
1	Og/Wh	RX+	Step+	A+				
2	Og	RX-	Step-	A-				
3	Gr/Wh	TX+	Dir+	B+				
4	BI		Err-					
5	BI/Wh		Err+					
6	Gr	TX-	Dir-	B-				
7	Br/Wh		Enable+					
8	Br		Enable-					