Thakkar Auto Works

18, Aurora Chowk, Alappuzha 174596
GSTIN: 06UC5905K1Z2 | Ph: 8657809134

Invoice No.	INV/783/26	**Date**	2026-10-23
Customer	Aarnav Mandal	**Vehicle**	Maruti Suzuki Baleno Zeta
Reg. No.	HR78BE4492	**Job Card**	JC/3200

#	Description	Amount (Rs.)
1	Rear Bumper - replacement	8,270
2	Windshield - replacement	11,000
3	Taillight - replacement	4,000
4	Painting and finishing	8,270
5	Labour charges	4,690
Subtotal		**36,230**
GST @ 18%		**6,521**
Total Payable		**42,751**

Payment due on delivery. Warranty on replaced parts as per manufacturer terms. This is a computer-generated invoice.