Saxena Auto Works

H.No. 585, Rao Nagar, Jhansi-713900
GSTIN: 06ZK2771H1Z7 | Ph: +919318393352

Invoice No.	INV/263/26	**Date**	2026-10-24
Customer	Deepa Chokshi	**Vehicle**	Kia Seltos HTK
Reg. No.	HR70NF4981	**Job Card**	JC/1634

#	Description	Amount (Rs.)
1	Rear Bumper - replacement	7,810
2	Painting and finishing	2,450
3	Labour charges	1,370
Subtotal		**11,630**
GST @ 18%		**2,093**
Total Payable		**13,723**

Payment due on delivery. Warranty on replaced parts as per manufacturer terms. This is a computer-generated invoice.