Kurian Auto Works

51/712, Ranganathan Ganj, Mysore-048175
GSTIN: 06VX5088V1Z2 | Ph: 09651370985

Invoice No.	INV/315/26	**Date**	2026-06-24
Customer	Chandran Taneja	**Vehicle**	Kia Seltos HTK
Reg. No.	HR64IF1158	**Job Card**	JC/6794

#	Description	Amount (Rs.)
1	Front Bumper - replacement	9,090
2	Clutch plate wear - replacement	6,500
3	Grille - replacement	2,760
4	Fender - replacement	6,170
5	Painting and finishing	7,470
6	Labour charges	5,580
Subtotal		**37,570**
GST @ 18%		**6,763**
Total Payable		**44,333**

Payment due on delivery. Warranty on replaced parts as per manufacturer terms. This is a computer-generated invoice.