Dyal Auto Works

H.No. 99, Balasubramanian Chowk, Dehradun 201533
GSTIN: 06NW8450R1Z2 | Ph: 8444310698

Invoice No.	INV/225/26	**Date**	2026-03-16
Customer	Inaya Kunda	**Vehicle**	Maruti Suzuki Swift VXi
Reg. No.	HR37FM8264	**Job Card**	JC/4475

#	Description	Amount (Rs.)
1	Rear Bumper - replacement	8,270
2	Windshield - replacement	11,880
3	Painting and finishing	6,980
4	Labour charges	2,840
Subtotal		**29,970**
GST @ 18%		**5,395**
Total Payable		**35,365**

Payment due on delivery. Warranty on replaced parts as per manufacturer terms. This is a computer-generated invoice.