Basu Auto Works

43, Bhatia Road, Jalandhar 586938
GSTIN: 06BM1046Q1Z5 | Ph: 08793741608

Invoice No.	INV/907/26	**Date**	2026-09-20
Customer	Mitesh Bhagat	**Vehicle**	Maruti Suzuki Swift VXi
Reg. No.	HR41FO3063	**Job Card**	JC/3370

#	Description	Amount (Rs.)
1	Rear Door - replacement	12,420
2	Clutch plate wear - replacement	6,500
3	Painting and finishing	5,340
4	Labour charges	4,110
Subtotal		**28,370**
GST @ 18%		**5,107**
Total Payable		**33,477**

Payment due on delivery. Warranty on replaced parts as per manufacturer terms. This is a computer-generated invoice.