
XJTU-SY
FEMTO
IMS
indicator shift at the alarm
(baseline standard deviations)
100
30
10
5
3
2
1
0.5
3sig_rms
ma3sig
ma5sig
ma2sig
ewma
cusum
detector rule
control chart
onset inside the baseline
median
3 standard deviations