A350

TEMPORARY REVISION TR132 issue 1 ELEVATOR FAILURE DURING FLARE A350-1000

AIRPLANE FLIGHT MANUAL

The content of this document is the property of Airbus. It is supplied in confidence and commercial security on its contents must be maintained. It must not be used for any purpose other than that for which it is supplied, nor may information contained in it be disclosed to unauthorized persons. It must not be reproduced in whole or in part without permission in writing from the owners of the copyright.

© AIRBUS 2005. All rights reserved.

Intentionally left blank

FOR INFORMATION ONLY DO NOT USE FOR OPERATIONAL PURPOSE

PRELIMINARY PAGES

Intentionally left blank

FOR INFORMATION ONLY DO NOT USE FOR OPERATIONAL PURPOSE

PRELIMINARY PAGES TABLE OF CONTENTS

A350 AIRPLANE FLIGHT MANUAL

APPRO APPROVAL DATA	
APPRO-TR TEMPORARY REVISIONS	
Elevator Failure During Flare A350-1000	A
LIM LIMITATIONS	
LIM-WGHT WEIGHTS AND LOADING	
Minimum Weight for Landing	A
LIM-OPS OPERATIONAL PARAMETERS	
Tailwind for LandingFinal Approach Slope	
Final Approach Slope	E
LIM-27 FLIGHT CONTROLS	
Slats/Flaps Configuration	A
NORM NORMAL PROCEDURES	
NORM-LDG APPROACH AND LANDING	
Minimum Approach Speed	Α

A350 AIRPLANE FLIGHT MANUAL

PRELIMINARY PAGES TABLE OF CONTENTS

APPROVAL DATA TEMPORARY REVISIONS

A350 AIRPLANE FLIGHT MANUAL

TR132 Issue 1 **ELEVATOR FAILURE DURING FLARE A350-1000**

Ident.: TDU / APPRO-TR-00025975.0001001 / 29 APR 22

EASA APPROVED

Criteria: (350-1000) and (((115496)))

Impacted DU: NONE

APPROVAL REFERENCE

APPROVED BY: EASA Approval date: 29 APR 22 Approval reference: 10079138

Do not remove this Temporary Revision until instructed to do so.

Reason for issue: This Temporary Revision is issued to implement limitations and procedures

in order to mitigate the risk of elevator failure during flare.

Applicable to: A350-1000 aircraft equipped with FCGS X13

This Temporary Revision is made up of the following Temporary Documentary Units:

APPRO-TR-00025975.0001001/29 APR 22 LIM-WGHT-00025976.0002001/29 APR 22 LIM-OPS-00025979,0001001/29 APR 22

LIM-OPS-00025980.0001001/29 APR 22 LIM-27-00025977.0001001/29 APR 22 NORM-LDG-00025983.0001001/29 APR 22

A350 AIRPLANE FLIGHT MANUAL

APPROVAL DATA TEMPORARY REVISIONS

A350 AIRPLANE FLIGHT MANUAL

LIMITATIONS WEIGHTS AND LOADING

EASA APPROVED

MINIMUM WEIGHT FOR LANDING

Ident.: TDU / LIM-WGHT-00025976.0002001 / 29 APR 22

Criteria: (350-1000) and (((115496)))

Impacted DU: NONE

Belongs to TR132 Issue 1

Minimum landing weight: 145 000 kg (319 670 lb)

A350 AIRPLANE FLIGHT MANUAL

LIMITATIONS WEIGHTS AND LOADING

LIMITATIONS **OPERATIONAL PARAMETERS**

A350 AIRPLANE FLIGHT MANUAL

TAILWIND FOR LANDING

Ident.: TDU / LIM-OPS-00025979.0001001 / 29 APR 22

EASA APPROVED

Criteria: (350-1000) and (((115496))) Impacted DU: 00020398 Belongs to TR132 Issue 1

Maximum tailwind for landing: 10 kt.

FINAL APPROACH SLOPE

Ident.: TDU / LIM-OPS-00025980,0001001 / 29 APR 22

EASA APPROVED

Criteria: (350-1000) and (((115496)))

Impacted DU: NONE Belongs to TR132 Issue 1

Maximum published final approach slope: 3.25 °

A350 AIRPLANE FLIGHT MANUAL

LIMITATIONS **OPERATIONAL PARAMETERS**

LIMITATIONS FLIGHT CONTROLS

A350 AIRPLANE FLIGHT MANUAL

SLATS/FLAPS CONFIGURATION

Ident.: TDU / LIM-27-00025977.0001001 / 29 APR 22

EASA APPROVED

Criteria: (350-1000) and (((115496))) Impacted DU: NONE Belongs to TR132 Issue 1

Landing with flaps FULL is prohibited.

Note: In case of abnormal or emergency procedures impacting the landing configuration, use the landing configuration provided in the abnormal or emergency procedures.

A350 AIRPLANE FLIGHT MANUAL

LIMITATIONS FLIGHT CONTROLS

NORMAL PROCEDURES APPROACH AND LANDING

A350 AIRPLANE FLIGHT MANUAL

MINIMUM APPROACH SPEED

Ident.: TDU / NORM-LDG-00025983.0001001 / 29 APR 22

EASA APPROVED

Criteria: (350-1000) and (((115496)))

Impacted DU: NONE Belongs to TR132 Issue 1

■ When landing weight is below or equal to 170 000 kg (374 786 lb):

Minimum approach speed: VLS + 10 kt

■ When landing weight is above 170 000 kg (374 786 lb):

Minimum approach speed: VLS + 5 kt

In case of abnormal or emergency procedures impacting the approach speed, use the Note: approach speeds provided in the abnormal or emergency procedures.

A350 AIRPLANE FLIGHT MANUAL

NORMAL PROCEDURES APPROACH AND LANDING