Version History

SDK

Version	Changed
3.2.6	UHFAPI version 2.9.4.1
	uhfrfid version 1.2.3.5
	rfidtx version 1.8.3.1
	R900LIB version 1.2.1.1
	rfidhost version 1.4.3.1
	UHFAPI_NET version 1.1.1.1
	R900APP_NET version 1.1.1.1
3.2.5	UHFAPI version 2.8.10.1
	uhfrfid version 1.2.3.3
	rfidtx version 1.7.3.1
	R900LIB version 1.2.1.1
	rfidhost version 1.4.1.2
	UHFAPI_NET version 1.1.1.1
	R900APP_NET version 1.1.1.1
3.2.4	UHFAPI version 2.8.9.1
	uhfrfid version 1.2.3.3
	rfidtx version 1.7.2.1
	R900LIB version 1.2.1.1
	rhidhost version 1.4.1.1
	UHFAPI_NET version 1.1.1.1
	R900APP_NET version 1.1.1.1
3.2.3	UHFAPI version 2.8.9.1
	uhfrfid version 1.2.3.2
	rfidtx version 1.7.1.1
	R900LIB version 1.2.1.1
	rhidhost version 1.4.1.1

UHFAPI

Version	Changed
2.9.4.1	1. Inventory report mode reset bug fix
2.9.3.1	1. enable access timeout error repoting
2.9.2.1	1. remove maximum attenuation limit check
2.9.1.1	1. wce power resume notification activation
2.8.11.1	1. stop operation when close() called

2.8.10.1	1. "data abort" on waited read API is fixed .
2.8.9.1	1. Open function speed up
	2. Inventory default target id revert to A to increase inventory speed.
	3. Stop api changed to fix endless waiting case.
2.8.6.1	1. Fix Japan non-LBT mode initialization problem.
	2. Activate Japan non-LBT mode channel off capability.
2.8.4.1	1. Fix api locking for invalid parameter.
	2. Activate default band channel off capability.
	3. Remove debug log generation.
2.8.3.3	First release

uhfrfid

Version	Changed
1.2.3.5	1. Api add for engineering
1.2.3.4	none
1.2.3.3	1. Separate rfidtx.dll from the dll.
	2. Fix default band parameter initialization.
1.2.2.7	1. Fix module parameter initialization
1.2.2.2	First release

rfidtx

Version	Changed
1.8.3.1	1. Bluetooth connection bug fix.
	2. Bluetooth port occupation problem fix.
1.8.2.1	none
1.8.1.1	none
1.7.3.1	1. Remote access is possible during the local operation.
1.7.2.1	1. Fix USB connection problem.
	2. Fix WinCE device connection problem.
1.7.1.1	1. Enhance module synchronization method to reduce
	2. Support module firmware version 1.4.5 and prior.
1.1.0.1	First release

R900LIB

Version	Changed
1.2.1.1	1. Protect nested API function call.

1.2.0.1	1. Fix reader inventory list clearing API function.
	2. Enhance reader detach detection method.
1.1.1.1	First release

rfidhost

Version	Changed
1.4.3.1	1. rearrange code for BTH_RDR_API compile option
1.4.2.1	1. add GetOperationParameters().
	2. bug fix. inventory parameter change after access or config.
1.4.1.2	1. upload inventoried tag information.
	2. ignore trigger event if not ready.
1.4.1.1	1. Improve reader trigger button tracking.
1.3.9.2	1. Increase Tag EPC memory size.
1.3.8.1	first release

UHFAPI_NET

Version	Changed
1.1.1.1	1. change import prototypes
1.0.0.0	first release

R900APP_NET

Version	Changed
1.1.1.1	1. Add access sample.
	2. Add comport selection sample into demo application.
1.0.0.0	first release