## Order No.WOI-FON-SAP/23-24/0002915288/24

## Maheen Label Tex Limited JOB DOCKET



JOB DOCKET NO.			JC/22-23/0881			JOB I	DOCKET	CKET DATE 04/11/2023							
JOB NAME				ORD. QTY	PRINT QTY	PRINT	PRINT QTY WITH WASTAG		AGE C	IMENSION	IS Prod.	Туре	WO NO		
NATURANA COT	50	50		3168	168		35 x 35 x	0 Stic	cker	SAP/23-24/00029-					
ERP Order No.	RP Order No. PONO PODate PRODUCT						JCT CODE	<b>.</b>	RE-PRINT						
WOI-FON-SAP/2	ON-SAP/23-24/0002915288/24 01-11-23 NATURANA COTTON TAG						-02								
Buyer NAME						Las	t Job Deta	ail							
Collar Flap		 )	Side Pa	ste	Ic	0.00			Tuck F	lap					
JOBCARD REMAI	RKS	-	ļ.							<u> </u>					
WO REMARKS	+														
FP REMARKS															
MASTER DOCID					FG	Stock	(			0					
					DELIVERY	DETAILS	S								
COMPANY NAME		HEEN						Qty :	0.00 De	elivery Date	e:01/11/2023				
ADDRESS	Mah	een label Tex									•	•			
			Product Name						der Qty Extra Qt		Print Qty			Final Job Qt	
		NATURAN	NA COTTON TA	G -02				50		0	50	2880	)	2930	
			Board Dat	aila	PAPER DI	IAILS				LIDE	· Cu	FETC		KG	
	Board Details Offset Paper-Local-Otley-80 GSM-23 x 36 INCH-LON								UPS 288			SHEETS 11		0.47	
CUT SIZE		SUT SHEET	WASTAGE SHEET		SHEET U				<u> </u>			GE (%)			
36.00 X 23.00		3	30	3						33					
	1	INK FR			<u> </u>					INK B					
Impress Printing Consumable-Impress-0-AS PRE ORIGINAL						Impr	mpress Printing Consumable-Impress-0-AS PRE ORIGINAL								
				C	PERATION	DETAI	L								
OPERATION	OPERATION DETAIL			Machine Name			MR TIM	IE F	PROCESS TIM			REMAR	K		
Board Cutting				Poller-92E 36 inch										,	
PlateMaking No of PlateMaking		No of Plate		CTP			00:00:0		00:06:00						
0			1 PassNo:2	HP Indigo 7K			00:10:0		00:05:00						
Printing Details			= 1 PassNo : 2	HP Ind			00:10:0		00:05:00						
Coating Details Type :Aq			Matt (Full)	MOE-1: 1C: 18.5		29.5	00:40:0		00:00:17						
Punching Details Die No :				Manula 1			00:00:0	00	00:03:18		· ··				
Sorting Details		Oh : Dar Ch	·	Manual(SORTII Manual(PACKII			00.00.0	20	00.0		Sorting				
Packing Details Total		Qty Per Sh	ipper : 0.00	wanua	I(PACKIN	NG)	00:00:0	JU	00:00	0:00					
					Material R	equired									
Sr No	Item Name							Req. Qty				Unit			
	Offset Paper-Local-Otley-80 GSM-23 x 36 INCH-LONG							11 Sheets							
CREATED USE	•									1 - 1 - 1		AP	PRO	OVED BY	

Job Name: NATURANA COTTON TAG -02-35.00 Job Docket No.: JC/22-23/0881

			Size	e Brea	ık Do	wn Detail						
Jol	bNo	JobName		Barco		Style		Size		Qty		Size
		1				· · · · · · · · · · · · · · · · · · ·	ļ					
			SHEE	T CU	ΓΤΙΝ	G SECTION						
Date Shift M/C Name		M/C Name	Qty. of		Operator Name			P. Wastage	Rej. Destroyed Sign of			
				Sheets Cut				Of Ups	i	F	ore	man/ Sup.
			PR	RINTIN	IG S	ECTION						
Date Shift M/C Name			Qty.		Operator Name			P. Wastage	Prod. Qty. Verified & Rej.			
			1	Produced		Asst. Operator		Of Ups		Destroyed Sign of		
					Name		,		Foreman/Sup.			
			DE	NIN ITIN	10.0	FOTION						
Date	Shift	M/C Name				ECTION		D Wastage	Y NO	Drod	Otv	Varified & Pai
Date	Silit	IVI/C Name	Qty. Produced		Operator Name Asst. Operator		P. Wastage X NO. Of Ups		Prod. Qty. Verified & Rej.  Destroyed Sign of			
			Troduced		Name		J. 0,0		Foreman/Sup.			
		COAT	ING/ LAM	/INAT	ION/	SPOT UV S	EC	TION				
COATING	TVDE:	Г	Date Sh		ift M/C N		CN			ety. P. Wastage X NO.		
		ioned category					CIV			-		Of Ups
Tick the below mentioned category									11000000			O1 Op3
4.Off-line	Primer wit	h UV Gloss (Window / Spot)	· · · · · · · · · · · · · · · · · · ·			•						
5.Matt U\	/ / AQ											
LAMINAT	TON TYPE	i: (	Operator I	Name								
-	/ Matt/ Glo		Prod. Qty.	Verif	ied &	Rej. Destroy	/ed	Sign of Forem	an/ Sup	o. :		
2.Other S	pecial Coa	ating										
		NIF	PUNCHII	NG / F	MR	OSSING / FC	11 11(	NG				
Date	Shift	M/C Name	Qty.		Operator Name			P. Wastage X NO.		Prod. Qty. Verified & Rej.		
			Produced		Asst. Operator Name			Of Ups		Destroyed Sign of		
									Foreman/Sup.			

Job Name: NATURANA COTTON TAG -02-35.00 Job Docket No.: JC/22-23/0881

		FI	NAI DACK	(ING DETAILS	6 / OFFER GIVEN				
Date	Shift	Operator Name	NAL FACE		. Produced	P. Wastage X NO. Of Ups	Prod. Qty. Verified & Rej. Destroyed Sign of Foreman/Sup.		
			CONICION	IMENT ADDD	OVED BY Q.C.				
1 Poconci	iliation / Pr	ocess Wastage Check		NIVIENT APPRO	JVED BY Q.C.				
2.Material		ocess wastage check							
l	abel Check								
4.Quantity									
· -	uality Chec	k							
l	entation Do								
					Name 8	& Signature Of Q.C / 0	Q.A. Person		
			DISF	PATCH CHECK	K-POINTS				
1.Approve	ed Job Doc	ket							
2.COA Ap	proved								
3.Comme	rcial Label	Pasted							
4.Invoice	Сору								
5.Vehicle	Check (As	per checklist)							
6.Lading (	Chart								
7.Form (If	any )								
Date	Date Shift Dispatch by Dispatch qty Exc		Excess qty.	Desp. Qty. Verified and excess					
						destroyed sign of Fo	oreman / Supervisor		