

Job Card - Customer Copy

Job Card No: JOB-2026-0001	Open Date/Time: 10/05/2026 19:31	Claim No: CLM-2026-0002	SR Type: Accident
Gate In: 10/05/2026 19:31	Advisor: Anil Shinde	Expected Delivery: 22/05/2026 19:31	Current KM: 1


Customer Details		Vehicle Details	
Name	anil Shinde	Vehicle Reg No	MH01BB1234
Mobile	9274066211	Model	Swift
Address	adajan surat	Variant / Colour	VXI / W
GST		Chassis / Engine	BB1234 / BB1234

Vehicle Condition & Inventory


Normal Inventory	
Inventory Item Name's	Yes/No/No's
Jack	No
Tool Kit	No
Mud Flap	
Floor Mat	
LH Mirror	No
RH Mirror	No
Center Mirror	No
Battery	No
Stereo	No
Front Wiper	No
Rear Wiper	No
Extra Accessories	No

Tyre Inventory				
Pos	Make	Size	Depth	Wheel Cap
Front Left				
Front Right				
Rear Left				
Rear Right				
Stepney				

Vehicle Fuel Status



Vehicle Damage Marking



Customer Requests / Repair Advice					
Sr	Job Code	Repair Details	Std Hrs	Parts Estimate	Labour Estimate
1	lab123	r&r	1.00	-	650.00
Parts Total		1500.00	Labour Total		650.00
GST			Estimated Bill		

Repair Instructions

I authorize the dealer to execute the jobs using necessary material at my cost. I understand that the vehicle is being stored, repaired and tested at my risk.
Date & Time : Customer Sign

I certify that the work has been done to my satisfaction and I have taken the delivery of the vehicle. I have been offered old parts/salvage by dealership.

I have been offered old parts/salvage by dealership.

Customer Signature

Customer Signature

Date

Thank You!

Job Card - Workshop Copy

Job Card No: JOB-2026-0001	Open Date/Time: 10/05/2026 19:31	Claim No: CLM-2026-0002	SR Type: Accident
Vehicle Reg No: MH01BB1234	Current KM: 1	Advisor: Anil Shinde	Expected Delivery: 22/05/2026 19:31

Customer Details		Vehicle Details	
Name	anil Shinde	Model	Swift
Mobile	9274066211	Variant / Colour	VXI / W
Address	adajan	Chassis No	BB1234
City	surat	Engine No	BB1234

Repair Advice by Service Advisor

Sr	Complaint Code	Job Code	Repair Details / Instructions	Std Hrs	Parts Est.	Labour Est.
1	ACR	lab123	r&r	1.00	-	650.00

Spare Parts / Lubricants

Sr	Part No	Description	Qty	Rate	Amount
1	PARTNO123	BUMPER	1	1500.00	1500.00

Job Allocation

Team Leader		Technician	
Bay No		Repair Status	Assembly

Cost Summary

Parts Total	1500.00	Labour Total	650.00
GST		Net Total	

Repair Instructions

--

Add-on Jobs: 1. 2.	Pending Jobs: 1. 2.
---------------------------------	----------------------------------

Customer Signature	Service Advisor Signature	Team Leader Signature	Quality Inspector Signature
--------------------	---------------------------	-----------------------	-----------------------------