Basic Block Diagram of System

Display

Arduino Board → Solid State Relay → Motor Winding

Tachometer