
CHAPTER 1 STATISTICAL BACKGROUND

Instructor: Lena Ahmadi




Course notes are copyrighted material. © Professor Alex Penlidis.

This copy is for individual use only in connection with this course. It may not be resold or used to make additional copies.

Tel: (519) 888-4567 x36634, E-mail: penlidis@uwaterloo.ca

Major Topics

- Chapter 1: Statistical Background (Mb: CHAPTER 2)
- Chapter 2: Regression Analysis
- Chapter 3: Statistical Design of Exp
- Chapter 4:
 Design/Analysis of Single
 Experiments
- Chapter 5: Blocking
- Chapter 6: Multifactor Experiments
- Chapter 7: Multifactor Experiments
- Chapter 8: Concluding Remarks



Course Targets

- Collect data (process or product information)
- Information (info) on <u>error</u> (allows one to make comparisons!)
- Develop mathematical <u>models</u> (and check for validity of models)
- Why are the above steps useful?

Course Targets (cont'd)

- Process understanding! (only way to design/simulate)
- Process optimization!
- Product improvement (if one understands property characteristics!)
- Identification and control
- Model-based approaches!
- ... (sky is the limit!)

Review basic statistical concepts including:

- Random variables
- Experimental error and measurement
- Mean and variance
- Random sampling and sample statistics
- Normal distribution
- · Central limit theorem
- Confidence intervals
- t-distribution
- Hypothesis testing
- Variance ratio tests; X² and F-distributions

WHY STATISTICS?

- What role does statistics play in scientific endeavour?
- Historical origin: measurements related to the "state".
- Statistics deals with the gathering and the analysis of data.
- What quantities that you deal with have variability associated with them?
- Statistics helps us with decisionmaking in the face of uncertainty!

DECISION-MAKING

During the process of decision-making we are interested in <u>statistical inference</u> which is:

The process of stating something about a population based on a sample (drawn from the population)

Tools for the inference process:

Estimation / Confidence Intervals Hypothesis Testing

RANDOM VARIABLE

- A random variable is a chance quantity, i.e., a mathematical variable whose value is determined by chance.
- When we perform an experiment there will be <u>some</u> <u>unique value</u> of the random variable which will correspond to this outcome.
- The value of the random variable cannot be predicted with certainty, because the outcome of the experiment cannot be predicted with certainty.
- However, we can usually express some knowledge about the <u>possible values of the random variable</u>.
- A statement of the probabilities of all possible outcomes of a random variable is called the <u>probability distribution</u> (or probability density function).
- We differentiate between a continuous and a discrete random variable.

EXPERIMENTAL ERROR

- When an experiment is carried out under what are, as nearly as possible, the same conditions, the observed results are never quite identical. The fluctuations which occur are referred to as:
 - noise
 - experimental error or variation
 - "error' (bias, stochastic part, ...)
 - uncertainty, etc.
- In statistics, "error" is a <u>technical</u>, <u>emotionally</u> <u>neutral</u>, term. It refers to often uncontrollable variation and *does not* associate blame!
- Sources can include: measurement, analytical, sampling, ambient conditions, skill or alertness of personnel, age and purity of reagents, etc.
- An awareness of the potential sources and effects of experimental error is essential in the design and analysis of experiments
- Experimental error is a random variable!

EXPERIMENTAL DATA

- An experimental result or datum in scientific work is often a numerical measurement which describes the outcome of an experimental run (trial, treatment); e.g., yield for a chemical experiment.
- One very useful way of dealing with measurements is to hypothesize the following (simplest) model:

$$y_i = \mu + \varepsilon_i$$

 $y_i = \text{random variable representing the}$
experiment al data for the ith experiment.
 $\mu = \text{"true" value}$
 $\varepsilon_i = \text{random variable representing the}$
experiment al error for the ith experiment.

 The error ε cannot be predicted exactly, but can be dealt with using probability theory.

MEAN AND VARIANCE

- These are quantities used to summarize information about random variables and their probability distributions (probability density functions).
- The mean (μ) is a measure of location. As such it represents a "typical" value or the long-term average value of the random variable. It is also referred to as the arithmetic mean or expectation:

$$E(X) = \mu = \sum_{x} xp(x)$$
 discrete r.v.
 $E(X) = \mu = \int_{x} xf(x)dx$ continuous r.v.

 The variance (σ²) is a measure of dispersion or scale. Having established a typical value of a random variable, it is also of interest to have some idea of the "spread":

$$V(X) = \sigma^{2} = E\{[X - E(X)]^{2}\}$$
$$= E(X^{2}) - [E(X)]^{2}$$

Basic properties of E () operator

- E(c) = c c is a constant
- E (aX) = a E (X) <u>linearity</u> of operator

Therefore:

E [aX ± bY] = E [aX] ± E [bY]
 a E (X) ± b E (Y)

Basic properties of V () operator

- V (X) or Var (X)
- Var [aX ± bY] =
 a² Var (X) + b² Var (Y)
 ± 2 a b Cov (X, Y)
- Never forget the above formula! We will use throughout the course!
- Cov (X, Y) ? (covariance)

Cov () operator (more in Ch 2, notes)

 Cov (as the word signifies) relates two random variables!

- If X,Y independent, then
 Cov (X, Y) = 0
- Converse statement? Be careful!

A few more remarks...

- E (X Y) ≠ E (X) E(Y), in general (equality holds only if X,Y are independent)
- Square root of Var gives the standard deviation (st dev or st error or se or s.e.)
- So, $Var(X) = \sigma^2 (for X)$
- σ² vs σ

POPULATION

- A population is the <u>whole set</u> from which we are collecting information.
- A population (<u>reference set</u>) is very large and can be a hypothetical concept including past, present and future production


Example: Suppose we are interested in measuring the lifespan of a particular type of battery.

 Often, as in the example above, it is impossible to make observations on 100% of the population, so we draw a random sample from it.

RANDOM SAMPLE (fair

representation)

 In a random sample, each member of the population has an equal chance of being included in the sample.



RANDOM SAMPLE

- To make inferences we must describe or summarize the data in our sample
- We make use of descriptors (indicators, metrics) called "<u>sample statistics</u>". The most commonly used are:

- Sample Mean:

 Average of all data values; gives a sense of location.

– Sample Variance:

 Average of the squared deviations from the mean; gives an indication of the scatter, spread or range of the data.

SAMPLE STATISTICS

	Sample	Population
Mean	\overline{X}	μ
Variance	S^2	σ^2
Std. Deviation	S	σ

$$\overline{X} = \frac{1}{n} \sum_{i=1}^{n} X_i$$

$$S^{2} = \frac{\sum_{i=1}^{n} (X_{i} - \overline{X})^{2}}{n-1} = \frac{1}{n-1} \left\{ \sum_{i=1}^{n} X_{i}^{2} - \frac{1}{n} \left(\sum_{i=1}^{n} X_{i} \right)^{2} \right\}$$

$$S = \sqrt{S^2}$$

A few remarks ...

Note that

$$E(s^2) = \sigma^2$$

• If $Var(X) = \sigma^2$, then $Var(mean) = \sigma^2/n$

More remarks...

 And do not forget to check the CoV or CV or coefficient of variation; (Why? Free of location!)

- CV = (s / mean)
- '% error' = 100 CV

SAMPLE STATISTICS EXAMPLE: YIELD DATA


$$\overline{X} = ?$$

$$S^2 = ?$$

$$S = ?$$


DESCRIBING A SAMPLE

- Pictures are useful to help describe a sample.
- A histogram (or frequency diagram), for example, indicates the shape of the data distribution; frequencies become probabilities in the long term).



NORMAL DISTRIBUTION

One of the most important distributions used for <u>statistical inference</u> (Gaussian, 'bell-shaped' curve).



$$P[-\sigma < X - \mu < \sigma] \cong 0.68$$


$$P[-2\sigma < X - \mu < 2\sigma] \cong 0.95$$

$$P[-3\sigma < X - \mu < 3\sigma] \cong 0.99$$

NORMAL DISTRIBUTION

The normal distribution requires \underline{two} $\underline{parameters}$, the mean and variance (μ , σ^2), to describe its shape (many examples)!

$$f(x) = \frac{1}{\sigma\sqrt{2\pi}} \exp\left\{-\frac{1}{2} \left(\frac{x-\mu}{\sigma}\right)^2\right\}$$



STANDARD NORMAL DISTRIBUTION

Consider the random variable Z defined by:

$$Z = \frac{X - \mu}{\sigma}$$
, where $X : N(\mu, \sigma^2)$.
 $E(Z) = \mu_Z = 0$; $V(Z) = \sigma_Z^2 = 1$

- Z is called the "standard" or "unit" normal random variable (unit normal deviate); if X ~ N(μ, σ²), then Z ~ N(0,1)
- To look up probabilities associated with any normal random variable X, first transform to Z and then look up the probability in a table; i.e., values of Z are tabulated.
- Example:

Given :
$$X : N(8,4)$$
. Find $P(X \le 10)$?

$$Z = \frac{10-8}{2} = 1.00$$

More remarks...

• E(Z) = ?

• Var(Z) = ?

 Refresh your memory on use of z-tables!

STANDARD NORMAL DISTRIBUTION

Example:

Given: X: N(8,4), find the value of x for which $P(X \le x) = 0.75$.

$$P(X \le x) = P(Z \le z) = 0.75$$

From the Table z = 0.6745

$$x = z\sigma + \mu = 0.6745 * 2 + 8 = 9.349$$

 $P(X \le 9.349) = 0.75$

Normal probability rules (basis of SQC/SPC,..):

$$P[-\sigma < X - \mu < \sigma] \cong 0.68$$

$$P[-2\sigma < X - \mu < 2\sigma] \cong 0.95$$

$$P[-3\sigma < X - \mu < 3\sigma] \cong 0.99$$


Exercise

- Involves the Normal distn; typical process specs example
- In an industrial process, the (property) of (a specimen) is considered important. The buyer sets specifications on the (property) to be 3 \pm 0.01 (appropriate units). The implication is that no part outside of this range will be accepted. It is known that in the process in question, the (property) follows a normal distn with μ = 3 and σ = 0.005 (units?). On the average, what is the % of product to be scrapped, given the production specs?
- (Hint: Start with a probability statement, as per 2nd yr Stats!)

NORMAL PROBABILITY PLOTS

A normal probability plot (NPP) is a tool for determining if a sample comes from a normal distribution. If it does, then the data should follow a straight line pattern on this plot.

Rank	X _i	P(rank)	Expected Value				
1	5	0.05	-1.645				
2	5.6	0.15	-1.035				
3	7	0.25	-0.675				
4	7.2	0.35	-0.385				
5	7.8	0.45	-0.125				
6	8.6	0.55	0.125				
7	8.8	0.65	0.385				
8	9.6	0.75	0.675				
9	10.6	0.85	1.035				
_10	12.0	0.95	1.645				



NPP remarks...

- P (rank) = (i 0.5) / n
- n = sample size (# of data)
- i = index (rank x_i (observed values)
 from low to high)
- Expected Normal Value on y-axis is the z-value from the tables corresponding to P(rank)
- P(rank) = cumulative probability value
- NPPs (very useful!) will be revisited in later chapters!
- Regular NPPs vs Half-Normal Plots

SHAPE OF DATA AND THE CENTRAL LIMIT THEOREM

- Do all raw data we collect follow the normal distribution? No, but averages do!
- Central Limit Theorem (CLT):


For a random variable X with mean μ and variance σ^2 , the distribution of the sample mean \overline{X} from a sample of size n on X follows the normal distribution with mean μ and variance σ^2/n . This is true regardless of the shape of the distribution of X.

 This, at least in part, explains why many measurements do follow the normal distribution.

DISTRIBUTIONS


Lab tests of notched Izod bars: 5 bars/sample

	0	1	2	3	4	5	6	7	8	9	10	11
Sample 1		0		0		0		0		0		
Mean 1						Χ						
Sample 2			0		0				0	0	0	
Mean 2								X				
Sample 3		0			0			0	0		0	
Mean 3							Χ					
Sample 4				0	0		0	0		0		
Mean 4							Χ					
Sample 5			0			0	0		0	0		
Mean 5							Χ					
Sample 6		0		0		0	0	0				
Mean 6					Χ							
Sample 7			0	0		0	0					0
Mean 7						Χ						



OTHER DISTRIBUTIONS

An extremely non-normal distribution:



Summary

- Statistics is the science of decisionmaking in the face of uncertainty.
- Sample statistics estimate population parameters (<u>fixed</u>, <u>yet unknown</u>).
- Put another way, we analyze the sample(s) and we make inferences about the population.
- Individual observations may or may not be normally distributed.
- Averages tend to be normally distributed (Central Limit Theorem).

CONFIDENCE INTERVALS (CIs)

- The sample mean is a point estimate. As a point estimate, it has the undesirable property that we do not know how far away it might be from the true population mean (it is unlikely to exactly equal μ).
- We would like to have an estimate/indicator which combines information from variability and sample size.
- A confidence interval (CI) is such an estimate.

IS THE MEAN ENOUGH?

Two companies, A and B, are producing pellets to be injection molded. The plasticizing time target is 1.8 seconds. You have your choice of which company to buy from.

Α	В
1.8 s	1.9 s

CONFIDENCE INTERVAL FOR THE MEAN

We can construct a confidence interval about the sample mean, X, such that we are 95.44% confident that the interval contains the true mean, μ . The 95.44% confidence interval would be:

$$\overline{X} \pm 2 \frac{\sigma}{\sqrt{n}}$$

A 99.74% confidence interval would be:


$$\overline{X} \pm 3 \frac{\sigma}{\sqrt{n}}$$

Example: For the two companies A and B from the previous page assume the standard deviations indicated are values of σ :

Company A:
$$1.8 \pm 2 \frac{1.41}{\sqrt{2}} = (-0.19, 3.79)$$

Company B:
$$1.9 \pm 2 \frac{0.11}{\sqrt{20}} = (1.85, 1.95)$$

X AND X DISTRIBUTION




 [An estimate of a statistic ± (a multiplier) · (the st dev of the estimate of the statistic)]

- General guiding formula for a CI
- CI on a population characteristic (population parameter)!
- The multiplier takes into account some level of significance (α, alpha)

 What are the multipliers for exactly 90, 95 and 99% confidence intervals?
 Check z-tables...

Confidence Level	Factor
90%	1.645
95%	1.96
99%	2.58

What do we mean by the word "confidence":



 For a 95% confidence interval: On repeated sampling from the population, 95% of the numerical intervals generated are expected to contain μ; by chance, 5% (1 in 20) will not.


REMARKS ABOUT CONFIDENCE INTERVALS

- The approach assumes no systematic error is present.
- 2-sided vs 1-sided
- Confidence intervals could be made narrower by decreasing the confidence level (increasing the significance level) or increasing n.
- The population mean, μ , is constant (fixed); the interval changes from sample to sample.
- Probability is based on the distribution of X; not on the individual observations on X.
- The distribution of X approaches the normal distribution according to the Central Limit Theorem, as n increases.
- The choice of the factor (1.96 at 95% confidence, for example) yields the shortest interval.

The t-DISTRIBUTION

- When the sample size is small and the variance is unknown, it must be estimated by S². The sample mean X follows a "t" distn ('Student t' distn) rather than a normal distn.
- Normal: $\overline{X} \pm 1.96 \frac{\sigma}{\sqrt{n}}$
- t-distribution: $\overline{X} \pm t \frac{S}{\sqrt{n}}$
- "t"-factor is the tabulated value of the t distribution with n-1 degrees of freedom (df) and a significance level α .
- Confidence level = 100% (1- α)
- Default: 95% for CI; 5% for α

THE t-DISTRIBUTION



The t-distribution has a different shape for different sample sizes (elongated tails; as n becomes large, then ?)

- Tutorial, Ch 1_ex 1 and Ch1_ex 2, on Cls
- Supposed to be review material from 2nd yr Stats
- Next? Hypothesis Testing (HT)!
- HT and CIs complementary; same math background, but from a slightly different angle (slightly different starting point)

HYPOTHESIS TESTING (HT)

- Suppose a reaction currently has a desirable yield of 70%
- Researchers have come up with a cheaper catalyst, but they are not sure it will give the same yield (claim? An alternative!)
- The "null hypothesis" ('devil's advocate', 'status quo') to disprove is:

$$H_0: \mu_0 = 70\%$$

- To test this, we could collect a random sample of yield data using the new catalyst and determine if the sample mean is different from 70%.
- But how different is different?

 We could reject the null hypothesis if, for example, a 95% confidence interval calculated for the new sample mean does not include 70%.

$$\begin{split} & \overline{X}_{\text{sample}} - t_{n-1,\frac{\alpha}{2}} \frac{S}{\sqrt{n}} \leq \mu_0 \leq \overline{X}_{\text{sample}} + t_{n-1,\frac{\alpha}{2}} \frac{S}{\sqrt{n}} \\ & - t_{n-1,\frac{\alpha}{2}} \frac{S}{\sqrt{n}} \leq \mu_0 - \overline{X}_{\text{sample}} \leq t_{n-1,\frac{\alpha}{2}} \frac{S}{\sqrt{n}} \\ & - t_{n-1,\frac{\alpha}{2}} \leq \frac{\mu_0 - \overline{X}_{\text{sample}}}{S/\sqrt{n}} \leq t_{n-1,\frac{\alpha}{2}} \end{split}$$

$$\left| \frac{\overline{X}_{sample} - \mu_0}{S / \sqrt{n}} \right| \le t_{n-1, \frac{\alpha}{2}}$$

 The last line is true if 70% is a reasonable value for the mean yield in light of the data.

Therefore, if

$$\left|\frac{X_{sample} - \mu_0}{S/\sqrt{n}}\right| \ge t_{n-1,\frac{\alpha}{2}}$$

we would reject the null hypothesis H_0 : $\mu_0 = 70\%$, and conclude that the new catalyst has indeed changed the yield.

 The above procedure has the important property that if we carry out a hypothesis test at a 95% confidence level, there is a 5% chance that we will wrongly reject the null hypothesis; i.e., claim that the yield is different from 70% when it is not.


Accompanying a null hypothesis H_o is an alternative hypothesis H₁ which we "accept" if we reject H₀. In its most general form:

$$H_1: \mu \neq 70\%$$
 (two-sided)
or
 $H_1: \mu > 70\%$ (one-sided)
or
 $H_1: \mu < 70\%$ (one-sided)


- The strength of a hypothesis test lies in rejecting H₀. Therefore, whatever is to be claimed should be stated as the alternative or "research" hypothesis H₁.
- When do we use a one-sided vs. a two-sided test (analogous to 1-sided vs. 2-sided Cls)?

Alternative hypothesis:


Two-sided, ≠



One-sided, >



One-sided, <



 Example: A soft-drink beverage company purchases 300 ml bottles from a glass company. It is important to ensure that the bottles meet the minimum internal pressure or bursting strength of 200 psi.

Either
$$H_0$$
: $\mu_0 = 200 \text{ psi}$ H_1 : $\mu > 200 \text{ psi}$ (1) or H_0 : $\mu_0 = 200 \text{ psi}$ H_1 : $\mu < 200 \text{ psi}$ (2)

(1): If H₀ is rejected, bottles ok.

⇒ If H₀ not rejected, bottles should not be used. Forces bottle manufacturer to "demonstrate" that bottles are ok.

(2): Bottles are ok, unless H₀ is rejected.

- (1) is appropriate if we have had trouble with this supplier; there is some probability that the null hypothesis is not rejected even though true mean pressure is greater than 200 psi.
- (2) is appropriate if we are generally happy with bottle supplier and a small deviation below 200 psi is not serious.

SUMMARY OF HYPOTHESIS TESTING

$$H_0$$
: $\mu_0 = 70\%$

$$H_1$$
: $μ ≠ 70%$

2. Set the significance level of the test (confidence level =
$$1 - \alpha$$
)

$$\alpha = 0.05$$

3. Choose the test statistic

$$\overline{X}: N(\mu_0, \sigma^2/n)$$

5. Collect a random sample, calculate the test statistic and make a decision on H₀:

If
$$\left| \frac{\overline{X}_{sample} - \mu_0}{S/\sqrt{n}} \right| \ge t_{n-1,\frac{\alpha}{2}}$$
 then we reject H_0

If
$$\left| \frac{\overline{\mathbf{X}}_{\text{sample}} - \mu_0}{S/\sqrt{n}} \right| < t_{n-1,\frac{\alpha}{2}}$$
 then we fail to reject H_0

P-VALUES

- Introduce concept schematically
- Commonly the value of α is set at 0.01 or 0.05. The philosophy behind setting this value is to "control" the probability of rejecting a correct (true) null hypothesis.
- Dilemma: What if the test statistic value is close to the critical value?
- An alternative to pre-specifying the value of α is to calculate the probability of exceeding the value you observed given the H₀ - the p-value.
- The amount of evidence for rejecting the null hypothesis is then given according to the following guidelines:

P<0.01	very strong evidence
0.01 <p<0.025< td=""><td>strong evidence</td></p<0.025<>	strong evidence
0.025 <p<0.05< td=""><td>moderate</td></p<0.05<>	moderate
0.05 <p<0.1< td=""><td>weak</td></p<0.1<>	weak

- Tutorial, Ch 1_ex 3 and Ch1_ex 4, on HT
- Supposed to be review material from 2nd yr Stats
- Can also be done via CIs
- Try to calculate P-values as well

 Essentially, with P-value you calculate your problem's α (alpha)

ESTIMATING THE DIFFERENCE BETWEEN TWO MEANS (Case 1 and Case 2)

 Sometimes we are interested in examining the difference between two means (μ₁-μ₂). Suppose we have made n₁ measurements on X₁ and n₂ measurements on X₂.

$$\overline{X}_{1}: N(\mu_{1}, \frac{\sigma_{1}^{2}}{n_{1}}) \qquad \overline{X}_{2}: N(\mu_{2}, \frac{\sigma_{2}^{2}}{n_{2}})
\overline{X}_{1} - \overline{X}_{2}: N(\mu_{1} - \mu_{2}, \frac{\sigma_{1}^{2}}{n_{1}} + \frac{\sigma_{2}^{2}}{n_{2}})$$

 We distinguish between two cases, which depend upon how much is known about the variances:

Case 1: σ_1^2 and σ_2^2 known (almost never used):

$$(\bar{x}_1 - \bar{x}_2) \pm z_{\alpha/2} \sqrt{\frac{\sigma_1^2}{n_1} + \frac{\sigma_2^2}{n_2}}$$

Case 2:

Case 2a: σ_1^2 and σ_2^2 "equal" and unknown (widely used):

$$(\bar{x}_1 - \bar{x}_2) \pm t_{\alpha/2,\nu} s_p \sqrt{\frac{1}{n_1} + \frac{1}{n_2}}$$

$$s_p^2 = \frac{(n_1 - 1)s_1^2 + (n_2 - 1)s_2^2}{n_1 + n_2 - 2}$$

$$s_p^2 = \text{"pooled" estimate}$$

$$\nu = n_1 + n_2 - 2$$

Case 2b: σ_1^2 and σ_2^2 unequal and unknown:

$$(\overline{x}_{1} - \overline{x}_{2}) \pm t_{\alpha/2}, \sqrt{\frac{s_{1}^{2}}{n_{1}} + \frac{s_{2}^{2}}{n_{2}}}$$

$$v = \frac{\left(\frac{s_{1}^{2}}{n_{1}} + \frac{s_{2}^{2}}{n_{2}}\right)^{2}}{\left[\left(\frac{s_{1}^{2}}{n_{1}}\right)^{2} \frac{1}{n_{1} - 1}\right] + \left[\left(\frac{s_{2}^{2}}{n_{2}}\right)^{2} \frac{1}{n_{2} - 1}\right]}$$

(rounded up (by convention) to the nearest integer)

ESTIMATING DIFFERENCES

- Tutorial, Ch 1_ex 5, on comparing two means
- Supposed to be review material from 2nd yr Stats
- Many alternatives in approaching these types of problems (CIs vs HT)

ESTIMATING DIFFERENCES

- Essentially, in Case 2a, we can make the assumption that population variances 1 and 2 are unknown to us but sufficiently close ('equal'), and proceed with the use of the 'pooled' variance.
- Is that a good assumption?
- We can always make the assumption and then check back (and hence, justify it).

HYPOTHESIS TESTS FOR VARIANCES (Case 3)

 Two companies A and B produce polycarbonate pellets. Here are the summary statistics for two pellet samples:

Company	N	\overline{X}	Variance	Std. Dev.
Α	100	0.024	2.25x10 ⁻⁶	0.0015
		g/pellet	(g/pellet) ²	g/pellet
В	100	0.025	1.64x10 ⁻⁵	0.0041
		g/pellet	(g/pellet) ²	g/pellet

 The pellets seem to have the same average weights, but there is a difference in the pellet weight variability.

F-TEST

 We can examine the difference by using an Ftest which involves the ratio of the two variances

$$S_1^2/S_2^2$$


- When testing for differences, the smaller observed variance is always in the denominator.
- The test involves the following hypotheses:

$$H_0: \sigma_1^2 / \sigma_2^2 = 1$$
 $H_1: \sigma_1^2 / \sigma_2^2 > 1$

 The null above says that the two variances are equal.

F-DISTRIBUTION

 The ratio is compared to an F-distribution to see if the variances are equal.



 The F-distribution requires two numbers to define its shape: F(df_{num}, df_{den}) where:

 df_{num} = degrees of freedom in numerator variance (n_1 -1)

 df_{den} = degrees of freedom in denominator variance (n_2 -1)


F-TEST

This probability can be found in an F-table:

degrees of freedom in numerator

		1	2	3	4
degrees of	1	161	200	216	225
freedom in		4052	4999	5403	5625
denominator	2	18.51	19.00	19.16	19.25
		98.49	99.01	99.17	99.25
	3	10.13	9.55	9.28	9.12
		34.12	30.81	29.46	28.71

regular type = 5% bold type = 1%



 The F-table above is for 5% and 1% significance levels. It provides "critical" F-values that are cut-off values for those probabilities.

F-TABLE

- To use the F-table:
 - 1. Choose your level of significance (e.g., 1% or 5%).
 - 2. Determine df_{num} and df_{den} from the respective sample sizes.
 - 3. Look up critical F-value from table:

If calculated ratio > critical F-value, reject H₀, hence the variances in the ratio seem significantly different.

F-TEST

Back to the pellet weight example:

$$S_B^2 = 1.64 \times 10^{-5}$$
 $S_A^2 = 2.25 \times 10^{-6}$
 $df_B = 100 - 1 = 99$ $df_A = 100 - 1 = 99$

$$F_{observed} = \frac{S_B^2}{S_A^2} = \frac{0.0000164}{0.00000225} = 7.29$$

Compare to the appropriate F-distn (F-tables):


Since
$$F_{crit}$$
 is 1.4 \rightarrow $F_{obs.}$ > F_{table} (99,99) at α = 0.05,


Therefore, the variances are significantly different from each other (i.e., reject H₀)

Remarks...

- Tutorial, Ch 1_ex 6, on obtaining a Cl on a variance
- Supposed to be review material from 2nd yr Stats

 Sometimes, two variables are related to each other in a linear fashion:







 A measure of the strength of the <u>linear</u> relationship between two variables X and Y, is given by the sample correlation coefficient:

$$r = \frac{\sum (X - \overline{X})(Y - \overline{Y})}{\sqrt{\sum (X - \overline{X})^2 \sum (Y - \overline{Y})^2}}$$


- The correlation coefficient
 - can range from -1 to +1
 - represents stronger positive (or negative) correlation as it gets closer to positive (or negative) 1
 - is an indicator of linear association only!






r =

r =






r =

r =

Remember: Correlation does not necessarily imply causation!




A plot of the population of Oldenburg at the end of each year against the number of storks observed in that year, 1930-1936; many other examples over the years!

SIMPLE LINEAR REGRESSION

When two variables are related linearly, a line can be used to represent and model the relationship between them.


$$Y = aX + b$$



$$T_F = T_C *9/5 + 32$$


SIMPLE LINEAR REGRESSION


 Some relationships are close to linear, but are not exact due to experimental error.



 These data could be modeled by a straight line. But how do we find the "best" line?

 We choose an equation (slope and intercept) that <u>minimizes the vertical distance</u> between the data and the assumed model.





 Mathematically, we can accomplish this by minimizing the sum of squared <u>residuals</u> (errors):

$$SSE = \sum (Y - \hat{Y})^2 = \sum e^2$$

where \hat{Y} = the estimate of Y provided

where \hat{Y} = the estimate of Y provided by the chosen line.

 The slope and intercept, respectively (see below), that minimize the SSE are given by:

$$\hat{a} = \frac{\sum (X - \overline{X})(Y - \overline{Y})}{\sum (X - \overline{X})^2}$$

$$\hat{b} = \overline{Y} - \hat{a}\overline{X}$$

 We can explain the regression in terms of variability in the data accounted for by the model:

Fuel Consumption against Vehicle Weight

y=-0.363+1.639*x+eps 7.0 6.5 FUEL CONSUMPTION (in gallons/100 miles) 6.0 5.5 5.0 4.5 4.0 3.5 3.0 2.5 2.0 2.4 2.8 1.6 3.2 3.6 4.0 4.4 WEIGHT (in 1000 lb)

 With some algebra we can decompose the total variation in the data into the amount explained by the regression (model) and the amount unexplained by the regression:

$$\sum (Y - \overline{Y})^2 = \sum (Y - \hat{Y})^2 + \sum (\hat{Y} - \overline{Y})^2$$

 \therefore SST = SSR + SSE

where
$$\sum (Y - \overline{Y})^2 = \text{total sum of squares} = \text{SST}$$

$$\sum (Y - \hat{Y})^2 = \text{S. of S. unexplained} = \text{SSE}$$

$$\sum (\hat{Y} - \overline{Y})^2 = \text{S. of S. explained} = \text{SSR}$$
by regression

ANALYSIS OF VARIANCE

 This breakdown of the variability can be summarized in an <u>Analysis of Variance</u> (ANOVA) table ('book-keeping'):

Source	SS	df	MS	F
Regression	\ /		SSR/(p-1)	MSR/MSE
Error	$\sum (Y - \hat{Y})^2$	n-p	SSE/(n-p)	
Total	$\sum (Y - \overline{Y})^2$	n-1		

where

df = number of independent observations to compile
 each sum-of-squares

p = number of parameters in the model (here 2)

n = number of observations

MS = mean square (variance)

So, what is MS essentially? MSE or MSE? F (F probe) above?

- The last column of the ANOVA table refers to the observed F-value for a hypothesis test which is looking at the <u>overall significance of the regression</u>.
- For a simple straight line this is equivalent to testing the slope against zero:

$$H_0: a = 0$$
 $H_1: a \neq 0$

 In a simple linear regression case, this is the same as testing the hypothesis that the variation explained by the model (i.e., via regression) is significantly larger than the error term:

$$H_0: \frac{MSR}{MSE} = 1$$
 $H_1: \frac{MSR}{MSE} > 1$


Where
$$MSR = SSR/df_{SSR} = variance$$
 explained by model $MSE = SSE/df_{SSE} = variance$ due to errors


What type of test is this?

- To test this hypothesis, we compare the ratio of MSR/MSE to the F-distribution. If MSR/MSE > F(p-1,n-p), then we are in the rejection region of the null hypothesis H₀, hence it seems that the slope (and therefore the model) is significant.
- If the model is significant, the model explains a major amount of the variability in the data.

REGRESSION DIAGNOSTICS (more in Ch 2, notes)

- The most valuable regression diagnostic tool is the residual plot (e vs something).
- In examining residual plots we are looking for trends or patterns.





REGRESSION DIAGNOSTICS

 Provided the residuals are "well-behaved", another useful quantity to examine is R², the "Coefficient of Determination":

$$R^2 = \frac{SSR}{SST}$$

- This ratio (R² above or r² from correlation coefficient slide) indicates what percentage of the variation present in the data is accounted for by the model.
 R² ranges from 0 to 1 and, in general, the closer it is to 1, the better the model explains the data.
- It is unwise to place too much emphasis on R² alone, or to consider it without examining residual plots. It is possible to have a low R² value with a model that fits the data reasonably well. Under what circumstances might this happen?

Example: ANSCOMBE'S DATA $(R^2 = 0.67)$

Ansco	mbo's	Data
Ansco	mbers	s Data

Observa-		
tion	x1	y1
1	10	8.04
2	8	6.95
3	13	7.58
4	9	8.81
5	11	8.33
6	14	9.96
7	6	7.24
8	4	4.26
9	12	10.84
10	7	4.82
11	5	5.68

x2	y2
10	9.14
8	8.14
13	8.74
9	8.77
11	9.26
14	8.1
6	6.13
4	3.1
12	9.13
7	7.26
5	4.74

х3	y3
10	7.46
8	6.77
13	12.74
9	7.11
11	7.81
14	8.84
6	6.08
4	5.39
12	8.15
7	6.42
5	5.73

x4	y4
8	6.58
8	5.76
8	7.71
8	8.84
8	8.47
8	7.04
8	5.25
19	12.5
8	5.56
8	7.91
8	6.89

Summary Statistics

N	11	11
mean	9.00	7.50
SD	3.16	1.94
r	0.82	

11	11
9.00	7.501
3.16	1.94
0.82	

11	11
9.00	7.50
3.16	1.94
0.82	


11	11
9.00	7.50
3.16	1.94
0.82	


Sources:


Edward R. Tufte, *The Visual Display of Quantitative Information* (Cheshire, Connecticut: Graphics Press, 1983), pp. 14-15.


F.J. Anscombe, "Graphs in Statistical Analysis," American Statistician, vol. 27 (Feb 1973), pp. 17-21.

ANSCOMBE'S DATA $(R^2 = 0.67)$









MULTIPLE LINEAR REGRESSION (more on this in Ch 2, notes)

 Often we have more than one X (independent, regressor, input, setting) variable. We then carry out Multiple Linear Regression instead of Simple Linear Regression:

$$Y_i = \beta_0 + \beta_1 X_{1i} + \beta_2 X_{2i} + \dots + \beta_p X_{pi} + \varepsilon_i \quad i = 1, \dots, n$$

• To test the **overall significance of the model**, we test the hypothesis that all the β_i 's (slopes) are equal to zero:

$$H_0: \beta_i = 0$$
 $H_1:$ some of $\beta_i \neq 0$

 Again, this involves an F-test in which the ratio MSR/MSE is compared against F(p-1,n-p) at a preselected confidence level.

SUMMARY

 In this section we have summarized the statistical methods necessary for

ESTIMATION
HYPOTHESIS TESTING and
CONFIDENCE INTERVALS
REGRESSION MODELLING
(linear)
ANOVA
(Normal Probability Plot,
Residual Plots)

 These techniques are an essential part of analyzing and therefore understanding experimental data (and a quick <u>overview</u> of a 2nd-yr Eng or Sci Applied Statistics course).

Map Conce Correlation and more... **Hypothesis Testing Confidence Interval Basic Stats** P_Value Linear Reg. Analysis

Helpful Review

Paired comparison test (Paired *t*-test):

"Special case of case II"

It is a special case of the two sample t-tests (Variance Unknown) occurs when the observations on the two populations of interest are collected in pairs. Each pair of observations, say (X_{1j}, X_{2j}) , is taken under homogeneous conditions, but these conditions may change from one pair to another. The test procedure consists of analyzing the differences between readings (d). The Hypothesis test would be $H_0: \mu_d = 0$ $H_1: \mu_d \neq 0$

and the test statistics would be $t_o = \frac{\overline{d} - \mu_d}{S_d/\sqrt{n}}$.

Where \overline{d} is the average of all d (differences between readings), and S_d is the standard deviations of all d (differences between readings).

(See section 2.5, pg 48 of Montgomery book, 10th ed.; or pg 53 of 8th ed.).