Sensor Drift and Calibration Issues - Repair Manual

Symptoms: Gradual deviation of sensor readings from expected baseline without corresponding physical performance change; erratic readings.

Common Causes:
- Sensor calibration drift over operational hours
- Wiring degradation or connector corrosion
- Thermal cycling effects on sensor electronics

Recommended Actions:
1. Cross-reference suspect sensor against redundant sensor readings
2. Perform sensor recalibration per manufacturer specification
3. Inspect wiring harness and connectors for corrosion or damage
4. Replace sensor if drift exceeds 10% of calibrated range
5. Log calibration date for future maintenance tracking

Priority: MEDIUM - Sensor issues can mask real degradation if not caught, leading to delayed detection of actual mechanical problems.