

ROBOARM – FULL WIRING (REV C)

Every board pin shown. Wires drawn between parts. Power rails use KiCad power symbols (+24V, +5V, +6V, GND). Unused pins carry no-connect flags.

