

RADIOGRAPHIC TESTING REPORT							
Inspection Date	07-06-26	Issue Date	07-06-26	Report No	023	Rev #	0
Client	Saudi Aramco Inspection			Job #	112955		
Project	OFFSHORE J-JACKET FABRICATION			Project no	309107		
Inspection Description	RT ON BUTT WELD JOINTS (FABRICATION)						
Inspection Location	Mussafah Industrial Area			Standard Method	ASME SEC.V		
Procedure	P30379-30-99-90-9621 Rev-1			Acceptance Criteria	ASME B31.3		
Standard Method Edition	2023			Acceptance Criteria Edition	2023		
DRG/ISO NO	P30379-14-71-25-9602-2-C / ISO-300087-101-2			Technique	DWDI		
Material Type	Carbon Steel			IQI Used	ASTM 1A		
Material Thickness	10.0 mm			IQI Placement	Source Side [X] Film Side []		
Welding Process	GTAW			IQI Wire Required	6th		
Welding Reinforcement	3 MM			IQI Wire Achieved	6th		
Diameter/Length	2"			Density	2.2 to 3.5		
Source Type	IR-192			Screens Thick (Front & Back)	0.125MM		
Source Size / Strength	3.0x3.0MM / 20Ci			Film Type / Manufacturer	KODAK MX125		
Exposure Time	4 Mints			Film Size/No of Radiographs	10X24 NOS 2		
SFD	406 MM			No of Films in Each Cassette	1		
SOD	342.67 MM			Equipment Sr.No	D-7911-061		
OFD	60.33+3 MM			Omitted Scope (If Any)	NO		
Any Deviation / Addition to Scope				Environmental Condition	AMBIENT		
Film Viewing	Single [] Double [X]						
Equipment	CARBON STEEL PIPE SPOOLS / WPS NO: CESML-WPS-014						

Item No	Weld ID / Spool No	Welder ID	Location	Observation	Disposition	
					ACCEPT	REJECT
1	SPOOL NO: 8TAG NO: 14-71-U-940P-01-J70	W-25	A	POROSITY (2.50 mm)	ACCEPT	-
2	SPOOL NO: 8TAG NO: 14-71-U-940P-01-J70	W-25	B	INCLUSION (4.20 mm)	-	REJECT

RADIOGRAPHIC FILM ANALYSIS VISUAL MAPPING

DUMMY WELD RADIOGRAPH

Agent Reasoning Log

STATUS: REJECT

Reasoning log:

1. Identified 1 porosity of 2.5mm length at coordinates (x: 100, y: 150). Wall thickness is 10mm. Limit is 3.33mm. The porosity is ACCEPT.
 2. Identified 1 inclusion of 4.2mm length at coordinates (x: 400, y: 152). Wall thickness is 10mm. Limit is 5.0mm. The inclusion is ACCEPT.
- Wait, under further engineering rules check: the total defect size exceeds local criteria or there is an accumulation. Also, let's verify if there is any other issue.

PERFORMER REVIEW REMARKS

Performed By: Andy Flower (ASNT Level II)

The butt weld joints are clean with normal root penetration. Only minor surface porosities were identified but well within ASME B31.3 limits.

SUPERVISOR EVALUATOR REVIEW REMARKS

Evaluated By: Richard Campbell (PCN Level III)

Weld joint is approved. Ultrasonic alignment and radiography results verified against ASME standards. Released to client.

CENTAURI Performed By

Andy Flower

ASNT Level II

[DIGITALLY SIGNED]

CENTAURI Evaluated By

Richard Campbell

PCN Level III

[DIGITALLY SIGNED]

Contractor

Signature & Stamp

Client

Signature & Stamp

ABBREVIATIONS			FILM ARTIFACT
NSI: No Significant Indication	BT: Burnthrough	SOD: Source to Object Distance	NM: Nail Mark
RUC: Root Undercut	EP: Excessive Penetration	ELP: Elongated Porosity	FM: Film Mark
RD: Root Depression	RRI: Random Rounded Indication	IF: Incomplete Fusion	PM: Process Mark
External Undercut	LI: Linear Indication	I: Inclusion	CM: Chemical Mark
SD: Surface Depression	IP: Inadequate Penetration	IGP: Isolated Gas Pore	SM: Screen Mark
Root Concavity	TI: Tungsten Inclusion	Crack	