

EQUIPMENT OVERHAUL AND CONDITION INSPECTION REPORT

Asset Identifier: T-200

Machine Type: Multi-Stage Steam Turbine T-200

Location: Power House Unit 4

Operating Status: High vibration detected on bearing 2 of T-200.

Recommended Actions: Rebalance rotor and inspect thrust bearings for T-200.

Technician: Reliability Engineering Team

Date: 2026-09-14