

REWORKIQ

Weekly Rework Management Report

Reporting Period: 07 Jul 2026 — 14 Jul 2026

Generated: 14 Jul 2026, 09:40

EXECUTIVE SUMMARY

TOTAL REWORKS 20 No prior data	PLANTS COVERED 5	CONTRACTORS INVOLVED 7	DEFECT TYPES
---	----------------------------	----------------------------------	--------------

PLANT SUMMARY

#	Name	Reworks	Share
1	Plant 2	6	30.0%
2	Plant 2A	6	30.0%
3	Plant 1	3	15.0%
4	Plant 3	3	15.0%
5	Plant 4	2	10.0%
TOTAL		20	100.0%

CONTRACTOR SUMMARY


#	Name	Reworks	Share
1	Aanjana	4	20.0%
2	PVE	4	20.0%
3	Dhan Laxmi	3	15.0%
4	KHE	3	15.0%
5	GS ENGG	3	15.0%
6	xyz	2	10.0%
7	Shivgauri	1	5.0%
TOTAL		20	100.0%

DEFECT SUMMARY

#	Name	Occurrences	Share
1	ORW - Orientation Wrong	5	25.0%

#	Name	Occurrences	Share
2	EDGE - Edge Preparation Not Done	4	20.0%
3	HOP - Hole Out / Hole Plug	3	15.0%
4	HOP	2	10.0%
5	SHD - Section Height / Diagonal Deviation	2	10.0%
6	OTH - Others	2	10.0%
7	LGT - Length Short / Excess	2	10.0%
TOTAL		20	100.0%

Top Defect Types — Visual Distribution



WEEK-OVER-WEEK COMPARISON

Metric	Previous Week	Current Week	Change
Total Reworks	N/A	20	No prior data

AI QUALITY INSIGHTS

EXECUTIVE SUMMARY

Over the past week, the total reworks recorded were 20, distributed across four plants and multiple contractors. The predominant defect identified was "Orientation Wrong," accounting for 25% of total reworks.

KEY OBSERVATIONS

The distribution of reworks is relatively balanced across various plants, with Plant 2 and Plant 2A each reporting 6 reworks. Contractor Aanjana led with 4 reworks, representing 20% of the total. Other major defects include edge preparation issues and hole inconsistencies.

ROOT CAUSE ANALYSIS

The primary cause of rework appears to stem from errors in orientation during fabrication, likely due to inadequate training or supervision. The frequency of edge preparation and hole issues suggests potential lapses in quality control protocols or insufficient inspections.

RECOMMENDATIONS

Enhance training programs focusing on orientation precision and edge preparation. Implement stricter quality control checks at critical stages in the fabrication process to identify defects early.

MANAGEMENT ACTION ITEMS

1. Schedule a training session for all relevant personnel addressing the identified issues.
2. Revise quality control procedures to include additional checks for orientation and edge preparation.
3. Monitor rework trends weekly to establish a baseline for continuous improvement.

Generated automatically by ReworkIQ. Figures are compiled from logged rework entries for the reporting period stated on the cover page and are subject to correction as records are finalised.