

W7500 Document History





Table of Contents

1	Reference Document History Information	3
2	Datasheet Document History Information	5



1 Reference Document History Information

Version	Date	Descriptions
Ver. 1.0.0	01MAY2015	1. Initial Release
Ver. 1.0.1	12JUNE2015	Corrected typing error: I2C block
Ver. 1.0.2	17AUG2015	 Deleted 1.1 List of abbreviations. Corrected Register acronym in Table 3. Offset Address for Common Register: PSID -> PSIDR Deleted PP mode with Figure 6 operation of boot code & Table 5 operation of mode selection in Chapter 8. Booting Sequence. Changed words: polling INT bit -> checking INT register in 17.3.2 Operation ADC with interrupt. Deleted unneeded content in 9.2.2 Read operations. Corrected nUARTRTS asserted condition: HIGH -> LOW, Corrected the sentence, 'When nUARTCTR is re-asserted(to a low value) the transmitter sends the next byte.': de-asserted -> re-asserted in 22.3.4 Hardware flow control. Added contents about 19.4.7 Timer0_0 Background Load Register(DUALTIMER0_0TimerBGLoad) / 19.6.7/ 19.10.7/ 19.12.7.
Ver. 1.0.3	08JAN2016	 Bit rate in SPI interface changed 'up to 2MHz and higher' to 'up to 20MHz. Bit rate generation example changed in 23.3.11 Programming the SSPCR1 Control Register.
Ver. 1.0.4	08MAR2016	1. In , GPIO0,1,2,3 changed to GPIOA,B,C,D
Ver. 1.0.5	22APR2016	 Added UART2 Description and Register in 23 Universal Asynchronous Receive Transmit(UART2) Deleted the greater part of I²C, set up the Errata Sheet Link (http://wizwiki.net/wiki/doku.php?id=products:w7500:documents)
Ver. 1.0.6	06JAN2017	1. Corrected Sn_DHAR1 bit R/W information

W7500 Document History 3 / 7



Ver. 1.0.7

 Modified Mode Register and Changed MD in simplified form to MR in 7.5.8 MR(Mode Register)



2 Datasheet Document History Information

Version	Date	Descriptions
Ver. 1.0.0	01MAY2015	1. Initial Release
Ver. 1.0.1	12JUNE2015	Corrected typing error: I2C block
Ver. 1.0.2	17AUG2015	 Deleted 1.1 List of abbreviations. Corrected Register acronym in Table 3. Offset Address for Common Register: PSID -> PSIDR. Deleted PP mode with Figure 6 & Table 5 in 8. Booting Swquence. Changed words: polling INT bit -> checking INT register in 17.3.2 Operation ADC with interrupt. Deleted unneeded content in 9.2.2 Read operation. Corrected nUARTRTS asserted condition: HIGH -> LOW, Corrected the sentence, 'When nUARTCTR is re-asserted(to a low value) the transmitter sends the next byte.': de-asserted -> re-asserted in 22.3.4 Hardware flow control. Deleted RTCCLK.
Ver. 1.0.3	14DEC2015	Corrected Package diagram error.
Ver. 1.0.4	08JAN2016	 Bit rate in SPI interface changed 'up to 2MHz and higher' to 'up to 20MHz'. Bit rate generation example changed in 23.3.11 Programing the SSPCR1 Control Register.
Ver. 1.0.5	08MAR2016	1. In 2.2.2 Memory map, GPIO 0,1,2,3 changed to GPIO A,B,C,D.
Ver. 1.0.6	03JUN2016	 Added UART2 description in 23 Universal Asynchronous Receive Transmit 2(UART2). Deleted the greater part of I²C with data receiving problem, set up the Errata Sheet Link. (http://wizwiki.net/wiki/doku.php?id=products:w7500:documents)

W7500 Document History 5 / 7



Ver. 1.0.7	13JAN2017	 Corrected External Oscillator Clock circuit information (see 10.3.1 External Oscillator Clock). Corrected Package Footprint information (see Figure 76. Footprint Information).
Ver. 1.0.8	09FEB2017	1. Add W7500 Pin Assignment (see 25 Pin Assignment).
Ver. 1.0.9	16FEB2017	Corrected W7500 Pin Assignment the wrong Type.

W7500 Document History 6 / 7



Copyright Notice

Copyright 2017 WIZnet Co., Ltd. All Rights Reserved.

Technical Support: http://wizwiki.net/forum or support@wiznet.io

Sales & Distribution: sales@wiznet.io

For more information, visit our website at http://www.wiznet.io