
the first cycle on the ramp, $t = 4.00$ s



1. the plan gives the reference r
2. the encoders measure the speed
3. the summing junction forms the error e
4. the computer computes the push u
5. the motors push
6. push, ramp's pull and drag change the speed for 10 ms
7. the new speed goes to the sensor for the next cycle