PORSCHE C A R S NORTH A M E R CA

Model Group Technical Bulletin 6 Cyl. Subject Part Identifier Number Adjusting Camshaft Timing 9504

ATTENTION: Service Manager / Service Technician

1996 911 Turbo **Models Affected:**

TOTAL CONTRACTOR

Concern: Correct adjustment procedure for camshaft timing.

General Information: If it becomes necessary to adjust the camshaft timing of 911 Turbo engines produced in the following engine number range, the camshaft

timing must be checked/adjusted using a dial indicator (previous

1505

method).

1996 911 Turbo

Engine Number Range: 61T00500 to 61T00657

Due to a possible machining error in the adjustment slot location on the camshaft, the camshaft timing must be adjusted as in the previous method using a dial indicator (see the 911 Turbo (993) workshop manual pages 15-13 to 15-18).

The camshaft timing in 911 Turbo engines produced before and after the above mentioned engine number range is to be adjusted using the standard 993 camshaft adjusting tools (see the 911 Turbo workshop manual pages 15-7 to 15-12).

Important Notice: Porsche Cars N.A Technical Bulletins are intended for use by professional technicians, not a "Do-it-yourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Special tools may be required to perform certain operations identified in these bulletins. Use of tools and procedures other than those recommended in these bulletins may be detrimental to the safe operation of your vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your Porsche Dealer for information on whether your vehicle may benefit from the information. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify correct part numbers ©1995 Porsche Cars North America, Inc.

Dealership Service manager _ Shop foreman Service technician Distribution Routing Asst. manager Warranty admin. Service technician

The trademarks Porsche[®], Targa[®], Carrera[®], Tiptronic[®], Variocam[®] and the Porsche Crest are registered trademarks of Dr. Ing. h.c.F. Porsche AG and its affiliate, Porsche Cars North America, Inc.



