
Technical Bulletin	Model 6 Cyl.	Group 6
Subject	Part Identifier	Number
Fitting Door Sill Covers	6807	9507

ATTENTION: Service Manager / Service Technician

Models Affected: 911 Carrera and 911 Carrera 4 from Model year 1995

General Information: The above mentioned vehicles can be retrofitted with stainless steel

door sill covers (Exclusive Option X 70).



Parts Information: 000 044 800 01 Set of sill covers with Carrera logo consisting

of

Carrera EXC 964 024 40 sill cover left EXC 964 024 41 sill cover right

000 044 800 02 Set of sill covers with Carrera 4 logo

consisting of:

Carrera 4 EXC 964 025 40 sill cover left EXC 964 025 41 sill cover right

000 044 800 03 Set of sill covers with Carrera Turbo logo

consisting of:

EXC 964 027 40 sill cover left EXC 964 027 41 sill cover right

000 044 800 04 Set of sill covers with Carrera RS logo

consisting of:

Carrera RS EXC 964 026 40 sill cover left EXC 964 026 41 sill cover right

©1995 Porsche Cars North America, Inc. All rights reserved. Cannot be reproduced without written permission. Service & Parts Publications.



Technical Bulletin 6 Cyl. 6 Subject Part Identifier Number 6807 9507

Installation:

- **1 -** Remove the existing sill covers and any glue residue which may be on the body sill.
- 2 Trial fit the stainless steel sill cover to the corresponding door sill. Remove the adhesive strip foil and press the sill cover onto the door sill

Important: Be certain the sill cover does not touch the bottom of the door and does not project from the door sill.

Labor Operation:

68 07 55 00 40 TU Remove and install one sill cover 68 07 56 00 70 TU Remove and install both sill covers

Important Notice: Porsche Cars N.A Technical Bulletins are intended for use by professional technicians, not a "Do-it-yourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Special tools may be required to perform certain operations identified in these bulletins. Use of tools and procedures other than those recommended in these bulletins may be detrimental to the safe operation of your vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your Porsche Dealer for information on whether your vehicle may benefit from the information. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify correct part numbers.

 Dealership
 Service manager
 Shop foreman
 Service technician

 Distribution
 Asst. manager
 Warranty admin.
 Service technician

The trademarks Porsche®, Targa®, Carrera®, Tiptronic®, Variocam® and the Porsche Crest are registered trademarks of Dr. Ing. h.c.F. Porsche AG and its affiliate, Porsche Cars North America, Inc.

©1995 Porsche Cars North America, Inc. All rights reserved. Cannot be reproduced without written permission. Service & Parts Publications.

