Technical Bulletin		Model	Gra
		6 Cyl.	6
Subject Timer for Installing		Part Identifier	Num
	Timer for Installing Cabrio Rear Window	61	950

ATTENTION: Service Manager / Service Technician

Models Affected: 911 Carrera 1995 Model Year on

Concern: Correct operation of hot glue timer for installation of cabriolet

rear window.

Important: The heating time process for removal or installation of the hot glue sealer must not exceed <u>TWO (2) minutes.</u> The

welding time must be monitored with a stop watch.

General Information:

The timer determines the duration of current flow when removing or refitting the rear window. The current supplied by a fully charged battery is used for this process. A heater wire system made up of copper leads is installed along the perimeter of the rear window and is covered by a bead of hot melt adhesive. Heating causes the hot melt adhesive to flow. This allows the rear window to be removed or installed.

When installing the special tooling, be certain that the pressure frame exerts adequate pressure on all areas around the window opening. Insufficient pressure will cause gaps that can result in overheating damage to the window and/or top material.

After the heating in (sealing) of the rear window is complete, the special tools must stay in position for a minimum of twenty (20) minutes until the hot melt adhesive has cooled.

Consult the workshop manual vol. 5 pages 64-25 through 64-30 for instructions regarding removing and installing cabriolet rear window.

Important Notice: Porsche Cars N.A Technical Bulletins are intended for use by professional technicians, not a "Do-it-yourselfer." They are written to inform these technicians of of that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Special tools may be required to perform certain operations in these bulletins. Use of tools and procedures other than those recommended in these bulletins may be detrimental to the safe operation of your vehicle. Properly trained technicit the equipment, tools, safety instructions and know-how to do a job properly and safety. If a condition is described, do not assume that the bulletin applies to your vehicle, or vehicle will have that condition. See your Porsche Dealer for information on whether your vehicle may benefit from the information. Part numbers listed in these bulletins are for only. Always check with your authorized Porsche dealer to verify correct part numbers.

,,						
Dealership	Candon manager	Shop foreman		Contino toobnicion		
Distribution	Service manager	Shop loreman	-	Service technician		 -
Routing	Asst. manager	Warranty admin.		Service technician		