Technical Bulletin 6 Cyl. 1 Subject Part Identifier Number Removing and Installing Fan Belt 1903 9505

ATTENTION: Service Manager / Service Technician

Models Affected: 1996 911 Turbo

Concern: Due to unfavorable tolerances on the A/C compressor console, the fan

belt cannot be removed.


General Information: When regular maintenance service or related engine repairs are per-

formed, the A/C compressor console should be reworked to permit

removal of the fan belt.

Work Procedure: The A/C compressor console should be reworked using a coarse body

file.






Figure 1

Figure 2

With a coarse body file, rework the A/C console in the area (darken area) shown in Figure 1 (arrows). Remove material until the fan belt can be easily removed (Figure 2). Use a vacuum cleaner to remove all filings.

Labor Information: Rework console during a Maintenance Service:

Labor Operation: 87 40 49 00 40 TU

Rework console (not done in conjunction with Maintenance Service):

Labor Operation: 21 43 19 00 80 TU

Includes remove and install intercooler

Important Notice: Porsche Cars N.A Technical Bulletins are intended for use by professional technicians, not a "Do-it-yourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Special tools may be required to perform certain operations identified in these bulletins. Use of tools and procedures other than those recommended in these bulletins may be detrimental to the safe operation of your vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your Porsche Dealer for information on whether your vehicle may benefit from the information. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify correct part numbers.

 Dealership
 Service manager
 Shop foreman
 Service technician

 Distribution
 Asst. manager
 Warranty admin.
 Service technician

The trademarks Porsche®, Targa®, Carrera®, Tiptronic®, Variocam® and the Porsche Crest are registered trademarks of Dr. Ing. h.c.F. Porsche AG and its affiliate, Porsche Cars North America, Inc.

