
(a) Candidate acceptance

```
reports = tuple(
    requirement.verify(mode=selected_mode)
    for requirement in owner.requirements)
if any(report.verified is not True
       for report in reports):
    continue
```

Python query

```
matches = battery.recommend_cots(
    cots_catalog,
    sort_by="rated_energy",
    reverse=True, limit=3)
```

(b) GUI recommendations



(c) Expanded verification for P45B

Requirement	Measure	Target	Predicate
energy_screen check	15.5 Wh	11 Wh	`measure >= target`
mass_screen check	0.07 kg	0.075 kg	`measure <= target`
voltage_screen check	3.6 V	3.6 V	`measure == target`