

PROJECT ESTIMATION REPORT

Project: Test Report
Date: January 15, 2026

System Input

Item	Value
PROFILES	
Description	Project Total Materials
Vertical Sill/Jamb Screw Spline Assembly (Jamb)	BE9-2513 (clear)
Vertical Flush Filler	E9-2512 (clear)
Vertical Two Piece Mullion Screw Spline Assembly	BE9-2511 (clear)
Horizontal Horizontal Screw Spline Assembly	BE9-2515 (clear)
Horizontal Head	BE9-2514 (clear)
Thermal Sill Flashing	BE9-2578 (clear)
Horizontal Glass Stop (Use with BE9-2514, BE9-2515, BE9-2517)	E9-2519 (clear)
ACCESSORIES	
Description	Project Total Materials
End Dam For Sill Flashing	E1-0199
Water Deflector	E2-0047
#12 x 1-1/4" PHSMS Type AB, Zinc Plated Steel, For Screw Spline Attachment	PC-1220

Total Quantity Required

Total Quantity Required	Total List Cost	Discounted Total List Cost	Residual Material Quantity	Residual Waste %	Residual Material Cost
8ft x2, 3ft x4	\$838.00	\$514.53	18ft x1, 2ft x1	41.67%	\$214.39
8ft x3	\$150.00	\$92.10	0.00 ft	0.00%	\$0.00
8ft x3	\$497.00	\$305.16	0.00 ft	0.00%	\$0.00
3ft x4	\$527.00	\$323.58	12ft x1	50.00%	\$161.79
3ft x4	\$444.00	\$272.62	12ft x1	50.00%	\$136.31
12ft	\$264.00	\$162.10	12ft x1	50.00%	\$81.05
3ft x8	\$85.05	\$52.22	0.00 ft	0.00%	\$0.00

Total Profile Cost

Orders Required

Orders Required	Total List Cost	Discounted Total List Cost	Residual Material Quantity	Residual Waste %	Residual Material Cost
1 order	\$64.80	\$39.79	18.00 pcs	90.00%	\$35.81
1 order	\$119.00	\$73.07	42.00 pcs	84.00%	\$61.38
1 order	\$18.30	\$11.24	44.00 pcs	44.00%	\$4.94
1 order	\$46.65	\$28.64	88.00 pcs	88.00%	\$25.21
1 order	\$48.60	\$29.84	96.00 pcs	96.00%	\$28.65
8 orders	\$36.00	\$22.10	0.00 pcs	0.00%	\$0.00
1 order	\$76.95	\$47.25	44.00 pcs	88.00%	\$41.58
1 order	\$76.95	\$47.25	42.00 pcs	84.00%	\$39.69
1 order	\$147.00	\$90.26	46.00 pcs	92.00%	\$83.04
1 order	\$56.70	\$34.81	44.00 pcs	88.00%	\$30.64
1 order	\$95.25	\$58.48	42.00 pcs	84.00%	\$49.13

Total Accessory Cost

Total Quantity Required

Total Quantity Required	Total List Cost	Discounted Total List Cost	Residual Material Quantity	Residual Waste %	Residual Material Cost
224ft	\$405.00	\$248.67	276ft x1	55.20%	\$137.27

Total Gasket Cost

Total Quantity Required

Total Quantity Required	Total List Cost	Discounted Total List Cost	Residual Material Quantity	Residual Waste %	Residual Material Cost
83.75 sqft	\$879.38	\$879.38	N/A	N/A	\$0.00

Total Glass Cost

Total Quantity Required

Total Quantity Required	Total List Cost	Discounted Total List Cost	Residual Material Quantity	Residual Waste %	Residual Material Cost
24.00 joints	\$360.00	\$360.00	N/A	N/A	\$0.00

Total Labor Cost

Bay Distribution Diagrams

