Convertir una fracción a porcentaje

Aumento en (x)	Combinación de Lentillas	Distancia del Objetivo al Motivo	Área de Trabajo cubierta en el Sensor
1/15x 6,66%	Sin Lentillas	10' 11.89" 3,350 _{metros}	14.17" x 21.26" 360 x 560 _{mm}
1/8x 12,50%	1/8x + Objetivo	5' 10.08" 1,780 _{metros}	7.56" x 11.34" 192 x 288 _{mm}
1/6x 16,66%	1/6x + Objetivo	4' 4.64" 1,336 _{metros}	5.67" x 8.50" 144 x 216 _{mm}
1/3x 33,33%	1/4x + 1/6 + Objetivo	2' 1.0" 635 _{milímetros}	2.72" x 4.06" 69 x 103 _{mm}
1/4x 25%	1/4x + Objetivo	2' 11.04" 890 _{milímetros}	3.78" x 5.67" 96 x 144 _{mm}
1/2x 50%	1/2x + Objetivo	1' 5.56" 446 _{milimetros}	1.89" x 2.83" 48 x 72 _{mm}
2/3x 66,66%	1/2x + 1/4 + Objetivo	1' 0.83" 326 _{milímetros}	1.38" x 2.09" 35 x 53 _{mm}
1x 100%	1x + Objetivo	8.70" 221 _{milimetros}	0.94" x 1.42" 24 x 36 _{mm}
1,5x 150%	1x + 1/2 + Objetivo	6' 0.6" 154 _{milímetros}	0.67" x 0.98" 17 x 25 _{mm}
2x 200%	2x + Objetivo	4.25" 108 _{milímetros}	0.47" x 0.71" 12 x 18 _{mm}
3x 300%	2x + 1x + Objetivo	2 .83" 72 _{milimetros}	0.33" x 0.50" 8.4 x 12.6 _{mm}

Donde el "**0%**", de aumento equivale a una relación de "**1:10**", y el "**100**%", de aumento equivale a una relación de "**1:1**"

Combinación de Lentillas	Aumento	Distancia de Trabajo	Distancia de Trabajo
1/15x = (sin lentillas)	6,66%	3,350 _{metros}	19,2 x 28,8 _{cm}
1/8x 12.5% =	12,5%	1,80 _{metros}	19,33 x 29 _{cm}
1/6x 16.66% =	16,66%	1,370 _{metros}	14,66 x 22,00 _{cm}
1/4x = 25%	25%	88,50 _{cm}	9,53 x 14,30 _{cm}
1/8x + 1/6x 12,5% + 16,6% =	7/24x 29,16%	101,00 _{cm}	10,93 x 16,40 _{cm}
1/4x + 1/8x 25% + 12,5% =	3/8x 37,5%	72,00 _{Cm}	7,93 x 11,60 _{cm}
1/4x	5/12x 41,66%	63,00 _{Cm}	6,83 x 10,25 _{cm}
1/2x 50% =	1/2x 50%	44,00 _{Cm}	4,80 x 7,20 _{cm}
1/2x + 1/8x = 50% + 12,5% =	5/8x 62,5%	39,30 _{Cm}	4,30 x 6,50 _{cm}
1/2x + 1/6x 50% + 16,66% =	4/6x 66,66%	36,60 _{Cm}	4,06 x 6,10 _{cm}
1/2x + 1/4x 50% + 25% =	3/4x 75%	31,80 _{cm}	3,53 x 5,30 _{cm}
1/2x	19/24x 79,16%	32,80 _{Cm}	3,68 x 5,52 _{cm}
1/2x + 1/4x + 1/8x = 50% + 12,5% =	7/8x 87,5%	28,20 _{cm}	3,26 x 4,90 _{cm}

Combinación de Lentillas	Aumento	Distancia de Trabajo	Distancia de Trabajo
1/2x + 1/4x + 1/6x = 50% + 25% + 16,66% =	7/8x 91,66%	27,1 _{Cm}	3,13 x 4,7 _{cm}
1x 100% =	1/1x 100%	21,70 _{cm}	24,00 x 36,00 _{mm}
1x 1/8x =	9/8x 112,5%	20,00 _{Cm}	22,66 x 34,00 _{mm}
1x 1/6x =	7/6x 116,66%	19,40 _{cm}	21,66 x 32,50 _{mm}
1x 1/4x 100% ⁺ 25%	5/4x 125%	17,30 _{Cm}	20,00 x 30,00 _{mm}
1x 1/6x 1/8x = 100% + 16,66% + 12,5% =	31/24x 129,16%	18,20 _{Cm}	20,80 x 31,20 _{mm}
1x + 1/4x + 1/8x = 12,5% =	11/8x 137,5%	16,60 _{Cm}	19,33 x 29,00 _{mm}
1x + 1/4x + 1/6x = 16,66% =	17/12x 141,66%	15,80 _{Cm}	18,66 x 28,00 _{mm}
1x 1/2x =	3/2x 150%	14,40 _{Cm}	16,66 x 25,00 _{mm}
1x + 1/2x + 1/8x = 100% + 12,5% =	13/8x 162,5%	13,20 _{Cm}	16,00 x 24,00 _{mm}
1x + 1/2x + 1/6x = 100% + 16,66% =	5/3x 166,66%	12,70 _{Cm}	15,66 x 23,50 _{mm}
$\frac{1x}{100\%} + \frac{1/2x}{50\%} + \frac{1/4x}{25\%} =$	7/4x 175%	12,10 _{Cm}	15,00 x 22,50 _{mm}
$\frac{1x}{100\%} + \frac{1/2x}{50\%} + \frac{1/4x}{25\%} = \frac{1/8x}{12,5\%} =$	15/8x 187,5%	11,00 _{cm}	14,66 x 22,00 _{mm}
$\frac{1x}{100\%} + \frac{1/2x}{50\%} + \frac{1/4x}{25\%} = \frac{1/6x}{16,66\%} =$	23/12x 191,66%	10,80 _{Cm}	14,13 x 21,20 _{mm}



Combinación de Lentillas	Aumento	Distancia de Trabajo	Distancia de Trabajo
2x 200% =	2/1x 200%	10,0 _{Cm}	12,00 x 18,00 _{mm}
2x + 1/8x =	17/8x 212,5%	9,40 _{Cm}	11,46 x 17,20 _{mm}
2x 1/6x = 200% + 16,66% =	13/6x 216,66%	9,20 _{Cm}	11,33 x 17,00 _{mm}
2x + 1/4x =	9/4x 225%	9,00 _{Cm}	10,80 x 16,20 _{mm}
2x 1/6x 1/8x = 200% + 16,66% + 12,5% =	55/24x 229,16%	8,80 _{Cm}	11,13 x 16,70 _{mm}
2x + 1/4x + 1/8x =	19/8x 237,5%	8,10 _{Cm}	10,66 x 16,00 _{mm}
2x + 1/4x + 1/6x = 16,66%	29/12x 241,66%	8,00 _{Cm}	10,40 x 15,60 _{mm}
2x + 1/2x =	5/2x 250%	7,10 _{Cm}	9,33 x 14,00 _{mm}
2x + 1/2x + 1/8x = 12,5%	21/8x 262,5%	6,12 _{cm}	9,20 x 13,80 _{mm}
2x + 1/2x + 1/6x = 16,66%	8/3x 266,66%	5,90 _{cm}	8,93 x 13,40 _{mm}
2x + 1/2x + 1/4x =	11/4x 275%	6,90 _{Cm}	9,26 x 13,90 _{mm}
$\frac{2x}{200\%} + \frac{1/2x}{50\%} + \frac{1/4x}{25\%} = \frac{1/8x}{12,5\%} =$	23/8x 287,5%	6,10 _{Cm}	9,13 x 13,70 _{mm}
2x 1/2x + 1/4x = 1/6x = 16,66% =	35/12x 291,66%	5,90 _{Cm}	8,80 x 13,20 _{mm}
2x + 1x =	3/1x 300%	6,70 _{cm}	8,13 x 12,20 _{mm}

Combinación de Lentillas	Aumento	Distancia de Trabajo	Distancia de Trabajo
2x	25/8x 312,50%	5,90 _{Cm}	8,06 x 12,10 _{mm}
2x 1x 1/6x = 200% + 100% + 16,66% =	19/6x 316,66%	5,90 _{cm}	8,00 x 12,00 _{mm}
2x 1x 1/4x = 25%	13/4x 325,00%	5,90 _{cm}	7,80 x 11,70 _{mm}
$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	27/8x 337,5%	4,90 _{cm}	7,73 x 11,60 _{mm}
2x + 1x + 1/4x + 1/6x = 25%	41/12x 341,66%	4,80 _{Cm}	7,50 x 11,25 _{mm}
2x 1x 1/2x = 200% + 100% + 50%	7/2x 350,00%	5,30 _{Cm}	7,33 x 11,00 _{mm}
$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	29/8x 362,50%	4,50 _{Cm}	7,06 x 10,60 _{mm}
$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	11/3x 366,66%	4,50 _{Cm}	6,93 x 10,40 _{mm}
$\begin{array}{cccccccccccccccccccccccccccccccccccc$	15/4x 375,00%	4,20 _{Cm}	6,76 x 10,15 _{mm}
$2x + 1x + \frac{1/2x}{200\%} + \frac{1/4x}{25\%} + \frac{1/8x}{12,5\%} =$	31/8x 387,50%	3,30 _{Cm}	6,73 x 10,10 _{mm}
2x 1x 1/2x 1/4x 1/6x 200% + 100% + 50% + 25% + 16,66% =	7/12x 391,66%	3,30 _{Cm}	6,70 x 10,05 _{mm}
2x + 1x + 1/2x + 1/4x + 1/6x + 1/8x = 200% + 100% + 50% + 25% + 16,66% + 12,5% = 25%	97/24x 404,16%	2,40 _{Cm}	6,66 x 10,00 _{mm}