




Cable Spool Holder Gridfinity



[VIEW IN BROWSER](#)

updated 16. 12. 2025 | published 16. 12. 2025

Summary

Universal and robust. Can be used with the Gridfinity system if needed

[Hobby & Makers](#) > [Organizers](#)

Tags: [spool](#) [organizer](#) [tool](#) [holder](#) [cable](#) [rc](#)
[spoolholder](#) [electricity](#) [cassette](#) [soldering](#) [electronics](#)
[robotics](#) [repair](#) [solder](#) [outdoor](#) [pcb](#) [fullyprintable](#) [wire](#)
[reel](#) [cableholder](#) [rugged](#) [wirespoolholder](#) [multipurpose](#)
[cablespool](#) [electrician](#) [wirespool](#) [cablereel](#) [gridfinity](#)
[gridfinityorganizer](#) [wirereel](#) [gridfinityspool](#)

This spool holder organizes your cables neat and tidy. It protects against unwanted unraveling, is modular and can be used with the gridfinity eco system. Great to use for outdoor repairs too, since one can carry them without the spool unraveling in the tool bag. Fully printable, no hardware needed. The reel can easily be filled with the power tool adapter. If you want to modify the holder to your own needs, **you are going to find the .step for download too.**

Printing:

Print all parts in the given orientation with 0.2mm layerheight.


Note: Print the Corner part and one Bolt as test print first! If you

discover that the test came out nicely but the bolt just falls out or gets stuck, scale -only- the bolt by increments 1% bigger or smaler until it fits nicely. This is caused by XY-comepnasation/Slicer sometimes messing up the tolerances. Depending on the settings used, one might have to use up to 105% scale for the bolt. If you dont feel comfortable using the printed fasteners afterwards, you are going to find a version for M3 bolts as well. Works with M3x8 to M3x16 bolts

Assembly:

You can put everything together as you want/need. The gridfinity corners can be replaced with a regular corner, if you dont want to use it with the Gridfinity system.

Otherwise assemble all parts as seen in the pictures below. The Bolts are intended to be used with a flat head secrew driver. Assembly procedure is the same for M3 bolts



How to use:

Wind up the spools by hand, before putting them in the holder or use the hand drill tool. be carefull and dont go full speed there, since PLA might melt becaus of excessive friction heat.




Info:

Tested some cable i have at hand, so you can expect the spool to take **roughly** the following amount of wire:

Cable outer diameter [mm]/ [AWG]	Smal Spool capacity [m]/[ft]	Spool capacity [m]/ [ft]
0.9mm / 19AWG	50m / 164ft	100m / 328ft
1.0mm / 18AWG	45m / 147ft	90m / 295ft
1.5mm / 15AWG	25m / 82ft	50m / 164ft

I used this [table](#) to convert outer diameter from mm to AWG

Looking for some bigger reels? Maybe have a try with [these](#) ones:




CHANGE LOG 12.07.2025

- Added a gridfinity corner with NO magnet holes
- Added a knob style wind up tool, intended for hand use without power tools

CHANGE LOG 16.12.2025

Added the .3mf and .step files for download too

Model files





spool_b.stl




sideplate_x2.stl



corner_gridfinitymagnets.stl



corner.stl



corner_cablefeedtrough.stl



bolt_flathead.stl



spoolsmal_a.stl

☐ Optional Part



spoolsmal_b.stl

☐ Optional Part



tool_a.stl



tool_b.stl




UseWithM3Bolts

4 files



sideplate_x2_m3.stl



corner_gridfinitymagnets_m3.stl



corner-m3.stl




corner_cablefeedtrough_m3.stl



Extra Parts

2 files



corner_gridfinitynomagnetholes.stl




tool_handcrank.stl



step and 3mf

2 files



cablespool_gridfinity.step



cablespool_gridfinity.3mf

License

This work is licensed under a
[Creative Commons \(4.0 International License\)](#)



Attribution-NonCommercial

-
- ✗ | Sharing without ATTRIBUTION
 - ✓ | Remix Culture allowed
 - ✗ | Commercial Use
 - ✗ | Free Cultural Works
 - ✗ | Meets Open Definition