

Faculty of Engineering

End Semester Examination May 2025

ME3CO49 Computer Integrated Manufacturing

Programme	:	B.Tech.	Branch/Specialisation	:	ME
Duration	:	3 hours	Maximum Marks	:	60

Note: All questions are compulsory. Internal choices, if any, are indicated. Assume suitable data if necessary. Notations and symbols have their usual meaning.

Section 1 (Answer all question(s))				Marks	CO	BL
Q1. What type of information is essential for manufacturing organizations to make production-related decisions?				1	1	1
<input type="radio"/> Marketing data only	<input type="radio"/> Financial reports only					
<input checked="" type="radio"/> Production schedules, inventory levels, and demand forecasts	<input type="radio"/> None of the above					
Q2. Which system helps in integrating data across different departments in a manufacturing organization?				1	1	1
<input checked="" type="radio"/> Enterprise Resource Planning (ERP)	<input type="radio"/> Customer Relationship Management (CRM)					
<input type="radio"/> Human Resource Management (HRM)	<input type="radio"/> None of the above					
Q3. What is the primary goal of Design for Manufacturing (DFM)?				1	2	1
<input type="radio"/> Increase product complexity	<input checked="" type="radio"/> Reduce manufacturing costs and improve efficiency					
<input type="radio"/> Increase product weight	<input type="radio"/> Limit automation in production					
Q4. Which of the following is not a key principle of DFM?				1	2	1
<input type="radio"/> Reducing the number of parts	<input type="radio"/> Using standard components					
<input checked="" type="radio"/> Using standard material for the components	<input checked="" type="radio"/> Minimizing assembly difficulties					
Q5. Which NC mode is used for drilling and hole-making operations?				1	3	1
<input checked="" type="radio"/> Point-to-point (PTP)	<input type="radio"/> Line contouring					
<input type="radio"/> 2D contouring	<input type="radio"/> 3D contouring					
Q6. What is the function of a Direct Numerical Control (DNC) system?				1	3	1
<input type="radio"/> It replaces CNC machines	<input checked="" type="radio"/> It controls multiple CNC machines from a central computer					
<input type="radio"/> It performs manual machining operations	<input type="radio"/> It is used only for turning operations					
Q7. What is the primary advantage of batch production over job shop production?				1	4	1
<input type="radio"/> Higher flexibility for custom products	<input checked="" type="radio"/> Lower production cost per unit due to economies of scale					
<input type="radio"/> Requires less planning and scheduling	<input type="radio"/> Eliminates the need for material handling					
Q8. Which of the following is a characteristic of job shop production?				1	4	1
<input type="radio"/> High volume, low variety production	<input type="radio"/> Dedicated production lines					
<input checked="" type="radio"/> Functional layout with general-purpose machines	<input type="radio"/> Continuous and automated production					

Q9. What is the primary goal of Rapid Prototyping (RP)?

1 5 1

- Mass production of parts
- Quick fabrication of physical models from CAD data
- Manual design validation
- Reducing the need for automation

Q10. Rapid prototyping primarily involves-

1 5 1

- Subtractive manufacturing
- Additive manufacturing
- Conventional machining
- Molding and casting

Section 2 (Answer all question(s))

Marks CO BL

Q11. Explain the role of enterprise resource planning in meeting the information needs of manufacturing firms.

4 1 2

Rubric	Marks
1 mark for each role of ERP	4

Q12. (a) Differentiate between master production scheduling and material requirements planning.

6 1 4

Rubric	Marks
1 marks for each diffrence	6

(OR)

(b) Draw CIM wheel and explain its major components.

Rubric	Marks
Diagram of CIM wheel	2
Major components	4

Section 3 (Answer all question(s))

Marks CO BL

Q13. What is design for manufacturing? Explain the four key principles of DFM.

4 2 2

Rubric	Marks
What is Design for Manufacturing?	1
Explain the three key principles of DFM	3

Q14. (a) What are the major challenges in transitioning from conventional product design to a CIM-based approach?

6 2 2

Rubric	Marks
1 marks for each challenge	6

(OR)

(b) Define computer-aided process planning. Explain its importance in modern production systems.

Rubric	Marks
Define Computer-Aided Process Planning.	2
Explain its importance in modern production system	4

Section 4 (Answer all question(s))

Marks CO BL

Q15. What is a CNC machine? Mention three advantages of CNC over conventional machines.

4 3 2

Rubric	Marks
What is a CNC Machine?	1
Mention three advantages of CNC over conventional machine.	3

Q16. (a) What is adaptive control in CNC machining? How does it improve machining performance?

6 3 2

Rubric	Marks
What is adaptive control in CNC machining	2
How does it improve machining performance?	4

(OR)

(b) Explain point-to-point and 2D contouring in NC machining with two examples of each.

Rubric	Marks
Explanation of Point to Point and 2D Contouring	4
Two examples of each	2

Section 5 (Answer all question(s))

Marks CO BL

Q17. What are part families? Why are they important in manufacturing?

4 4 2

Rubric	Marks
Part Families	2
Importance in manufacturing	2

Q18. (a) What is a flexible manufacturing system? What are the key components?

6 4 2

Rubric	Marks
Flexible Manufacturing System	2
key components	4

(OR)

(b) Explain the advantages of using robots and automated guided vehicles in material handling in manufacturing.

Rubric	Marks
Advantage of using Robots	3
Advantage of using Automated Guided Vehicle.	3

Section 6 (Answer all question(s))

Marks CO BL

Q19. What is rapid prototyping? Why is it important in modern manufacturing?

4 5 2

Rubric	Marks
What is Rapid prototyping	2
Importance in modern manufacturing	2

Q20. (a) Explain the stereolithography process with a neat diagram.

6 5 2

Rubric	Marks
Explain Stereolithography process	4
Neat diagram of the process	2

(OR)

(b) Explain the fused deposition modeling process with a neat diagram.

Rubric	Marks
Explain Fused Deposition Modeling process	4
Neat Diagram of the process	2
