
[4]

Q.6 Attempt any two:

- Write the formula for finding the volume of 5 (a) Cylinder, (b) Frustum of cone and (c) Segment of sphere.
- ii. Find the cost of 2000 C I pulleys as shown in the fig. Its surfaces are to be 5 machined after casting. The pattern is supplied by the customer. Following data is to be used. Cost of metal = Rs 20/kg, Moulds prepared by each worker = 20, Melting charges = 20% of metal cost. Machining allowance on each side = 2 mm. Wages of each moulder = Rs 160 / day. Density of cast iron = 7.2 gm/cc. Overhead charges = 25% of metal cost.



- iii. Describe the following methods:
 - (a) The Average ordinate rule
 - (b) The trapezoidal rule

Total No. of Questions: 6

Total No. of Printed Pages:4

Enrollment No.....



5

Faculty of Engineering

End Sem (Odd) Examination Dec-2018 OE00007 Mechanical Estimation & Costing

Programme: B.Tech. Branch/Specialisation: All


Maximum Marks: 60 Duration: 3 Hrs.

Note: All questions are compulsory. Internal choices, if any, are indicated. Answers of Q.1 (M0)

		ould be written in full instead of only				
Q.1	i.	Main factors to be considered while	= =]	
		(a) Quantity of material	(b) Availability of m	aterial		
		(c) Transportation of material	(d) All of these			
	ii.	Qualification of estimator is:			1	
		(a) Should be an engineer				
		(b) Understanding of manufacturing	g process			
		(c) Knowledge of sketch and drawing	ng			
		(d) All of these				
	iii.	iii. Which of the following is Direct material for machine shop?				
		(a) High speed steel	(b) Coolant			
		(c) Cotton	(d) All of these			
	iv.	Which of the following is considered	ed as indirect expenses	for a factory?	1	
		(a) Stationary (b) Cleaner	(c) Crane driver	(d) All of these		
	v.	Which operation cannot be perform	ed on manual milling i	machine?	1	
		(a) Side cutting (b) Profiling	(c) Slot cutting	(d) Turning		
	vi.	Welding operation does not include	;		1	
		(a) Machining cost	(b) Power cost			
		(c) Electrode cost	(d) All of these			
	vii.	ii. A product becomes obsolete when there is:				
		(a) Similar product at low cost				
		(b) New product at latest technolog	y			
		(c) Stops proper functioning				
		(d) All of these				
		• •		РΤ	\mathbf{O}	

	viii.	Calculation of depreciation rate is important because of:		1
		(a) Replacement of assets	(b) Tax benefits	
		(c) Avoid run out of business	(d) All of these	
	ix.	Mensuration is important for calculat	ing	1
		(a) Area and volume		
		(b) Quantity of material required		
		(c) Material cost		
		(d) All of these		
	х.	Area of irregular figures can be calcu	•	1
			(b) The trapezoidal rule	
		(c) The Simpson's rule	(d) All of these	
Q.2	i.	List any five objectives of estimation		2
Q.2	ii.		considered while estimating the cost	3
	11.	of a product?	considered with estimating the cost	3
	iii.	•	imation. Also describe qualities and	5
		function of an estimator.	1	
OR	iv.	Define standard cost. Differentiate b	etween estimation and costing. Show	5
		the advantages of efficient costing		
	_		_	
Q.3	i.	Draw the block diagram of componen		2
	ii.	_	ocation of overhead cost in the	3
	:::	organisation.	is Do 60,000 and the distributor	5
	iii.	-	is Rs. 60,000 and the distributor of the market price. It is found	3
			% of factory cost. The material	
		cost, labour cost and factory	•	
			2,000, determine the profit on each	
		machine. Neglect other overheads.	2,000, determine the profit on each	
OR	iv.	· ·	e: Marginal Cost, out of pocket Cost,	5
		Sunk cost, Differential cost, variable		
		,		
Q.4	i.	Define cutting speed and feed related	d to lathe. List at least six operations	4
		performed in machine shop.		

ii. A product shown in figure below is to be turned from 35 mm 6 diameter and 150 mm long MS bar stock. Calculate the machining time required if depth of cut is not to exceed 5 mm and cutting speed is 20 m/min. Feed is 1 mm/rev. for drilling and facing. Feed for turning is 2 mm/rev



- OR iii Estimate the cost of weld from the following data: Thickness of plate =10 6 mm; Electrode diameter = 6 mm; Minimum arc voltage =30 volts; Current used = 250 Amperes; Welding speed = 10 m/hour; Electrode used/meter of weld= 0.350 Kg; Labour rate= Rs. 40/hr; Power rate = Rs. 3/Kwh; Electrode rate = Rs. 8/Kg; Efficiency of welding m/c= 50%; Connecting ratio= 0.4; Overhead charges= 80% of direct charges; Labour accomplishment factor =60%.
- Q.5 i. Explain Obsolescence. Explain the sinking fund method for calculating 4 the depreciation
 - ii. The automatic screw cutting machine has been purchased for Rs. 60,000. 6
 In the start of second year a motor is fitted into the machine costing Rs.
 2000. Its scrap value at the end of 10 years is estimated as Rs. 12,000.
 Calculate the following by reducing balance method:
 - (a) Depreciation rate (b) Depreciation in first two years and last two years
- OR iii. A car was purchased for Rs 96,000. Its estimated life period **6** is ten years. The residual value of the car after its useful life is Rs 24,000. Rs. 5000 added in for name transfer.
 - (a) Calculate the depreciation rate for first two year using sum of digit year.
 - (b) Calculate the depreciation fund at the end of two years.

P.T.O.

Marking Scheme

OE00007 Mechanical Estimation & Costing

		0-0000, 0-0000		
Q.1	i.	Main factors to be considered while prepare the detailed es	timate is	1
		d) All of the above		
	ii.	Qualification of estimator is:		1
		d) All of the above		
	iii.	Which of the following is Direct material for machine shop	?	1
		a) High speed steel		
	iv.	Which of the following is considered as indirect expenses	for a factory?	1
		(d) All of these	•	
	v.	Which operation cannot be performed on manual milling n	nachine?	1
		(d) Turning		
	vi.	Welding operation does not include		1
		a) Machining cost		
	vii.	A product cannot becomes obsolete when there is:		1
		(d) All of these		
	viii.	Calculation of depreciation rate is important because of:		1
		(d) All of these		
	ix.	Mensuration is important for calculating		1
		(d) All of these		
	х.	Area of irregular figures can be calculated by:		1
		(d) All of these		
Q.2	i.	Any five objectives of estimation.		2
		Five objectives		
	ii.	Elements to be considered while estimating the cost of a pr	oduct?	3
		Each element 1 mark	(1 mark * 3)	
	iii.	Source of error	3 marks	5
		Qualities and function of estimator	2 marks.	
OR	iv.	Standard cost	2 marks	5
		Difference between estimation and costing	2 marks	
		Advantages of efficient costing	1 mark.	
Q.3	i.	Block diagram of components of cost.		2
(ii.	Any Three methods of allocation of overhead cost in the or	ganisation	3
		1 mark for each	(1 mark * 3)	
	iii.	Material cost	1 mark	5
				-

4 4
6
4
4
4
4
4
4
4
6
6
U
5
5
5
-
