

TALLY SHEET



T00E1SLD

Check Name:

HM-WP CC-N418LA DEC2018 [E.O. 's]

Work Order No: WO - 103867625		Start Date: 26-Dec-2018 05:00		
Aircraft:	Flight Hours:	Flight Cycles:		
B767F - N418LA	TSN: 57247,26 TSO: 57247,26 C	CSN: 14849 CSO: 14849		

Task List

ne	Zone	Task Name	Barcode	Checked
1	144,198,21 1	(29-015-00-01-OP(JIC) (AUTO&MANUAL RAT DEPLOYMENT SYSTEMS)	T00D788D	
2		AD-B767-27-A0009(JIC) (FLIGHT CONTROLS - Elevator - Repetitive Pogo Check)	T00D6M5C	
3		AD-B767-27-A0011(JIC) (FLIGHT CONTROLS - Elevator - Repetitive Mis-Rig Check)	T00D77V9	
4		AD-B767-27-A0016 (JIC) (FLIGHT CONTROLS / RUDDER AND ELEVATOR CONTROL SYSTEM / FREEPLAY INSPECTION)	T00D6U47	
5		AD-B767-27-A0053 PART 1 (JIC) (FLIGHT CONTROLS / RUDDER CONTROL SYSTEM / LUBRICATION)	T00D6M5E	
6		AD-B767-27-A0053 PART 2 (JIC) (FLIGHT CONTROLS / ELEVATOR CONTROL SYSTEM / LUBRICATION)	T00D6M5T	
7		AD-B767-28-A0495 (JIC) (FUEL - Distribution - Engine Fuel Feed Boost and Override/Jettison Pump Wire Bundle Sleeve Inspection/Replacement)	T00A29ZD	
8		AD-B767-28-A0497 (GROUP 14)(JIC) (FUEL - Engine Fuel Feed System - Fuel Boost Pump and Override/Jettison Pump Wiring Change)	T0062BCC	
9		AD-B767-34-A2383 PART1 (JIC) (NAVIGATION - Air Data System - Altimetry System Test)	T00D74WJ	
10		AD-B767-34-A2383 PART2 (LAN) (JIC) (NAVIGATION - Air Data System - Altimetry System Test)	T00D74WN	
11		AD-B767-34-A2383 PART2 (LAN) (JIC) (NAVIGATION - Air Data System - Altimetry System Test)	T004QC83	
12		AD-B767-34-A2383 PART3 (JIC) (NAVIGATION - Air Data System - Altimetry System Test)	T00DHB55	
13		AD-B767-34-A7627 PART 1 (JIC) (ATC TRANSPONDER SYSTEM TEST)	T00E3SAR	
14		AD-B767-34-A7627 PART 1 (JIC) (ATC TRANSPONDER SYSTEM TEST)	T00CP8C6	
15		AD-B767-51-A0061 PART 1 (JIC) (STRUCTURES / AIRFRAME DRAINAGE / CANTED PRESSURE DECK DRAIN INSPECTION AND CLEANING)	T00D6W3Z	
16		AD-B767-51-A0061 PART 2 (JIC) (STRUCTURES / AIRFRAME DRAINAGE / CANTED PRESSURE DECK DRAIN INSPECTION AND CLEANING)	T00A1X9V	

Date Printed: 15-Dec-2018 Form TS-001 Rev 01 Page: 1 de 4

		T00E1SLD	
17		SECTION 41 - STATION 287, BL 25 NOSE WHEEL WELL BULKHEAD VERTICAL STIFFENERS CRACK - INSPECTION AND REPAIR)	T00BQ61Y
18		AD-B767-53-A6427 PART 2 (RH-INITIAL)(GROUP 1)(JIC) (FUSELAGE - SECTION 41 - STATION 287, BL 25 NOSE WHEEL WELL BULKHEAD VERTICAL STIFFENERS CRACK - INSPECTION AND REPAIR)	T00BQ618
19		AD-B767-57-A0002 PART 1 (LH)(JIC) (External Wing Skin surface / Detailed and HFEC inspection at the Aft Pitch Load Fitting)	
20		AD-B767-57-A0002 PART 2 (RH)(JIC) (External Wing Skin surface / Detailed and HFEC inspection at the Aft Pitch Load Fitting)	T00D60KT
21		AD-B767-57-A0002 PART 3 (MSN>34245)(LH)(JIC) (Wing Skin Bolt Open-Hole HFEC inspection at the Aft Pitch Load Fitting / Group 2 / Config. 6 (Airplanes with General Electric Engines and without S.I.P. embodied))	T00486VA
22		AD-B767-57-A0002 PART 4 (MSN>34245)(RH)(JIC) (Wing Skin Bolt Open-Hole HFEC inspection at the Aft Pitch Load fitting / Group 2 / Config. 6 (Airplanes with General Electric Engines and without S.I.P. embodied))	T00486UM
23		AD-B767-57-A7490 PART 1 (REPETITIVE)(LH WING)(JIC) (HFEC INSPECTION OF LOWER WING SKIN EXTERNAL SURFACE - STRINGER L-6.5)	T00D5UAH
24		AD-B767-57-A7490 PART 2 (REPETITIVE)(RH WING)(JIC) (HFEC INSPECTION OF LOWER WING SKIN EXTERNAL SURFACE - STRINGER L-6.5)	
25			T00D5UC6
26		LOWER OUTBOARD WING SKIN EXTERNAL SURFACE - STRINGER L-	T00D5UAS
27		AD-B767-78-A0012 (JIC) (EXHAUST (CF6-80C2 ENGINES) - THRUST REVERSER CONTROL SYSTEM - DIRECTIONAL PILOT VALVE - LEAK CHECK)	T00D4FPE
28			T00D4FNK
29			T00D7C1B
30		DA-08-0007-08 (JIC-L7) (WEIGHING OF BOEING 767-300 AIRPLANES)	T00A2DKE
31		DA-08-0007-08 (JIC-MODIFICATION) (WEIGHING OF BOEING 767-300 AIRPLANES)	T00A2DKF
32		BOEING 767-300 AIRPLANES))	T00A2DKX
33		CAUTION ON HANDLING)	T00D7874
34	135,136	IH-B767-21-A1504 (JIC-INST) (BOFRIP - Check of the Cooling Packs)	T00ECFYM
35	136,120,11 9,135	IH-B767-21-A1738 (JIC-INST) (BOFRIP - System Test - Cooling Pack System)	T00ECFZ6
36	5,136	Temperature Control)	T00ECFYX
37	5,136	Valve)	T00ECH98
38	233,243,24 4,253,254,2 11		T00ECFYR
39	120	IH-B767-21-A1742 (JIC-INST) (BOFRIP - Zone Temperature Controller BITE Test")	
40	120	Controller BITE Test)	T00ECG5V
41		IH-B767-21-A2460 (JIC) (BOFRIP - Clean the Flow Control and Shutoff Valve)	T00ECGAB

Page: 2 de 4

		T00E1SLD	
42		IH-B767-21-B0486 PART 1 (LH) (JIC) (COOLING PACK SYSTEM - BOFRIP - INSPECTION TO PACK COMPONENTS)	T00EPGEB
43		IH-B767-21-B0486 PART 2 (RH) (JIC) (COOLING PACK SYSTEM - BOFRIP - INSPECTION TO PACK COMPONENTS)	T00EPGGM
44	121,122	IH-B767-21-B0962(JIC) (CLEAN & VISUAL INSPECTION - EQUIPMENT COOLING SYSTEM - CONAMINATION FROM	T00EZ712
45		IH-B767-30-A7949 PART 1 (JIC) (ICE AND RAIN PROTECTION - Flight Compartment Window Anti-Icing - Windshield Inspection)	T00D04RB
46		IH-B767-30-A7949 PART 2 (JIC) (ICE AND RAIN PROTECTION - Flight Compartment Window Anti-Icing - Windshield Inspection)	T00D04PA
47	731	IH-B767-32-A4811-LH-CONF2(JIC) (MLG SEALS REPLACEMENT WITH LOWER BEARING ASSY OF 3/8")	T00AENCD
48	741	IH-B767-32-A4811-RH-CONF2(JIC) (MLG SEALS REPLACEMENT WITH LOWER BEARING ASSY OF 3/8")	T00AENAV
49		IH-B767-53-A1706 (REQ) (PREVENTIVE ACTIONS TO AVOID CORROSION BETWEEN WING CENTER SECTION (WCS) REAR SPAR WEB AND REAR SPAR BULKHEAD FITTINGS)	T00D6GLY
50	211	IH-B767-56-B0009 PART 1 (JIC) (Flight compartment windows, inspection left No. 1 windows (Windshields))	T00ECWUV
51	212	IH-B767-56-B0009 PART 2 (JIC) (Flight compartment windows, inspection right No. 1 windows (Windshields))	T00ECWT4
52		(UNASSIGNED - IH-B767-57-A0891 PART 4 (JIC) (WINGS - LEADING) EDGE AND LEADING EDGE DEVICES - SLAT TRACK HOUSING DRAIN	T00E9QZY
53	211	CHECKLIST B767 IH-B767-70-A8926-CHECK-C(JIC) (RUN UP CHECKLIST B767)	T00EWX2X
54		IH-CF6-80C2-73-A3800 (JIC) (PS3 MANIFOLD P-CLAMPS INSPECTION)	T00D5HM0
55		IH-CF6-80C2-73-A3800 (JIC) (PS3 MANIFOLD P-CLAMPS INSPECTION)	T00D5HLQ
56		IH-CF6-80C2-73-A5876 (JIC) (ECU CABLE - INSPECTIONS AND CLEANING ELECTRICAL CONNECTORS OF START VALVE)	T00EV7VG
57		IH-CF6-80C2-73-A5876 (JIC) (ECU CABLE - INSPECTIONS AND CLEANING ELECTRICAL CONNECTORS OF START VALVE)	T00EV800
58		MD-B767-34-A2573 (JIC) (ON GROUND STANDBY COMPASS MAGNETIC SWING)	T00D73BK
59		UNASSIGNED - OT-72-0006-04(JIC) (COMBUSTOR SECTION AND HPT STAGE 1 AND 2 BLADES BORESCOPE INSPECTION)	T00ELM6Y
60		RP-21-1067-00-PARTII(JIC-INSPECTION) (AIR CONDITIONING PACK 1 AND 2 DUCT ASSY MIX-MUFF INLET, INSPECTION)	T00D6GN3
61		RP-21-1067-00-PARTII(JIC-L7) (AIR CONDITIONING PACK 1 AND 2 DUCT ASSY MIX-MUFF INLET, INSPECTION)	T00D6GN2
62		RP-54-1700-01-(JIC-INSPECTION) (ENGINE N°1, RH STRUT MIDSPAR FITTING, RH BOLT INSPECTIONS OF SHIM MIGRATED.)	T00D5SU9
63		RP-54-1700-01-(JIC-L7) (ENGINE N°1, RH STRUT MIDSPAR FITTING, RH BOLT INSPECTIONS OF SHIM MIGRATED.)	T00D5SU8
64		SI-55-0006(JIC-INSPECTION) (INSPECTION SHIM AT HORIZONTAL STABILIZER CUTOUT CENTER SECTION AT LH LOWER BODY LONGERON STA 1809.5)	T00D7B8A
65		SI-57-0200(REQ) (INSPECTION OF SHIM MIGRATED AT RH WING - DIAGONAL BRACE FWD PITCH LOAD FITTING INBOARD SIDE BOLT)	T00D5SU5
66		SI-B767-53-A4746-00(REQ) (PERFORM INSPECTION OF FUSELAGE UNDER CABIN FLOOR STRUCTURE IN STIFFENER AT LBL 40.0 STA 246 FLOOR BEAM.)	T00D60C2
67		SI-B767-53-A4815-00 (REQ) (REPETITIVE INSPECTIONS OF MIGRATED SHIMS AT LEVEL OF STA 1582 AT STGR END OF S-17LH, S-19RH, S-15RH, S-9LH, S-18LH)	T00D5HKY

	110		r critimisa by (F		Oignatule		Date
gnatı kill	ures:	ours	Performed By (F	Print)	Signature		Date
84	· · · · · ·					T00EUTRZ	
83		IH-CF6-80C2-36-A8711 (JIC) (PNEUMATIC PRESSURE REGULATING VALVE CONTROLLER (PRVC) PRVC HOSE ASSEMBLY REPLACEMENT)					
82		IH-CF6-80C2-36-A8711 (JIC) (PNEUMATIC PRESSURE REGULATING VALVE CONTROLLER (PRVC) PRVC HOSE ASSEMBLY REPLACEMENT)			T00D60CR		
81		IH-B767-23-A2426 (JIC-INSTRUCTIONS) (BOFRIP - HF Communication System - System Test)			T00F13H5		
80	119,211,21 2	IH-B767-34-A1745 (JIC-INST) (BOFRIP - System Test - Weather Radar System)			T00F0UVE		
79		AD-B767-78-A0006 PART 2 (JIC) (ENGINE 2 - THRUST REVERSER CONTROL SYSTEM - OPERATIONAL TEST (CF6-80C2 ENGINES))				T00EXTLY	
78		AD-B767-78-A0006 PART 1 (JIC) (ENGINE 1 - THRUST REVERSER CONTROL SYSTEM - OPERATIONAL TEST (CF6-80C2 ENGINES))				T00EXU7A	
77	119,211,21 2	IH-B767-34-A1544 (JIC-INST) (BOFRIP - Operational Test - Weather Radar System)				T00F0UMH	
 76		IH-CF6-80C2-24-A4852 (REQ) (DECAL INSPECTION - PRESSURE DIFFERENTIAL INDICATOR (DPI) POP OUT)				 T00EXY9F	
75		CLOSE-B767	CLOSE-B767 ZONA100 (Master Panel Card B767 ZONA 100)				
74		OPEN-B767	ZONA100 (Master Pan	el Card B767 ZOI	NA 100)	T00F0DQ8	
73		CLOSE-B767	ZONA300 (Master Pa	nel Card B767 Z0	DNA 300)	T00F0DQ7	
72		OPEN-B767	ZONA300 (Master Pan	el Card B767 ZOI	NA 300)	T00F0DQ6	
71		ACTUATOR- SHAFT SPLINES AND SPHERICAL GEAR TEETH - LUBRICATION) SL-52-0127-00(JIC-TEST) (CARGO DOOR LATCH/HOOK ACTUATOR- SHAFT SPLINES AND SPHERICAL GEAR TEETH - LUBRICATION)				T00D7B98	
70		SL-52-0127-00(JIC-MODIFICATION) (CARGO DOOR LATCH/HOOK				T00D7B9A	
69		SL-52-0127-00(JIC-L7) (CARGO DOOR LATCH/HOOK ACTUATOR- SHAFT SPLINES AND SPHERICAL GEAR TEETH - LUBRICATION)			T00D7B99		
		SI-B767-53-A4824(REQ) (INSPECTION AT UNDER CABIN FLOOR STRUCTURE STA 246 LBL 50 ANGLE WITH CRACK REPAIRED.)			T00D5TRC		