N/A



ENGINEERING AND MAINTENANCE

Workscope #

Revision #

*** CANN *** PLEASE ROB U3L LOWER EMERG EQUIP STWG COMPT LOCK (P/N 1437RNSTKA486) TO SERVICE VH-OQJ

T00KJDVE

Rego or Serial No A/C Type or Part No Work Package Location **VH-OQI AUH/BASE** 380 VH-OQI 12YR + GEARS 04FEB23 AUH **QFXXXX TRU03**

Parent Assembly : AIRBUS A380-840 - VH-OQI Issue to account

: J388028 (OQI CHECK 12.1 OFSHORE

MAINT CHECK)

: 25-23 - LININGS AND FURNISHINGS Inventory **Config Position** : 25-23

Parent Req

Block

Zones

Repetitive Task for

Panels

TASK DESCRIPTION/INSTRUCTION

Skills/Labour: 1 X MECH

Type - Subtype : AD-HOC TASK -

Task Priority:

Description :

PLEASE ROB U3L LOWER EMERG EQUIP STWG COMPT LOCK (P/N 1437RNSTKA486) TO

SERVICE VH-OQJ

REFER CMM 25-27-96 FIG 16, GRAPHIC "D" ITEM 60 FOR DETAILS (ATTACHED)

Instructions : nil

	\sim		•			_	
TF		NII		ΛШ	- 1)	Λ	

Description **Notes** Name

Note: If Technical data has not been printed, navigate to the Task Information tab and select the magnifying glass in the Hyperlink column.

ACTIONS				NOT FOR HARD COP	Y ACTION
SKILL	ROLE	USER	STAFF/AUTH No	ACTION	STEPS
MECH	Tech	Kurkowski, Christopher	630956	Action 1. Kurkowski, Christopher,18-Oct-2022 17:47 C/O REMOVAL OF U3L LOWER EMERG EQUIP STWG COMPT LOCK ASSY I.A.W. CMM 25-27-96.	1
MECH	Cert	Nair, Shannon	QE1028776	Action. Certified	

JOB CARD STEPS					
Order	Description	Job Step Action	Sign	Certify	Status
1	PLEASE REMOVE U3L LOWER EMERG EQUIP STWG COMPT LOCK ASSY IAW CMM 25-27-96		Christopher Kurkowski	Shannon Nair	COMPLETE
2	PLEASE INSTALL U3L LOWER EMERG EQUIP STWG COMPT LOCK ASSY IAW CMM 25-27-96				

Generated By: Date Printed: 22-Dec-2022 18:00 Page: 1 of 4

Revision # : N/A

*** CANN *** PLEASE ROB U3L LOWER EMERG EQUIP STWG COMPT LOCK (P/N 1437RNSTKA486) TO SERVICE VH-OQJ

Workscope # : 1



PART REC	QUIREMENTS		NOT FOR HARD COPY ACTION
Qty	Part Number	Part Grp / Config Slot	Part Note
1	1437RNSTKA486	1437RNSTKA486 (LOCK ASSY)	

PARTS TO BE REMOVED				NOT FOR	HARD COPY	ACTION
Qty	Part Grp/Config Slot	Position	Part No	Serial No/ Batch No	Reason	Action
1	1437RNSTKA486 (LOCK ASSY)		1437RNSTKA486	BN 13095041	ROBBED	Action 1

PARTS TO BE INSTALLED				NOT FOR HARD	COPY ACTION
Qty	Part Grp/Config Slot	Position	Part No	Serial No/ Batch No	Action
1	1437RNSTKA486 (LOCK ASSY)		1437RNSTKA486		

MEASUREMENTS			
Parameter	Inventory	Value	Unit

TOOLS		NOT FOR HARD COPY ACTION		
Part No	Description	Serial Number	Action	

PANELS		NOT FOR HARD COPY ACTIO		
Panel	Zone	Labour	Maintenance Tasks	Status



Revision #

N/A

*** CANN *** PLEASE ROB U3L LOWER EMERG EQUIP STWG COMPT LOCK (P/N 1437RNSTKA486) TO SERVICE VH-OQJ

TOOKJDVE

Workscope # : 1

HARDCOPY ACTION		
ACTION TAKEN / PROGRESSIVE CERTIFICATION	SIGN Staff No / Date	CERTIFY Auth No / Date
	_	

N/A

ENGINEERING AND MAINTENANCE

Revision #

*** CANN *** PLEASE ROB U3L LOWER EMERG EQUIP STWG COMPT LOCK (P/N 1437RNSTKA486) TO SERVICE VH-OQJ

Workscope #



						T00KJDVE
PARTS REI	MOVED					
Qty	Position	Part No.		Seria	al/ Batch No.	Reason
PARTS INS	TALLED					
Qty	Position	Part No.		Seria	al/ Batch No.	RCN
FUNCTIONAL CHECK SHEE NO. INDEPENDEN		ATTACH SHEET REGISTER 1 2 3 4 5 6 7 8 9 10		SUPPLEME	NTARY CARDS RAISED	
INSPECTION SHEET NO.						
FINAL CERTIFICATION						
N/A If task deferred			REASON:			
	Cert No.:		SIG: Cert No		DA1	ΓE:

CARD CLEARANCE THE PERSON SIGNING THIS WILL BE RESPONSIBLE TO ENSURE THAT ALL WORK ON THIS CARD HAS BEEN ACTIONED AND CERTIFIED CORRECTLY

SIGNATURE:
DATE

Generated By: Date Printed: 22-Dec-2022 18:00 Page: 4 of 4

N/A



ENGINEERING AND MAINTENANCE

Revision # Workscope #

*** TSR *** RTL 310 SEAT BELT OF GUEST SEAT 4F IS INOP Reported By: SCHLACHTE Staff No: EF-131.

NON-ROUTINE

T00HGXM8

Rego or Serial No

A/C Type or Part No

Work Package

Location

VH-OQI

380

VH-OQI 12YR + GEARS 04FEB23 AUH **QFXXXX TRU03**

AUH/BASE

Parent Assembly

: AIRBUS A380-840 - VH-OQI

Issue to account

: J388028 (OQI CHECK 12.1 OFSHORE

MAINT CHECK)

Inventory

: 25-20 - PASSENGER COMPARTMENT

Block

Config Position Zones

: 25-20

Parent Req

Repetitive Task for

Panels

TASK DESCRIPTION/INSTRUCTION

Skills/Labour: 1 X MECH

Type - Subtype : CORRECTIVE ACTION -

Task Priority:

Description:

Instructions : nil

TECHNICAL DATA

Name

Description

Notes

Note: If Technical data has not been printed, navigate to the Task Information tab and select the magnifying glass in the Hyperlink column.

FAULT INFORMATION

Found During Task: QFA6017

Raised By : Christopher Simpson **Failed System**

25-20 - PASSENGER COMPARTMENT

Fault Source

: TECMAINT

Logbook Ref

TOQI24SEP20310

Fault Description

Christopher Simpson, 25-SEP-2020 09:34 UTC

SEAT BELT OF GUEST SEAT 4F IS INOP

Reported By: SCHLACHTE

Staff No: EF-131

MOC COMMENT 25SEP20 LJO27 - DEFECT NOT MEL APPLICABLE. MEL NOT REQUIRED.

MEASUREMENTS REQUIRED

Generated By: Date Printed: 22-Dec-2022 18:00 Page: 1 of 4

: N/A

NON-ROUTINE

*** TSR *** RTL 310 SEAT BELT OF GUEST SEAT 4F IS INOP

Reported By: SCHLACHTE Staff No: EF-131.

Workscope # : 9

Revision #

T00HGXM8

ACTIONS				NOT FOR HARD COP	Y ACTION
SKILL	ROLE	USER	STAFF/AUTH No	ACTION	STEPS
LOG	Log	Simpson, Christopher	189846	Action 1. Simpson, Christopher,25-Sep-2020 09:34 DISPATCH IAW MEL 25-20-05A SEE NOTE 1 OF MEL 25- 20-01A GUEST SEAT BLOCKED AND PLACARDED DO NOT OCCUPY TO HOLD Authorisation Number: EF-131	

JOB C	ARD STEPS				
Order	Description	Job Step Action	Sign	Certify	Status

PART REQUIREMENTS			NOT FOR HARD COPY ACTION
Qty	Part Number	Part Grp / Config Slot	Part Note

PARTS TO BE REMOVED				NOT FOR	HARD COPY	ACTION
Qty	Part Grp/Config Slot	Position	Part No	Serial No/ Batch No	Reason	Action

PARTS TO BE INSTALLED				NOT FOR HARD	COPY ACTION
Qty	Part Grp/Config Slot	Position	Part No	Serial No/ Batch No	Action
MEASURE	MENTS				

MEAGOREMENTO							
Parameter	Inventory	Value	Unit				
Select Failure Category ()	25-20 - PASSENGER COMPARTMENT	MIS/BRKN					

TOOLS		NOT FOR HARD	COPY ACTION
Part No	Description	Serial Number	Action

PANELS		NOT FOR HARD CO	PY ACTION	
Panel	Zone	Labour	Maintenance Tasks	Status

N/A

NON-ROUTINE

Revision #

*** TSR *** RTL 310 SEAT BELT OF GUEST SEAT 4F IS INOP Reported By: SCHLACHTE Staff No: EF-131.

Workscope # : 9

T00HGXM8

COPY ACTION		
ACTION TAKEN / PROGRESSIVE CERTIFICATION	SIGN Staff No / Date	CERTIFY Auth No / Date

Revision # N/A

*** TSR *** RTL 310 SEAT BELT OF GUEST SEAT 4F IS INOP Reported By: SCHLACHTE Staff No: EF-131.

Workscope #

NON-RC	DUTINE					T00HGXM8
PARTS REI	MOVED					
Qty	Position	Pa	rt No.	Ser	ial/ Batch No.	Reason
PARTS INS	TALLED					
Qty	Position	Pa	rt No.	Seri	ial/ Batch No.	RCN
FUNCTIONAL CHECK SHEE NO.	Т		H SHEET REG 4 5 6 7 8		SUPPLEMEN	NTARY CARDS RAISED
INDEPENDEN INSPECTION SHEET NO.	Т					
	FINAL CERTIFICATIO	N				
	N/A If task deferred		REASON	l:		
	Cert No.: _		SIG: Cert No.		DAT	E:
					CARD CLEARANC	

THE PERSON SIGNING THIS WILL BE RESPONSIBLE TO ENSURE THAT ALL WORK ON THIS CARD HAS BEEN ACTIONED AND **CERTIFIED CORRECTLY**

SIGNATURE:	
DATE	

Generated By: Date Printed: 22-Dec-2022 18:00 Page: 4 of 4

Revision #

23

40

J-380-05-21-50-210-803 (GENERAL VISUAL INSPECTION OF THE **LOWER DECK AFT CARGO COMPARTMENT. (EWIS))**

Workscope #

J-380-05-21-50-210-803

T005REAM

A/C Type or Part No Work Package Rego or Serial No Location VH-OQI 380 VH-OQI 12YR + GEARS 04FEB23 AUH **AUH/BASE QFXXXX TRU03**

Parent Assembly : AIRBUS A380-840 - VH-OQI Issue to account : J388028 (OQI CHECK 12.1 OFSHORE

MAINT CHECK)

Inventory : 05-21 - ZONAL INSPECTION : LOWER HALF : 6YR (6YR-CHECK)

OF FUSELAGE

: 05-21 **Parent Req**

R-380-ZL-151-00002-01 (GENERAL VISUAL INSPECTION OF THE LOWER

DECK AFT CARGO COMPARTMENT.

(EWIS) ** PLANNING ALERT **)

Zones : 151, 152 Repetitive Task for

Panels

Config Position

Description

TASK DESCRIPTION/INSTRU	CTI	ON
-------------------------	-----	----

INSPECTION - GENERAL Skills/Labour: 1 X MECH Type - Subtype Task Priority:

VISUAL INSPECTION 1. J-380-05-21-50-210-807 covers the requirements of J-380-05-21-50-210-803.

2. THIS INSPECTION REQUIRES THE REMOVAL OF: SIDEWALL PANELS Z150;

Instructions : Accomplish A380 AMM 05-21-50-210-803-A

TECHNICAL DATA					
Name	Description	Notes			
AMM 05-21-50-210-803-A REV60					

Note: If Technical data has not been printed, navigate to the Task Information tab and select the magnifying glass in the Hyperlink column.

ACTIONS				NOT FOR HARD COPY ACTION		
SKILL	ROLE	USER	STAFF/AUTH No	ACTION	STEPS	

Generated By: Date Printed: 22-Dec-2022 18:02 Page: 1 of 5 ENGINEERING AND MAINTENANCE Revision # : 23

J-380-05-21-50-210-803 (GENERAL VISUAL INSPECTION OF THE LOWER DECK AFT CARGO COMPARTMENT. (EWIS))

Workscope # : 40

J-380-05-21-50-210-803

T005REAM

JOB CA	JOB CARD STEPS							
Order	Description	Job Step Action	Sign	Certify	Status			
1	NOTE This is an EWIS (Electrical Wiring Interconnection System) procedure. EWIS is specified in ESPM 20-33-11.							
2	3. Job Set-upSubtask 05-21-50-010-003-A - Effectivity: [001-999] A. Get Access (1) Get access to the Lower Deck (LD) aft cargo-compartment Ref. AMM Task 50-10-00-010-802-A. (2) Refer to chapter 25 to know which equipment/furnishings you must remove to get access to the work area. Then remove these items. (3) If installed, remove the LD Cabin Crew Rest Compartment (CCRC) Ref. AMM Task 25-53-42-000-801-A. (4) Remove the applicable sidewall panels from FR56 to FR86/87 Ref. AMM Task 50-14-00-000-801-A.							
3	4. Procedure Subtask 05-21-50-210-003-A - Effectivity: [001-999] A. Inspection Inspection Area of the Lower-Deck Aft Cargo-Compartment Effectivity: [001-999] (1) Do a general visual inspection of the aft cargo compartment behind the sidewall panels (zones 151 and 152) with the FLASHLIGHT, ESPM 2033110. (2) Make sure that there are no signs of damage, corrosion, leaks, cracks or rub marks on the structure, the systems and the equipment that you can see. (3) Make sure that all the installations (wiring, ducting and piping) are correctly attached.							
4	 Close-upSubtask 05-21-50-410-003-A - Effectivity: [001-999] A. Close Access Make sure that the work area is clean and clear of tools and other items. Install the applicable sidewall panels from FR56 to FR86/87 Ref. AMM Task 50-14-00-400-801-A. Refer to chapter 25 for installation instructions for the equipment/ furnishings that you removed during the removal procedure. Then install these items. If removed, install the LD CCRC Ref. AMM Task 25-53-42-400-801-A. Close the access to the LD aft cargo-compartment Ref. AMM Task 50-10-00-410-802-A. Remove all the fixtures, tools, test and support equipment used during this procedure. 							

PART REG	PART REQUIREMENTS		NOT FOR HARD COPY ACTION		
Qty	Part Number	Part Grp / Config Slot	Part Note		

PARTS TO BE REMOVED			NOT FOR HARD COPY ACTION				
Qty	Part Grp/Config Slot	Position	Part No	Serial No/ Batch No	Reason	Action	

Generated By: Date Printed: 22-Dec-2022 18:02 Page: 2 of 5



ENGINEERING AND MAINTENANCE Revision # : 23

J-380-05-21-50-210-803 (GENERAL VISUAL INSPECTION OF THE LOWER DECK AFT CARGO COMPARTMENT. (EWIS))

Workscope # : 40

J-380-05-21-50-210-803

T005REAM

PARTS TO BE INSTALLED NOT FOR HARD COPY ACTION									
Qty	Part Grp/Config Slot Position Part No Serial No/ Batch No						Action		
MEASUREMENTS									
	Parameter Inventory Value							Unit	
TOOLS						NOT FOR HAR	D CO	PY ACTION	
	Part No Description Serial Number							Action	
PANELS NOT FOR HARD COPY ACTION									
Panel		Zone		Labour	Mair	ntenance Tasks		Status	

23



J-380-05-21-50-210-803 (GENERAL VISUAL INSPECTION OF THE LOWER DECK AFT CARGO COMPARTMENT. (EWIS))

Workscope # : 40

Revision #

J-380-05-21-50-210-803

TOOSPEAM	

HARDCOPY ACTION					
ACTION TAKEN / PROGRESSIVE CERTIFICATION	SIGN Staff No / Date	CERTIFY Auth No / Date			
	_				

ENGINEERING AND MAINTENANCE Revision # : 23

J-380-05-21-50-210-803 (GENERAL VISUAL INSPECTION OF THE LOWER DECK AFT CARGO COMPARTMENT. (EWIS))

Workscope # : 40

J-380-05-21-50-210-803

J-360-00						
PARTS REI	MOVED					
Qty	Position	Part No.		Seria	al/ Batch No.	Reason
PARTS INS	TALLED					
Qty	Position	Part No.		Seria	al/ Batch No.	RCN
FUNCTIONAL CHECK SHEE NO.		ATTACH SHE			SUPPLEME	ENTARY CARDS RAISED
INDEPENDEN INSPECTION SHEET NO.	Т					
	FINAL CERTIFICATIO N/A If task deferred	N	TASK DEFERRAL - REF:REASON:			
SIG: Cert No.: DATE:			SIG: DATE:			

CARD CLEARANCE
THE PERSON SIGNING THIS WILL BE RESPONSIBLE TO ENSURE
THAT ALL WORK ON THIS CARD HAS BEEN ACTIONED AND

CERTIFIED CORRECTLY

SIGNATURE:
DATE

Generated By: Date Printed: 22-Dec-2022 18:02 Page: 5 of 5



Revision #

Workscope # 313

23

J-380-21-52-00-220-801-521 (PACKS (AIR GENERATION UNITS -AGU)- DETAILED INSPECTION OF LH WING AIR GENERATION UNIT WATER INJECTOR NOZZLE FOR EROSION.)

J-380-21-52-00-220-801-521

T00B14QY

Location

Rego or Serial No A/C Type or Part No Work Package VH-OQI 380 VH-OQI 12YR + GEARS 04FEB23 AUH **QFXXXX TRU03**

AUH/BASE

Parent Assembly : AIRBUS A380-840 - VH-OQI Issue to account

: J388028 (OQI CHECK 12.1 OFSHORE

MAINT CHECK)

Inventory : 21-52 - PACKS (AIR GENERATION UNITS - Block

: 3YR (3YR-CHECK *** PLANNING ALERT

*** (REFER DESCRIPTION))

AGU) : 21-52

Parent Req

: R-380-215200-00002-01-A (PACKS (AIR GENERATION UNITS - AGU)- DETAILED INSPECTION OF AIR GENERATION

UNIT WATER INJECTOR NOZZLE FOR

EROSION.)

Zones

: 520

Repetitive Task for

: 191HL, 521CB, 521NB **Panels**

TASK DESCRIPTION/INSTRUCTION

INSPECTION - DETAILED Skills/Labour: 1 X MECH Type - Subtype

VISUAL INSPECTION

Task Priority:

Description:

Config Position

Instructions : Accomplish A380 AMM 21-52-00-220-801-A

TECHNICAL DATA					
Name	Description	Notes			
AMM 21.52.00.220.801.A PEV60					

Note: If Technical data has not been printed, navigate to the Task Information tab and select the magnifying glass in the Hyperlink column.

ACTIONS					NOT FOR HARD COP	Y ACTION
	SKILL	ROLE	USER	STAFF/AUTH No	ACTION	STEPS

Generated By: Date Printed: 22-Dec-2022 18:11 Page: 1 of 6



FNGINEERING AND MAINTENANCE Revision # : 23

J-380-21-52-00-220-801-521 (PACKS (AIR GENERATION UNITS - AGU)- DETAILED INSPECTION OF LH WING AIR GENERATION UNIT WATER INJECTOR NOZZLE FOR EROSION.)

Workscope # : 313

J-380-21-52-00-220-801-521

T00B14QY

JOB C	JOB CARD STEPS				
Order	Description	Job Step Action	Sign	Certify	Status
1	3. Job Set-upSubtask 21-52-00-860-007-A - Effectivity: [001-999] A. Aircraft Maintenance Configuration (1) Energize the aircraft electrical circuits Ref. AMM Task 24-41-00-861-801-A.				
2	<u>Subtask 21-52-00-010-002-A - Effectivity: [001-999]</u> B. Get Access (1) Remove the spray nozzle(s) Ref. AMM Task 21-53-54-000-801-A.				
3	4. Procedure Subtask 21-52-00-220-001-A - Effectivity: [001-999] A. Detailed Inspection				
	Water Injector Nozzle <u>Effectivity: [001-999]</u> NOTE It is permitted to use the water injector nozzle with black deposit marks.				
	 (1) Clean the component interfaces and the adjacent area. (2) Do a detailed inspection of the water injector nozzle for erosion: a. Measure the distance between the orifice surface and the pintle end. Make sure that the distance from the orifice surface to the pintle end is maximum 4.064 mm (0.1600 in.). b. If there is erosion, replace the water injector nozzle. 				
4	5. Close-upSubtask 21-52-00-410-002-A - Effectivity: [001-999] A. Close Access (1) Install the spray nozzle(s) Ref. AMM Task 21-53-54-400-801-A.				
5	Subtask 21-52-00-860-008-A - Effectivity: [001-999]B. Aircraft Maintenance Configuration (1) Put the aircraft back to its initial configuration (2) Make sure that the work area is clean and clear of tools and other items. (3) Remove the ground support and maintenance equipment, the special and standard tools and all other items. (4) De-energize the aircraft electrical circuits Ref. AMM Task 24-41-00-862-801-A.				

PART REQUIREMENTS NOT FOR HARD COPY AG				
Qty	Part Number	Part Grp / Config Slot	Part Note	
0	ROYCO GREASE 64	04-027 (DIESTER BASED GREASE WITH MOLYB. DISULF.(MIL-G-21164))		
0	19-003	19-003 (LINT-FREE COTTON CLOTH)		
0	LOTOXANE 20L	11-026 (SOLVENT GENERAL PURPOSE)		
0	BONDERITE M-CR 1201 AERO	13-002 (CHEMICAL CONVRSN COATING YELLOW ALUMINUM)		

Generated By: Date Printed: 22-Dec-2022 18:11 Page: 2 of 6

ENGINEERING AND MAINTENANCE Revision # : 23

J-380-21-52-00-220-801-521 (PACKS (AIR GENERATION UNITS - AGU)- DETAILED INSPECTION OF LH WING AIR GENERATION UNIT WATER INJECTOR NOZZLE FOR EROSION.)

Workscope # : 313

J-380-21-52-00-220-801-521

T00B14QY

PARTS TO BE REMOVED			NOT FOR HARD COPY ACTION				
Qty	Part Grp/Config Slot	Position	Part No	Serial No/ Batch No	Reason	Action	

PARTS TO BE INSTALLED				NOT FOR HARD	COPY ACTION
Qty	Part Grp/Config Slot	Position	Part No	Serial No/ Batch No	Action

MEASUREMENTS			
Parameter	Inventory	Value	Unit

TOOLS	NOT FOR HARD	COPY ACTION	
Part No	Description	Serial Number	Action
98L27801001000	98L27801001000 (LOCKING TOOL - FLAP/SLAT CONTROL LEVER)		

PANELS			NOT FOR HARD CO	PY ACTION
Panel	Zone	Labour	Maintenance Tasks	Status

Generated By: Date Printed: 22-Dec-2022 18:11 Page: 3 of 6

23



Revision #

Workscope # : 313

J-380-21-52-00-220-801-521 (PACKS (AIR GENERATION UNITS -AGU)- DETAILED INSPECTION OF LH WING AIR GENERATION UNIT WATER INJECTOR NOZZLE FOR EROSION.)

J-380-21-52-00-220-801-521

T00B14QY

RDCOPY ACTION				
ACTION TAKEN / PROGRESSIVE CERTIFICATION	SIGN Staff No / Date	CERTIFY Auth No / Date		
_				

23

: 313

ENGINEERING AND MAINTENANCE

Revision #

Workscope #


J-380-21-52-00-220-801-521 (PACKS (AIR GENERATION UNITS -AGU)- DETAILED INSPECTION OF LH WING AIR GENERATION UNIT WATER INJECTOR NOZZLE FOR EROSION.)

J-380-21-52-00-220-801-521

TOOP14OV				

PARTS REI	PARTS REMOVED							
Qty	Position	Part No.		Seri	al/ Batch No.	Reason		
PARTS INS	PARTS INSTALLED							
Qty	Position	Part No.		Seri	al/ Batch No.	RCN		
FUNCTIONAL CHECK SHEET NO. INDEPENDENT INSPECTION SHEET NO.		ATTACH SHEET REGIS			SUPPLEMEN	NTARY CARDS RAISED		
FINAL CERTIFICATION				TASK DEFERRAL - REF:				
N/A If task deferred			REASON:					
	Cert No.: _		SIG: DATE:			E:		

Generated By: Date Printed: 22-Dec-2022 18:11 Page: 5 of 6





Revision # 23

J-380-21-52-00-220-801-521 (PACKS (AIR GENERATION UNITS -AGU)- DETAILED INSPECTION OF LH WING AIR GENERATION UNIT WATER INJECTOR NOZZLE FOR EROSION.)

Workscope # 313

J-380-21-52-00-220-801-521



CARD CLEARANCE THE PERSON SIGNING THIS WILL BE RESPONSIBLE TO ENSURE THAT ALL WORK ON THIS CARD HAS BEEN ACTIONED AND **CERTIFIED CORRECTLY**

SIGNATURE:	
DATE	

Generated By: Date Printed: 22-Dec-2022 18:11 Page: 6 of 6



*** TSR ** * RTL 810 REF RTL 784 - SEAT 3K O/R CABLE ASSY PNR 3AAL0289501 AND SIDE SPREADER PNR 3AAM0094502 NIL STOCK Workscope #

Revision #

2

N/A

LA....



VH-OQI



Rego or Serial No A/C Type or Part No

Work Package

Location

380

VH-OQI 12YR + GEARS 04FEB23 AUH **QFXXXX TRU03**

AUH/BASE

Parent Assembly : AIRBUS A380-840 - VH-OQI Issue to account : J388028 (OQI CHECK 12.1 OFSHORE

MAINT CHECK)

Config Position

Inventory

: 25-21 - PASSENGER COMPARTMENT SEAT Block

Parent Req

: 25-21 (1.1)

Repetitive Task for

Zones

Panels

TASK DESCRIPTION/INSTRUCTION

Skills/Labour: 1 X CABIN

Type - Subtype : CORRECTIVE ACTION -

Task Priority:

Description:

Instructions : nil

TECHNICAL DATA

Name Description **Notes**

Note: If Technical data has not been printed, navigate to the Task Information tab and select the magnifying glass in the Hyperlink column.

FAULT INFORMATION

Found During Task : QFA0093

Raised By **Failed System** Anishkar Chaudhary 25-21 - PASSENGER COMPARTMENT

SEAT

Fault Source : TECMAINT Logbook Ref TOQI23OCT19810

Fault Description Anishkar Chaudhary, 23-OCT-2019 21:41 UTC

REF RTL 784 - SEAT 3K O/R CABLE ASSY PNR 3AAL0289501 AND SIDE SPREADER PNR

3AAM0094502 NIL STOCK LAX, HOWEVER SEAT 3K ELECT OPS CHK SATIS.

Reported By: A CHAUDHARY

Staff No: 955126

MEASUREMENTS REQUIRED

Generated By: Date Printed: 22-Dec-2022 18:00 Page: 1 of 5



Revision # : N/A

*** TSR ** * RTL 810 REF RTL 784 - SEAT 3K O/R CABLE ASSY PNR 3AAL0289501 AND SIDE SPREADER PNR 3AAM0094502 NIL STOCK Workscope # : 2

LA.....

NON-ROUTINE



ACTIONS	ACTIONS NOT FOR HARD COPY A							
SKILL	ROLE	USER	STAFF/AUTH No	ACTION	STEPS			
LOG	Log	Chaudhary, Anishkar	955126	Action 1. Chaudhary, Anishkar,23-Oct-2019 21:41 PNR 3AAM0094502 AND PNR 3AAL0289501 NIL STOCK LAX. TO HOLD. Authorisation Number: QE599369				
CABIN	Tech	Baylor, Daniel	256843	Action 2. Baylor, Daniel,18-Dec-2019 05:07 O/R CABLE ASSY REPLACED IAW CMM 25-24-49 (SEAT PAN)	1			
CABIN	Cert	Burns, Bruce	QE408442	Action. Certified				

JOB CA	JOB CARD STEPS								
Order	Description	Job Step Action	Sign	Certify	Status				
1	REPLACE O/R CABLE ASSY PNR 3AAL0289501		Daniel Baylor	Bruce Burns	COMPLETE				
2	REPLACE SIDE SPREADER PNR 3AAM0094502								

PART RE	QUIREMENTS	NOT FOR HARD COPY ACTION	
Qty	Part Number	Part Grp / Config Slot	Part Note
_	0.4.41.0000.504	3AAL0289501 (OVERRIDE CABLE ASSEMBLY,	IN STOCK SYD, DRS 29JUN20
1	3AAL0289501	SEAT PAN)	05FEB20 STK@SDC/LAX
			STILL NIL STOCK 29JUN20 - NONE ON ORDER - NO EDD
1	3AAM0094502		STILL NIL STOCK 27MAY20 - 1 ON ORDER - NO EDD
		3AAM0094502 (PLATE ASSEMBLY, SIDE SPREADER (LH))	NIL STOCK 20NOV19 - x1 ON ORDER
			NIC 25OCT19 - CMM 25-24-49 BE AEROSPACE FIG 10, ITEM 405 - email sent to SHR Matplan.

PARTS	TO BE REMOVED			NOT FOR	HARD COPY	ACTION
Qty	Part Grp/Config Slot	Position	Part No	Serial No/ Batch No	Reason	Action

Generated By: Date Printed: 22-Dec-2022 18:00 Page: 2 of 5

: N/A Revision #

*** TSR ** * RTL 810 REF RTL 784 - SEAT 3K O/R CABLE ASSY PNR 3AAL0289501 AND SIDE SPREADER PNR 3AAM0094502 NIL STOCK Workscope # : 2

LA.....

NON-ROUTINE

T00GFB8T

PARTS T	O BE INSTALLED	NOT FOR HARD COPY ACTION			
Qty	Part Grp/Config Slot	Position	Part No	Serial No/ Batch No	Action
1	3AAL0289501 (OVERRIDE CABLE ASSEMBLY, SEAT PAN)		3AAL0289501	191640246	Action 2
1	3AAM0094502 (PLATE ASSEMBLY, SIDE SPREADER (LH))		3AAM0094502		

MEASUREMENTS							
Parameter	Inventory	Value	Unit				
Select Failure Category ()	25-21 - PASSENGER COMPARTMENT SEAT	COMPNT					

TOOLS		NOT FOR HARD	COPY ACTION
Part No	Description	Serial Number	Action

PANELS NOT FOR HARD COPY				
Panel	Zone	Labour	Maintenance Tasks	Status

Generated By: Date Printed: 22-Dec-2022 18:00 Page: 3 of 5

Revision #

: N/A

*** TSR ** * RTL 810 REF RTL 784 - SEAT 3K O/R CABLE ASSY PNR 3AAL0289501 AND SIDE SPREADER PNR 3AAM0094502 NIL STOCK LA.....

Workscope # : 2

NON-ROUTINE

T00GFB8T

	HARDCOPY ACTION					
SIGN Staff No / Date	CERTIFY Auth No / Date					
\dashv						
\dashv						
_						
_						
\dashv						
_						
_						
_						
_						
\dashv						
\dashv						
_						
_						
	SIGN Staff No / Date					

Revision #

: N/A

*** TSR ** * RTL 810 REF RTL 784 - SEAT 3K O/R CABLE ASSY PNR 3AAL0289501 AND SIDE SPREADER PNR 3AAM0094502 NIL STOCK

Workscope # : 2

LA.....

NO	N-	RC	11	TI	N	F
	1 4 -		J		14	_

TOOCEDOT						

						T00GFB8T		
PARTS REMOVED								
Qty	Position	Part No.		Serial/ Batch No.		Reason		
PARTS INSTALLED								
Qty	Position	Part No.		Serial/ Batch No.		RCN		
FUNCTIONAL CHECK SHEE NO. INDEPENDEN' INSPECTION SHEET NO.		ATTACH SHE		l l	SUPPLEMENTARY CARDS RAISED			
FINAL CERTIFICATION N/A If task deferred				TASK DEFERRAL - REF: REASON:				
SIG: Cert No.: DATE:				SIG: DATE:				

CARD CLEARANCE THE PERSON SIGNING THIS WILL BE RESPONSIBLE TO ENSURE THAT ALL WORK ON THIS CARD HAS BEEN ACTIONED AND CERTIFIED CORRECTLY

SIGNATURE:

Generated By: Date Printed: 22-Dec-2022 18:00 Page: 5 of 5