

Aircraft Type:





Effective Code:

Page: 1 / 9

#### \*\*\*USE THE REGION BELOW FOR HARDCOPY CERTIFICATION (NOT e-SIGN)\*\*\*

#### **WORK PACKAGE INFORMATION:**

#### HM-WP CC-CXK AUG2022 [1C+2C+4C+8C+S1+S2+S4+S8+AWL] [EO]

Serial N°:

11 -							
	B767F - C0	C-CXK		37802	021		
	Work Loca	ation:		Organization:	Start Date:		
	AUH/ADAT	HGR		CMA DGAC N° 593	8/8/22 4:00 AM		
	Work Orde	er N°		Flight Hours:	Flight Cyc	cles:	
	WO - 1407	55053					
				TASK LIST:			
Line N°	Barcode:	Status:		Task Name:		OBS	Signature
1	T00KCP2K	ACTV		AD-B767-27-A0016 (JIC) (FLIGHT CONTROLS / RUDDER AND ELEVATOR CONTROL SYSTEM / FREEPLAY INSPECTION)			
2	T00LFQRF	ACTV		AD-B767-27-A0235 PART 1 (JIC) (FLIGHT CONTROLS - Horizontal Stabilizer - Actuator Maintenance Changes)			
3	T00LXC7S	ACTV		AD-B767-27-A0235 PART 2 (JIC) (FLIGHT CONTROLS - Horizontal Stabilizer - Actuator Maintenance Changes)			
4	T00KG6H3	ACTV	AD-E Altim	3767-34-A2383 PART2 (LAN) (JIC) (NAVIGATION - Air Data System - etry System Test)			
5	T00KH45Z	ACTV		D-B767-34-A2383 PART2 (LAN) (JIC) (NAVIGATION - Air Data System - cimetry System Test)			
6	T00MBH14	ACTV		AD-B767-34-A2383 PART3 (JIC) (NAVIGATION - Air Data System - Altimetry System Test)			
7	T00KDP01	ACTV	AD-E	-B767-34-A7627 PART 1 (JIC) (ATC TRANSPONDER SYSTEM TEST)			



CC-CXK

# \*\*\*USE THE REGION BELOW FOR HARDCOPY CERTIFICATION (NOT e-SIGN)\*\*\*

	· · · · · · · · ·		T		
8	T00KDP08	ACTV	AD-B767-34-A7627 PART 1 (JIC) (ATC TRANSPONDER SYSTEM TEST)	INSP	
9	T00MXGGK	ACTV	AD-B767-51-A0061 PART 1 (JIC) (STRUCTURES / AIRFRAME DRAINAGE / CANTED PRESSURE DECK DRAIN INSPECTION AND CLEANING)	INSP	
10	T00KD4K0	ACTV	AD-B767-51-A0061 PART 2 (JIC) (STRUCTURES / AIRFRAME DRAINAGE / CANTED PRESSURE DECK DRAIN INSPECTION AND CLEANING)	INSP	
11	T00F2P4K	ACTV	AD-B767-51-A0061 PART 3 (JIC) (STRUCTURES / AIRFRAME DRAINAGE / CANTED PRESSURE DECK DRAIN INSPECTION AND CLEANING)	INSP	
12	T00MSKXD	ACTV	AD-B767-78-A0006 PART 1 (JIC) (ENGINE 1 - THRUST REVERSER CONTROL SYSTEM - OPERATIONAL TEST (CF6-80C2 ENGINES))	INSP	
13	T00KGGD2	ACTV	AD-B767-78-A0012 (JIC) (EXHAUST (CF6-80C2 ENGINES) - THRUST REVERSER CONTROL SYSTEM - DIRECTIONAL PILOT VALVE - LEAK CHECK)	INSP	
14	T00KGGCW	ACTV	AD-B767-78-A0012 (JIC) (EXHAUST (CF6-80C2 ENGINES) - THRUST REVERSER CONTROL SYSTEM - DIRECTIONAL PILOT VALVE - LEAK CHECK)	INSP	
15	T00LFLY9	ACTV	AD-B767-78-A0018 (ENG1)(JIC) (EXHAUST (CF6-80C2 Engines) - Thrust Reverser - Thrust Reverser Control System - Center Drive Unit (CDU) Cone Brake Integrity Test)	INSP	
16	T00LFLYN	ACTV	AD-B767-78-A0018 (ENG2)(JIC) (EXHAUST (CF6-80C2 Engines) - Thrust Reverser - Thrust Reverser Control System - Center Drive Unit (CDU) Cone Brake Integrity Test)	INSP	
17	T00N0TB7	ACTV	AD-CF6-80C2-72-B0991 (JIC) (FUEL MANIFOLD AND DRAINS HMU/MEC IDLER ADAPTER INSPECTION)	Me INSP	
18	T00JU8FA	ACTV	CABIN-B767-CHECK-A1386 (JIC) (WASTE TROLLEY - BRAKE INSPECTION)		
19	T00MREKH	ACTV	IH-53-4067-00(JIC-LA) (FUSELAGE - CARGO LOADER - ALIGNMENT TAPE INSTALLATION)	INSP	

Printed Date: 28-Jul-2022



CC-CXK

## \*\*\*USE THE REGION BELOW FOR HARDCOPY CERTIFICATION (NOT e-SIGN)\*\*\*

20	T00MREKG	ACTV	IH-53-4067-00(JIC-MODIFICATION) (FUSELAGE - CARGO LOADER - ALIGNMENT TAPE INSTALLATION)	INSP
21	T00KBLDH	ACTV	IH-B767-21-A1504 (JIC-INST). (BOFRIP - Check of the Cooling Packs)	
22	T00MULF9	ACTV	IH-B767-21-A1738 PART 2 (JIC) (BOFRIP - System Test - Cooling Pack System)	
23	T00MULF7	ACTV	IH-B767-21-A1740 PART 2 (JIC) (BOFRIP - Operational Test - Pack Low Limit Valve)	
24	T00KEL7Z	ACTV	IH-B767-21-A1741 (JIC-INST) (BOFRIP - Clean the Components)	INSP
25	T00KGSVM	ACTV	IH-B767-22-A3097 (REQ) (GROUND TEST 40 (AUTOFLIGHT))	
26	T00N0RXJ	ACTV	IH-B767-23-B6252 (JIC) (SDU REMOVAL/INSTALLATION FOR ELECTRONIC LRU CLEANING)	
27	T00GUS48	ACTV	IH-B767-27-B1161 PART 1 (LH)(JIC) (FLIGHT CONTROLS - Leading Edge Slat System - Rotary Actuator Assembly, Offset Gearbox and Quill Shaft Inspection)  INSF	
28	T00GUS4U	ACTV	IH-B767-27-B1161 PART 3 (RH)(JIC) (FLIGHT CONTROLS - Leading Edge Slat System - Rotary Actuator Assembly, Offset Gearbox and Quill Shaft Inspection)	INSP
29	T00L38AY	ACTV	IH-B767-27-B5760 (JIC) (FLAP/SLAT ADJUSTMENT)	
30	T00L33M3	ACTV	IH-B767-28-B5758 (JIC) (BOOSTER FUEL PUMPS INSULATION RESISTANCE TEST)	
31	T00L57K9	ACTV	IH-B767-28-B5786 (JIC) (FUEL FEED SYSTEM - PRESSURE SENSE LINES CHECK)	





# \*\*\*USE THE REGION BELOW FOR HARDCOPY CERTIFICATION (NOT e-SIGN)\*\*\*

32	T00L5S5B	ACTV	IH-B767-28-B5839 (JIC) (FUEL QUANTITY INDICATING SYSTEM - FQIS SYSTEM - TEST)	INSP
33	T00MJM70	ACTV	IH-B767-28-B6985 (JIC) (FUEL FEED SYSTEM - PRESSURE SENSE LINES CHECK - BOOST PUMPS)	
34	T00N1PR8	ACTV	IH-B767-28-B7453 (JIC) (OVERRIDE AND JETTISON PUMPS - insulation resistance test)	INSP
35	T00L3N0M	ACTV	IH-B767-29-B5756 (JIC) (HYDRAULIC SYSTEM LINE AND COMPONENTS FILTERS INSPECTION)	
36	T00KF0EW	ACTV	IH-B767-30-A7949 PART 1 (JIC) (ICE AND RAIN PROTECTION - Flight Compartment Window Anti-Icing - Windshield Inspection)	
37	T00KF60E	ACTV	IH-B767-30-A7949 PART 2 (JIC) (ICE AND RAIN PROTECTION - Flight Compartment Window Anti-Icing - Windshield Inspection)	
38	T00L33SV	ACTV	IH-B767-32-B4054 (JIC) (PITOT STATIC PROBE ANTI-ICING _ HEAVY MAINTENANCE INSPECTION)	INSP
39	T00KH1D9	ACTV	IH-B767-33-A2669 (JIC-INSTRUCTIONS) (BOFRIP - Emergency Lights - Operational Test of the Lights Connected to the Exit Doors and Hatches)	
40	T00KH1DD	ACTV	IH-B767-33-A2670 (JIC-INSTRUCTIONS) (BOFRIP - Emergency Lights - Operational Test of the Lights Connected to the Hydraulic Motor-Driven Generator)	
41	T00KH1D6	ACTV	IH-B767-33-A2671 (JIC-INSTRUCTIONS) (BOFRIP - Emergency Lights - Functional Test)	
42	T00KGZ72	ACTV	IH-B767-33-A2672 (JIC-INSTRUCTIONS) (BOFRIP - Battery Pack - Charge the Batteries)	
43	T00MRBAY	ACTV	IH-B767-34-A2427 (JIC) (BOFRIP - Operational Test - TCAS)	
	·	·		·



CC-CXK
Page: 5 / 9

# \*\*\*USE THE REGION BELOW FOR HARDCOPY CERTIFICATION (NOT e-SIGN)\*\*\*

44	T00MPSNJ	ACTV	IH-B767-34-B0297 (JIC) (BOFRIP - Operational Test of IRS)	
45	T00MYTZS	ACTV	IH-B767-38-B7440(JIC) (LAVATORY POTABLE WATER SYSTEM- BASIC SWITCH & SWITCH ACTUATOR INSPECTION)	
46	T00LCTTH	ACTV	IH-B767-49-B2196 (JIC) (GTCP331-200 - HEALTH CHECK)	INSP
47	T00KFT6B	ACTV	IH-B767-53-A1706 (REQ) (PREVENTIVE ACTIONS TO AVOID CORROSION BETWEEN WING CENTER SECTION (WCS) REAR SPAR WEB AND REAR SPAR BULKHEAD FITTINGS)	INSP
48	T00KDNKX	ACTV	IH-B767-56-B0009 PART 1 (JIC) (Flight compartment windows, inspection left No. 1 windows (Windshields))	INSP
49	T00KDNQJ	ACTV	IH-B767-56-B0009 PART 2 (JIC) (Flight compartment windows, inspection right No. 1 windows (Windshields))	INSP
50	T00MNADN	ACTV	IH-B767-57-A0891 PART 3 (JIC) (WINGS - LEADING EDGE AND LEADING EDGE DEVICES - SLAT TRACK HOUSING DRAIN LINE REPLACEMENT)	INSP
51	T00MNADT	ACTV	IH-B767-57-A0891 PART 4 (JIC) (WINGS - LEADING EDGE AND LEADING EDGE DEVICES - SLAT TRACK HOUSING DRAIN LINE REPLACEMENT)	INSP
52	T00KGECX	ACTV	IH-B767-70-A8926-CHECK-C(JIC) (RUN UP CHECKLIST B767)	INSP
53	T00LR0V6	ACTV	IH-B767-78-B4154 PART 1 LH ENG (JIC) (THRUST REVERSER _ RELIABILITY FULL T/R SYSTEM RIGGING AND LUBRICATION)	
54	T00LR14M	ACTV	IH-B767-78-B4154 PART 2 RH ENG (JIC) (THRUST REVERSER _ RELIABILITY FULL T/R SYSTEM RIGGING AND LUBRICATION)	
55	T00KDT64	ACTV	IH-CF6-80C2-73-A3800 (JIC) (PS3 MANIFOLD P-CLAMPS INSPECTION)	INSP



CC-CXK

# \*\*\*USE THE REGION BELOW FOR HARDCOPY CERTIFICATION (NOT e-SIGN)\*\*\*

56	T00KJGS0	ACTV	IH-CF6-80C2-73-A3800 (JIC) (PS3 MANIFOLD P-CLAMPS INSPECTION)	INSP	
57	T00MS3T9	ACTV	IH-CF6-80C2-73-A5876 (JIC) (ECU CABLE - INSPECTIONS AND CLEANING ELECTRICAL CONNECTORS OF START VALVE)		
58	T00MS98Q	ACTV	IH-CF6-80C2-73-A5876 (JIC) (ECU CABLE - INSPECTIONS AND CLEANING ELECTRICAL CONNECTORS OF START VALVE)		
59	T00KCEXC	ACTV	MD-B767-11-A4905(JIC-MODIFICATION) (EMERGENCY RESCUE ACCESS DEMARCATION)		
60	T00KDNP5	ACTV	MD-B767-27-B3288 (JIC) (STABILIZER/RUDDER - HYDRAULIC SYSTEM - INSPECTION)		
61	T00MRBJ9	ACTV	MD-B767-27-B4333 (JIC) (FLIGHT CONTROLS - Horizontal Stabilizer - Drain Holes, Limit Switch and Position Transmitter Modules Inspection, and Repair)		
62	T00F5W17	ACTV	RP-56-1021(JIC-INSPECTION) (INSPECTION AT PASSENGER CABIN WINDOWS OUTER PANE)	ASSENGER CABIN INSP	
63	T00KRP33	ACTV	RP-B767-57-B5102(REQ) (PERMANENT REPAIR FOR CORROSION ON RH WING SPOILER SUPPORT BEAM UPPER FLANGE)		
64	T00KB0SK	ACTV	SI-57-0148 (REQ) (INSPECTION OF LH WING LOWER SURFACE SIDE LOAD FITTING INB FWD ZONE WITH SHIM MIGRATED)		
65	T00KB0D0	ACTV	SI-B767-53-B1257 (REQ) (INSPECTION OF HORIZONTAL STABILIZER PIVOT FITTING AT STA. 1809.5 LH SIDE LOWER ZONE WITH SHIM MIGRATED.)		
66	T00KCXG3	ACTV	SI-B767-57-A7517 (REQ) (INSPECTION OF SHIM MIGRATED AT ENG#2 NACELLE STRUT DIAGONAL BRACE INBRD FITTING)		
67	T00KDJ0C	ACTV	SL-52-0127-00(JIC) (CARGO DOOR LATCH/HOOK ACTUATOR- SHAFT SPLINES AND SPHERICAL GEAR TEETH - LUBRICATION)	INSP	



CC-CXK

# \*\*\*USE THE REGION BELOW FOR HARDCOPY CERTIFICATION (NOT e-SIGN)\*\*\*

68	T00N20CZ	ACTV	OPEN-B767 ZONA400 (Master Panel Card B767 ZONA 400)		
69	T00N20D0	ACTV	CLOSE-B767 ZONA400 (Master Panel Card B767 ZONA 400)		
70	T00N20D2	ACTV	OPEN-B767 ZONA500 (Master Panel Card B767 ZONA 500)		
71	T00N20D3	ACTV	CLOSE-B767 ZONA500 (Master Panel Card B767 ZONA 500)		
72	T00N20D4	ACTV	OPEN-B767 ZONA300 (Master Panel Card B767 ZONA 300)		
73	T00N20D5	ACTV	CLOSE-B767 ZONA300 (Master Panel Card B767 ZONA 300)		
74	T00N20D6	ACTV	OPEN-B767 ZONA100 (Master Panel Card B767 ZONA 100)		
75	T00N20D7	ACTV	CLOSE-B767 ZONA100 (Master Panel Card B767 ZONA 100)		
76	T00N4REE	ACTV	IH-B767-05-A7657-INSP(JIC) (REGISTER ALL FORMS 337 GENERATED DURING C CHECK)	INSP	
77	T00N4RJZ	ACTV	IH-B767-22-B1234(REQ) (CAT II/III AUTHORIZATION NEXT TO EXPIRE)		
78	T00N4KKD	ACTV	IH-B767-00-B3575(REQ) (TAKE A PHOTOGRAPHY OF APU START AND AUTOLAND SUMMARY SHEET)  Me		
79	T00N2ESH	ACTV	AASR-B767-54-B5253(REQ) (REPETITIVE INSPECTION OF ENG #2 EXHAUST AFT RING 14" BETWEEN 12 TO 01 HRS WITH INTERIM REPAIR)		

Printed Date: 28-Jul-2022



CC-CXK

### \*\*\*USE THE REGION BELOW FOR HARDCOPY CERTIFICATION (NOT e-SIGN)\*\*\*

80	T00N4ZB4	ACTV	AD-B767-28-B4558 PART 2 (JIC) (Fuel - Center Fuel Tank FQIS wire separation for airplanes that have not equipped with a Flammability Reductions Means (FMR))		
81	T00N50NK	ACTV	IH-B767-25-B5769 (JIC) (767-300BCF - EMERGENCY EQUIPMENT INSPECTION)	INSP	
82	T00N50DD	ACTV	IH-B767-78-B2904 PART 1 (JIC) (FAN REVERSER ACTUATION SYSTEM ANTIFREEZE ADITION)	Me INSP	
83	T00N50NZ	ACTV	IH-B767-78-B2904 PART 2 (JIC) (FAN REVERSER ACTUATION SYSTEM ANTIFREEZE ADITION)	Me INSP	
84	T00N50NU	ACTV	IH-B767-78-B2904 PART 3 (JIC) (FAN REVERSER ACTUATION SYSTEM ANTIFREEZE ADITION)	/STEM Me INSP	
85	T00N50PJ	ACTV	IH-B767-78-B2904 PART 4 (JIC) (FAN REVERSER ACTUATION SYSTEM ANTIFREEZE ADITION)	Me INSP	
86	T00N6UE8	ACTV	SI-A320FAM-57-B5057(REQ) (REPETITIVE INSPECTION FOR TEMPORARY REPAIR DUE A CORROSION ON RH WING SPOILER SUPPORT BEAM UPPER FLANGE)		
87	T00N513W	ACTV	AD-B767-27-A0011(JIC) (FLIGHT CONTROLS - Elevator - Repetitive Mis-Rig Check)	INSP	

Release Remarks								

SIGNATURE							
The signer below certifies that the Work Package has been completed.							
Skill	Skill Signed by Signature						

Ne - Task that cannot be electronic signed

Me - Task that requires recording measurements, tolerence or values

NA - Task that has a step N/A added by

INSP - Task considered RII



CC-CXK

\*\*\*USE THE REGION BELOW FOR HARDCOPY CERTIFICATION (NOT e-SIGN)\*\*\*