

Pole pairs number

 With the motor detached from the circuit, place a DC voltage roughly 5% of maximum across two motor leads.



 Manually turning the spindle, measure the number of detents found in one mechanical revolution. This is the number of pole pairs for the motor.



Do not leave the voltage applied for more than a minute or two since this can heat up the motor and may stress the voltage supply.





DC voltage source