Circuit	Matériau conducteur		$m = S_{ph}/S_{PE(N)}$			
		m = 1	m = 2	m = 3	m = 4	
3P + N  ou  P + N	cuivre	1	0,67	0,50	0,40	
	aluminium	0,62	$0,\!42$	0,31	$0,\!25$	

