

SOUTH CENTRAL RAILWAY

SC DIVISION - ALERT ADVICE No. 16/2025

No.sfy-12/SC/AA-16/2025

Date: 29.10.2025

Sub:Train operations during foggy & inclement weather - Precautions

Precautions and rules as mentioned in GR 3.61& 4.16 and SRs there under to be strictly followed during foggy/inclement weather for train operations by the concerned field staff. In this connection, following laid down instructions are once again reiterated for strict implementation;

1. Strengthening of Rail infrastructure before foggy weather:

- Ensure adequate availability of detonators at all stations for use during the fog.
- Lime marking to be ensured across the track near the signal warning Board (near the distant signal in double distant signal territory).
- All signal warning Boards, Whistle boards, W/L boards, Fog signal Posts and lifting barriers of vulnerable LC Gates are repainted to ensure proper visibility.
- Ensure that retro reflective strip in Sigma shape for identification of stop signal is provided as per the existing instructions.
- Provision of LED base flasher Red light in rear of SLR with a switch control to be used by the Guard when the train is held up in Automatic block territory in abnormal situations including during dense fog which is in addition to the flashing red tail lamp.
- VTO shall be prescribed in the SWRs of the stations.
- Fog Signal Posts are erected at 270m in rear of FSS in either direction to indicate the location for placing detonators by fog signalman. However, not necessary to place detonators on double distant signaling territory.

2. Precautions by Loco Pilot: The Loco Pilot shall take action in regard to speed of the train during fog in **Absolute block System & in Automatic block Territory** as under:-

- Fog safe devices provided to the Loco Pilots in all locomotives should be effectively used in these foggy weather periods.
- When the LP experiences dense fog and in his judgment feels that visibility is impaired/restricted, he shall control his train speed and be prepared to stop short of any obstruction. However, the speed shall not exceed,
 - A maximum of 75 KMPH in Absolute Block System.
 - A maximum of 75 KMPH in Automatic Block System while passing automatic stop signal at 'green', 30 KMPH when the signal is in 'double yellow' and further restricted speed when the signal is in 'yellow' so as to be prepared to stop at the next stop signal.


➤ In case fog safe device is not available in locomotives or the device fails en route, the maximum speed of 75 KMPH as indicated above shall be reduced to 60 KMPH or less subject to judgment of Loco pilot.

- Prevailing fog situation should be advised to Crew and train manager in lobby during 'sign ON'
- Loco pilot to whistle frequently to warn the gateman (where provided) and road users of an approaching train at level crossings.

3. Besides, the above laid down instructions, the following precautions to be followed during foggy weather.

- Check the locomotive head light, flasher light, wipers, sanders, speedometer, auto drain valve and cab heaters etc., are in working condition.
- Ensure window glasses are intact.
- Switch 'ON' head light during foggy weather.
- Depending on severity of fog, if necessary Loco Pilot should control the speed further.
- Shunting should not be carried out on non-isolated lines after granting line clear to a train.
- Train waiting for Authority to proceed shall not be drawn ahead and placed between Starter & Advanced Starter Signals, unless that portion is provided with Track Circuits or Axle Counters.(As per GR 5.18)
- Train Managers should ensure a flashing red tail lamp is kept in working condition even during day on the last vehicle. Train Manager to protect the train in rear when train is abnormally detained at Home signal due to delayed signal.
- Train manager shall show a stop hand signal towards the rear, when train has been stopped at an Automatic stop signal.
- If a Patrolman does not turn up within 15 minutes of his scheduled arrival, the Station Master on duty shall take the following action.
 - Stop run through trains proceeding into the block section, advise the Station Master at the other end of the block section to take similar action and also advise SCOR, the Gang mate and the PWI,
 - Issue a Caution Order of 40 KMPH to all trains proceeding into the block section advising the Loco Pilot to be on the alert.
 - The Caution Orders referred above shall be issued until Patrolman has arrived and reported that the line is safe for passage of trains.
- Educate the Trackmen regarding Cold Weather Patrolling and subsequent action to be taken in case of weld failures/rail fractures.
- Ensure the Gang and Patrolman is provided with full protection equipment.
- Patrolman/Keyman should be instructed to keep a watch for any rail/weld failure during their daily patrolling of track.
- Loco pilots to observe the availability lime marking/sigma boards during foggy weather and non availability of above to pass the remarks in CMS while signing OFF at lobby for further immediate attention.

Further, it should be ensured that the staff be advised and counselled regarding provisions in the G&SRs and above instructions before onset of fog without any deviation and compliance to be ensured. Each and every crew is to be imparted necessary training about the system of working of trains during fog.


 [ए. सुरेश]
 वरि. मंसंधि/सिकं
 [A. Suresh]
 Sr. DSO/SC

Copy:DRM/SC for kind information.

ADRM/O and ADRM/I for kind information.

All Branch Officers for information and necessary action.

All Field Supervisors for information and necessary action.

विषय: कोहरे और खराब मौसम के दौरान गाड़ी संचालन – सावधानियां.

गाड़ी संचालनों के दौरान कोहरे /खराब मौसम के दौरान सा.नि. 3.61 और 4.16 तथा उसके अंतर्गत स.नि. में उल्लिखित सावधानियों और नियमों का संबंधित फील्ड कर्मचारियों द्वारा कड़ाई से पालन किया जाए. इस संबंध में, नीचे दिए गए अनुदेशों का कड़ाई से पालन करने के लिए उन्हें पुनः दोहराया जाता है;

1. कोहरे के मौसम से पहले रेल अवसंरचना को मज़बूत करना:

- कोहरे के मौसम के दौरान उपयोग करने के लिए सभी स्टेशनों पर पटाखों की पर्याप्त उपलब्धता सुनिश्चित करना.
- सिगनल वार्निंग बोर्ड के पास (डबल डिस्टैंट सिगनल वाले क्षेत्र में डिस्टैंट सिगनल के पास) ट्रैक पर चूने की मार्किंग ज़रूर की जाए.
- सभी सिगनल चेतावनी बोर्ड, सीटी बोर्ड, W/L बोर्ड, कोहरा सिगनल पोस्ट और वल्लरेबल समपार फाटकों के लिफ्टिंग बैरियर को उचित दृश्यता के लिए दोबारा पेंट किया गया है.
- सुनिश्चित करें कि स्टॉप सिगनल की पहचान के लिए सिगमा आकार में रेड्रो रिफ्लेक्टिव पट्टी की व्यवस्था वर्तमान अनुदेशों के अनुसार की गयी है.
- गार्ड द्वारा कौंध लाल पिछली बत्ती के अतिरिक्त एसएलआर के पीछे एक स्विच कंट्रोल के साथ एलईडी बेस फ्लैशर लाल बत्ती का उपयोग तब किया जाएगा, जब घने कोहरे के दौरान सहित गाड़ी ऑटोमैटिक ब्लॉक क्षेत्र में असामान्य स्थितियों में फंसी होगी.
- स्टेशनों के स्टेशन संचालन नियमों में दृश्यता परीक्षा वस्तु निर्धारित की जाएगी.
- कोहरा सिगनलमैन द्वारा पटाखों को रखने के लिए स्थान सूचित करने हेतु दोनों दिशाओं में एफएसएस के पीछे 270 मी. पर कोहरा सिगनल खंभे स्थापित किए गए हैं. तथापि डबल डिस्टैंट सिगनल क्षेत्र में पटाखे रखने की आवश्यकता नहीं है.

2. लोको पायलट द्वारा पूर्वोपाय : पूर्ण ब्लॉक पद्धति और ऑटोमैटिक ब्लॉक क्षेत्र में कोहरे के दौरान गाड़ी की गति के संबंध में लोको पायलट नीचे बताए गए अनुसार कार्रवाई करेगा:-


- सभी लोकोमोटिवों में लोको पायलटों को दिए गए कोहरा संरक्षा उपकरणों का उपयोग इस कोहरे के मौसम की अवधि में प्रभावी रूप से किया जाना चाहिए.
 - जब लोको पायलट को घना कोहरा दिखे और उसे लगे कि दृश्यता कम हो गई है/प्रतिबंधित हुई है, तो वह अपनी गाड़ी की गति नियंत्रित करेगा और किसी भी रुकावट से पहले रुकने के लिए तैयार रहेगा. हालांकि, गति बढ़नी नहीं चाहिए.
 - पूर्ण ब्लॉक पद्धति में अधिकतम 75 कि.मी.प्र.घं. होगी.
 - ऑटोमैटिक ब्लॉक सिस्टम में 'हरा' सिगनल पर ऑटोमैटिक स्टॉप सिगनल पार करते समय अधिकतम 75 कि.मी.प्र.घं., जब सिगनल 'दोहरा पीला' हो तो 30 कि.मी.प्र.घं. और जब सिगनल 'पीला' हो तो और भी कम गति रखनी होगी ताकि अगले स्टॉप सिगनल पर रुकने के लिए तैयार रहा जा सके.
- लोकोमोटिव में कोहरा सुरक्षा उपकरण न होने या मार्ग में उपकरण की खराबी होने के मामले में, ऊपर बतायी गयी 75 कि.मी.प्र.घं. की अधिकतम गति को लोको पायलट के निर्णय के अनुसार 60कि.मी.प्र.घं. या उससे कम कर दिया जाएगा.
- लॉबी में 'साइन ऑन' के दौरान कर्मिंदल और गाड़ी प्रबंधक को मौजूदा कोहरे की स्थिति के बारे में सूचित किया जाना चाहिए.
 - लोको पायलट को समपार फाटकों पर आने वाली गाड़ी के बारे में फाटकवाला (जहां उपलब्ध हो) और सड़क उपयोक्ताओं को सचेत करने के लिए बार-बार सीटी बजानी होगी.

3. उपर्युक्त अनुदेशों के अतिरिक्त, कोहरे के मौसम के दौरान निम्नलिखित सावधानियां बरतनी चाहिए.

- लोकोमोटिव की हेड लाइट, फ्लैशर लाइट, वाइपर, सैंडर, स्पीडोमीटर, ऑटो ब्रेन वाल्व और कैब हीटर आदि की जांच करें कि वे काम करने की स्थिति में हैं या नहीं.
- सुनिश्चित करें कि खिड़कियों के शीशे सही सलामत हैं.

- कोहरे के मौसम के दौरान हेड लाइट का स्विच 'ऑन' करें.
- कोहरे की गंभीरता पर आधारित आवश्यकतानुसार लोको पायलट को गति को और कम करना चाहिए.
- गाड़ी के लिए लाइन क्लियर देने के बाद, नॉन-आइसोलेटेड लाइनों पर शंटिंग नहीं करनी चाहिए..
- प्रस्थान प्राधिकार की प्रतीक्षा करनेवाली गाड़ी को तब तक आगे खींचकर स्टार्टर और एडवांस्ड स्टार्टर सिगनल के बीच नहीं रखा जाएगा, जब तक कि उस हिस्से में ट्रैक सर्किट या एक्सल काउंटर न हों. (सा.नि. 5.18 के अनुसार)
- गाड़ी प्रबंधकों को सुनिश्चित करना चाहिए कि अंतिम वाहन पर दिन के दौरान भी कौंध लाल पिछली बत्ती को कार्य स्थिति में रखा जाता है. गाड़ी प्रबंधक को गाड़ी को पीछे से सुरक्षित रखना होगा जब सिगनल में देरी के कारण गाड़ी होम सिगनल पर असामान्य रूप से रुकी हो.
- जब कोई गाड़ी ऑटोमैटिक स्टॉप सिगनल पर रुकी हो, तो गाड़ी प्रबंधक पीछे की ओर स्टॉप हैंड सिगनल प्रदर्शित करेगा.
- यदि पेट्रोलमैन उसके निर्धारित आगमन के 15 मिनट के भीतर नहीं आता है, तो ड्यूटी स्टेशन मास्टर निम्नलिखित कार्रवाई करेगा.
 - ब्लॉक सेक्शन में से सीधी जानेवाली गाड़ियों को रोकेगा, ब्लॉक सेक्शन के दूसरे छोर पर वही कार्रवाई करने के लिए स्टेशन मास्टर को सूचित करेगा और सेक्शन नियंत्रक, गैंगमेट और रेलपथ निरीक्षक को भी सूचित करेगा.
 - सभी गाड़ियों के लिए 40 कि.मी.प्र.घं. का सतर्कता आदेश जारी करें जिसमें लोको पायलट को सतर्क रहने के लिए सूचित किया जाए.
- उपर्युक्त सतर्कता आदेश तब तक जारी रहेंगे जब तक पेट्रोलमैन आकर यह रिपोर्ट न दें कि लाइन गाड़ियों के गुजरने के लिए सुरक्षित है.
 - ट्रैकमेन को ठंडे मौसम में पेट्रोलिंग और वेल्ड फेल होने/रेल टूटने की स्थिति में की जाने वाली कार्रवाई के बारे में बताएं.
 - सुनिश्चित करें कि गैंग और पेट्रोलमैन को पूरे सुरक्षा उपकरण दिए जाते हैं.
 - पेट्रोलमैन/कीमैन को निर्देश दिया जाना चाहिए कि वे ट्रैक की प्रतिदिन पेट्रोलिंग के दौरान किसी भी रेल/वेल्ड खराबी पर नज़र रखें.
 - लोको पायलट को कोहरे वाले मौसम में लाइम मार्किंग/सिगमा बोर्ड की उपलब्धता देखनी होगी और अगर ये उपलब्ध नहीं हैं तो लॉबी में साइन ऑफ करते समय सीएमएस में रिमार्क्स लिखने होंगे ताकि उन पर तुरंत ध्यान दिया जा सके.

इसके अतिरिक्त, यह सुनिश्चित करना चाहिए कि कर्मचारियों को सा व स नि में दिए गए प्रावधान और ऊपर दिए गए निर्देशों के बारे में कर्मचारियों को कोहरा आरंभ होने से पहले बिना किसी बदलाव के सूचित किया जाए और परामर्श दिया जाना चाहिए और उनका पालन सुनिश्चित किया जाए. प्रत्येक कर्मिंदल को कोहरे के दौरान गाड़ियों के काम करने के सिस्टम के बारे में आवश्यक प्रशिक्षण दिया जाना चाहिए.


(ए. सुरेश)

वरि.मंसंधि/सिकं

प्रतिलिपि:- मरेप्र/सिकं को सूचनार्थ.

अमरेप्र/परिचालन और अमरेप्र/इन्फ्रा को सूचनार्थ.

सभी शाखा अधिकारियों को सूचना और आवश्यक कार्रवाई के लिए.

सभी फील्ड पर्यवेक्षकों को सूचना और आवश्यक कार्रवाई के लिए.