

दक्षिण मध्य रेलवे

सेफ्टी.387/फ्लाई लीफ/19/2025

फ्लाई लीफ सं. 19 / 2025

ध्यान दें..... लोको रनिंग कर्मचारी और परिचालन प्राधिकारी.....

शंटिंग

(साधारण व सहायक नियम का परिशिष्ट-XII, शब्दि पर्वी.22 दिनांक 22-09-2025, साधारण व सहायक नियम और दमरे दिनांक 21.10.2025 का संयुक्त कार्यविधि आदेश)

शंटिंग से तात्पर्य किसी वाहन या वाहनों को इंजन सहित या उसके बिना अथवा किसी इंजन वाले या किसी अन्य स्वचालित वाहन की आवाजाही से है जिसका उद्देश्य वाहन को जोड़ना, अलग करना या स्थानांतरित करना अथवा किसी अन्य उद्देश्य के लिए हो. ;(साधारण 1.02 (49))

1. शंटिंग अनुदेश वे अनुदेश होते हैं जो स्टेशन मास्टर लोको पायलट, शंटर, गार्ड, शंटिंग जमादार या इस काम के लिए चुने गए किसी भी पॉइंट्स मैन को शंटिंग के विवरण के बारे में बताते हैं. शंटिंग ऑपरेशन को फिक्स्ड सिग्नल या हथ सिग्नल या बोलकर दिए गए अनुदेशों से नियंत्रित किया जाएगा. (परिशिष्ट-XII)
2. प्रमुख स्टेशनों पर, जहां शंटिंग की निगरानी के लिए अलग-अलग कर्मचारी जैसे आउटडोर स्टेशन मास्टर / यार्ड एसएम / वाईएम / शंटिंग मास्टर / शंटिंग जमादार प्रदान किए जाते हैं, स्टेशन सेक्शन के भीतर फॉर्म संख्या टी / 806 देने की आवश्यकता नहीं है. ऐसे स्टेशनों को संबंधित वरिष्ठ मंडल परिचालन प्रबंधक द्वारा अधिसूचित किया जाएगा और स्टेशन संचालन नियम में सम्मिलित किया जाएगा. (परिशिष्ट-XII) (सहायक नियम 5.14.9)
3. स्टेशन सेक्शन में किए जाने वाले सभी शंट संचालन के विवरण के साथ फॉर्म टी/806 में शंटिंग आदेश जारी किया जाएगा और दोहरी लाइन में ब्लॉक फॉरवर्ड/ब्लॉक बैक और एकल लाइन में ब्लॉक बैक के दौरान शंटिंग करने के लिए भी आदेश दिया जाएगा. शंटिंग की देखरेख करने वाला गार्ड/योग्य रेलवे कर्मचारी गाड़ी के साथ रहेगा. अगर कोई समपार फाटक है, तो उसे बंद करना स्टेशन मास्टर और लोको पायलट को सुनिश्चित करना होगा. (परिशिष्ट-XII)
4. फॉर्म टी/806 में जारी शंटिंग आदेश को साइडिंग की लंबाई के बारे में अतिरिक्त जानकारी के साथ ठीक से भरा जाना चाहिए.(संयुक्त कार्यविधि आदेश)
5. एलपी / टीएमआर / शंटर और शंटिंग स्टाफ की यह ज़िम्मेदारी है कि वे शंटिंग आरंभ होने से पहले शंटिंग की प्रतिबंधों के बारे में जानकारी दें. (संयुक्त कार्यविधि आदेश)
6. जो व्यक्ति आरंभ में शंटिंग ऑपरेशन के लिए अनुदेश देता है, वह अनुदेश नहीं बदलेगा और पॉइंट वगैरह बदलने की इजाज़त नहीं देगा, जब तक कि वह खुद यह सुनिश्चित न कर ले कि शंटिंग ऑपरेशन पूरी तरह से बंद कर दिए गए हैं. (संयुक्त कार्यविधि आदेश)
7. शंटिंग कर्मचारी को उस स्टेशन, यार्ड या लाइन के लेआउट की जानकारी होनी चाहिए जहां वे काम कर रहे हैं. उन्हें डेड एंड तक लाइन की लंबाई स्पष्ट रूप से समझनी चाहिए, जिसे मीटर/कितने कोच या मालडिब्बे उसमें आ सकते हैं, के हिसाब से मापा जाता है.पुश-बैक शंटिंग आरंभ करने से पहले, लोको पायलट / शंटर / शंटिंग स्टाफ को इसमें शामिल वैगन या कोच की संख्या पता होनी चाहिए. (संयुक्त कार्यविधि आदेश)
8. स्टेशन मास्टर यह सुनिश्चित करेगा कि एक्सोल्यूट ब्लॉक प्रणाली में संबंधित ब्लॉक सेक्शन और स्वचालित ब्लॉक प्रणाली में दो ब्लॉक स्टेशनों के बीच की पूरी लाइन गाड़ियों से खाली हो. स्टेशन को ब्लॉक फॉरवर्ड या ब्लॉक बैक ऑपरेशन आरंभ करने से पहले दूसरी तरफ के स्टेशन मास्टर से भी स्वीकृति लेनी होगी. (परिशिष्ट-XII)

9. प्राइवेट नंबरों के लेन-देन के नीचे ब्लॉक फॉरवर्ड / ब्लॉक बैक मैसेज दिए जाएंगे और टीएसआर में लाल हासिल से एंट्री की जाएगी. एसएम, पीएन के लेन-देन के नीचे एससीओआर को सूचित करेगा.-(परिशिष्ट-XII)
10. पहला रोक सिगनल और आखरी रोक सिगनल को छोड़कर सभी फिक्स्ड सिगनल शंटिंग के लिए हटाए जा सकते हैं. जहां शंट संचलन सिगनल से नियंत्रित नहीं होते, वहां मार्ग में सभी संबंधित पॉइंट सही ढंग से सेट किए जाएंगे, जहां दिया गया हो वहां "कोटर बोल्ट और पिन डाला जाएगा" या "क्लैप और पैडलॉक किया जाएगा" और पीएचएस दिखाया जाएगा. (परिशिष्ट-XII)
11. जब किसी चौकी पर स्वयं अथवा रोक सिगनल के नीचे लगा हुआ स्थिर शंट सिगनल खराब हो जाता है, तो टी/369 (3बी) जारी किया जाएगा और पॉइंट्स की उचित सेटिंग सुनिश्चित करने तथा क्लैम्पिंग एवं पैडलॉकिंग द्वारा सुरक्षित करने के पश्चात ऐसी खराबी सिगनल के नीचे से आगे बढ़ो हथ सिगनल दिखाया जाना चाहिए. जब शंटिंग अनुमत सूचक (एसपीआई) खराब हो जाता है, तो टी/369 (3बी) जारी किया जाएगा और पॉइंट्स की उचित सेटिंग सुनिश्चित करने और "कोटर बोल्ट और पिन इंसर्शन" या "क्लैम्पिंग और पैडलॉकिंग" द्वारा सुरक्षित करने के बाद उसके नीचे से आगे बढ़ो हथ सिगनल दिखाया जाना चाहिए" (परिशिष्ट-XII)
12. जब यात्री गाड़ियों में गाड़ियों को जोड़ने या अलग करने के लिए शंटिंग की आवश्यकता हो, तो गाड़ियों के साथ या बिना गाड़ियों के शंटिंग इंजन / बैकिंग इंजन / गाड़ी इंजन पहले गाड़ी से 20 मीटर दूर रुकेगा और उसके बाद ध्यान से शंटिंग करेगा. (परिशिष्ट-XII) (सहायक नियम 5.13.3)
13. डेड एंड पर खत्म होने वाली लाइन पर शंटिंग संचलन में पीछे धकेलते समय, गाड़ी को डेड एंड से 20 मीटर पहले रोकना चाहिए और फिर सावधानी से पीछे धकेलना चाहिए ताकि डेड एंड से टकराने से बचा जा सके.(परिशिष्ट-XII)
14. स्टैंडर्ड बफ़र्स का इंतज़ाम और बफ़र्स / डेड एंड का रेगुलर मेंटेनेंस संबंधित सुपरवाइज़र को सुनिश्चित करना होगा. डेड एंड्स / बफ़र स्टॉप्स पर रोशनी वाली स्ट्रिप्स लगानी होंगी ताकि शंटिंग स्टाफ़ रात के समय बफ़र स्टॉप / डेड एंड के पास होने का साफ़ पता लगा सके. (संयुक्त कार्यविधि आदेश)
15. जिन स्टेशन यार्ड में ग्रेड कंडोनेशन मिल गया है, वहां शंटिंग के बारे में कंडोनेशन के साथ जारी किए गए खास निर्देशों का पालन किया जाएगा. (परिशिष्ट-XII)
16. किसी स्टेशन के आउटर, होम और आखिरी स्टॉप सिग्नल को शंटिंग के लिए "ऑफ" नहीं किया जाएगा. (सा.नि. 3.46(1))
17. जब निर्धारित शर्तों के अंतर्गत दिया गया वीटीपी (या निर्धारित वीटीओ) स्टेशन मास्टर को दिखाई न दे, तो आने वाली गाड़ी को लाइन क्लियर देने के बाद नॉन-आइसोलेटेड लाइनों पर कोई शंटिंग नहीं करनी चाहिए.(सहायक नियम 3.61.7 (3) (iii))
18. शंटर्स को स्टेशन की सीमा के अंदर शंटिंग करने की अनुमति दी जा सकती है, लेकिन मंडल रेल प्रबंधक के विशेष अनुदेशों के अलावा, उन्हें स्टेशन की सीमा के बाहर किसी भी गाड़ी में काम करने की अनुमति नहीं होगी. (सहायक नियम 4.20.1).
19. जब कोई गाड़ी खराबी या डैमेज की वजह से गाड़ी से अलग हो जाती है, तो सबसे पास के टीएसआर को बताया जाएगा. इस गाड़ी को अलग से स्टेबल और सुरक्षित किया जाएगा. ऐसी गाड़ी के साथ या उसके सामने अनावश्यक शंटिंग से बचना चाहिए. जब तक टीएसआर से फिट सर्टिफाइड न हो जाए, तब तक गाड़ी को दोबारा यातायात उपयोग के लिए या स्टेशन से दूर काम पर नहीं रखा जाएगा. (सहायक नियम 4.29.6).
20. अगर उस लाइन पर कोई शंटिंग करना ज़रूरी हो जिस पर मटीरियल ट्रेन खड़ी है ,तो गार्ड शंटिंग के दौरान पूरे समय मौजूद रहेगा. (सहायक नियम 4.64.1.2).
21. शंटिंग ऑपरेशन को स्थिर सिगनल या हथ सिगनल या मौखिक अनुदेशों द्वारा नियंत्रित किया जाएगा. (साधारण नियम 5.13 (1))

22. हालाँकि ,लोको पायलट पूरी तरह से सिगनल पर निर्भर नहीं रहेगा और हमेशा सतर्क और सावधान रहेगा. **(साधारण नियम 5.13 (2))**
23. शंटिंग ऑपरेशन के दौरान गति 15किलोमीटर प्रति घंटे से ज्यादा नहीं होनी चाहिए ,जब तक कि विशेष अनुदेशों के अंतर्गत ऐसा करने की अनुमति न दी गई हो. **(साधारण नियम 5.13 (3))**
24. लोको पायलट ,अपने लिए “ऑफ” किए गए रोक सिगनल पर जाने से पहले,जब भी आवश्यक हो,शंटिंग कर रहे रेलवे कर्मचारी के हाथ के इशारों को देखेगा. स्थिर सिगनल से चलने वाली फ्री लाइन पर लाइट इंजन के शंट संचलन के दौरान शंटिंग कर्मचारी को साथ रहने की आवश्यकता नहीं है. किसी भी शक की हालत में या जब लाइन रुकावट से खाली न हो ,तो शंटिंग कर्मचारी इंजन के साथ रहेगा और हाथ का इशारा देगा. **(सहायक नियम 5.13.1.)**
25. जिन स्टेशनों पर अलग शंटिंग कर्मचारी काम पर रखे गए हैं ,वे सभी शंटिंग ऑपरेशन देखेंगे. अन्य सभी स्टेशनों पर, शंटिंग ऑपरेशन की निगरानी स्टेशन मास्टर के आदेश पर गाड़ी के गार्ड द्वारा स्वयं की जाएगी.**(सहायक नियम 5.14.1.)**
26. अगर किसी गाड़ी को मेन लाइन से एक लाइन से दूसरी लाइन पर शंट करना आवश्यक हो, तो गार्ड अपने ब्रेक-वैन में चलेगा और ऐसी शंटिंग सिर्फ स्टेशन मास्टर की देखरेख में ही की जाएगी. **(सहायक नियम 5.14.2.)**
27. पेट्रोल ,केरोसिन तेल ,लिक्रिड फ्यूल ,स्पिरिट और दूसरे बहुत ज्यादा ज्वलनशील लिक्रिड से भरे मालडिब्बे को शंट करते समय ,गति 8 कि.मी प्रति घंटा तक ही सीमित रखनी चाहिए. **(सहायक नियम 5.14.3.)**
28. यात्रियों वाले डिब्बों को स्टेशन मास्टर और संबंधित गाड़ी के गार्ड के व्यक्तिगत आदेश के बिना शंटिंग के लिए नहीं ले जाया जाएगा. गार्ड मिलकर सभी सावधानियां बरतने, यात्रियों को चेतावनी देने और डिब्बों में यात्रियों या उन लोगों को होने वाले हादसों को रोकने के लिए ज़िम्मेदार होंगे जो यह सोचकर डिब्बों में चढ़ने या उतरने की कोशिश करते हैं कि गाड़ी स्टार्ट हो गई है. गार्ड को वैक्यूम ब्रेक कनेक्ट करना होगा और यह पक्का करना होगा कि शंटिंग सुरक्षित तरीके से की जाए. **(सहायक नियम 5.14.4.)**
29. यदि शंट संचलन शंट सिगनल/स्टार्टर सिगनल द्वारा नियंत्रित होती हैं, जो फेसिंग पॉइंट्स का पता लगाता है, तो शंट/स्टार्टर को “ऑफ” कर दिया जाएगा और अन्य सभी मामलों में, फेसिंग पॉइंट्स को क्लैप/कॉटर बोल्ट और पैडलॉक किया जाएगा. **(सहायक नियम 5.14.5.)**
30. विस्फोटक वाले मालडिब्बों की शंटिंग स्टेशन मास्टर से कम नहीं, किसी पदाधिकारी की देखरेख में ही की जाएगी, जो शंटिंग ऑपरेशन के दौरान यह सुनिश्चित करेगा. **(सहायक नियम 5.14.6.)**
- (ए) विस्फोटक वाले मालडिब्बे को इलेक्ट्रिक/डीज़ल लोकोमोटिव से कम से कम एक मालडिब्बा से अलग रखा जाएगा ,जिसमें विस्फोटक या दूसरा खतरनाक सामान या ज्वलनशील चीज़ें न हों.
- (बी) सभी संचलन की स्पीड 8 किमी प्रति घंटा से ज्यादा नहीं होनी चाहिए ,और
- (सी) कोई रफ ,हंप ,फ्लाई या लूज़ शंटिंग नहीं होती है.
31. उन स्टेशनों पर जहां विशेष अनुदेश के अंतर्गत आने वाली गाड़ी को जिन पॉइंट से गुज़रना है, वहां शंटिंग संचलन की अनुमति है, वहां नीचे दिए गए अनुदेश का अनुपालन किया जाएगा:**(सहायक नियम-5.16)**
- (1) विशेष अनुदेशों के अंतर्गत जिन शंटिंग संचलन की अनुमति है ,उन्हें सिगनलिंग और इंटरलॉकिंग योजना और स्टेशन संचालन नियम आरेख पर स्पष्ट रूप से लिखा जाना चाहिए.
- (2) विशेष अनुदेशों के अंतर्गत जिन शंटिंग मूवमेंट की अनुमति दी गई है ,उनकी जानकारी स्टेशन संचालन नियम में स्पष्ट रूप से लिखी होनी चाहिए ,साथ ही नीचे दी गई सावधानियों की सूची भी होनी चाहिए:

क्र.सं.	सिगनल वाली शंटिंग गतिविधियों की अनुमति है		बरती जाने वाली सावधानियां
	सिगनल संख्या से	पॉइंट नंबर की ओर जिसके ऊपर से आने वाली गाड़ी को गुज़रना है)	

1.			
2.			

- (3) शंटिंग संचलन आम तौर पर लोको को उस पॉइंट की ओर ले जाकर किया जाएगा ,जहाँ से आने वाली गाड़ी को गुज़रना है.
- (4) इंजन को उस जगह की ओर धकेलते हुए शंटिंग संचलन ,जहाँ से आने वाली गाड़ी को गुज़रना है , विशेष स्थिति में ही किया जाएगा और नीचे दी गई सावधानियां बरती जाएंगी:
- (क) शंटिंग स्टाफ में से एक, फॉर्मेशन की सबसे आगे वाली गाड़ी में (संचलन की दिशा में) चलेगा. अगर सबसे आगे वाली गाड़ी से चलने की कोई सुविधा नहीं है, तो शंटिंग कर्मचारी सबसे आगे वाली गाड़ी के बगल में चलेगा;;
- (ख) शंटिंग कर्मचारी पैनी नजर रखेगा और लोको पायलट को लगातार आगे बढ़ने का इशारा देगा;
- (ग) धक्का देने के दौरान लोको पायलट शंटिंग कर्मचारी द्वारा प्रदर्शित किए जा रहे आगे बढ़ने के हथ सिगनल का लगातार निरीक्षण करेगा;
- (घ) शंटिंग कर्मचारी से आगे बढ़ो हैंड सिगनल न मिलने पर ,लोको पायलट तुरंत संचलन रोक देगा.
- (ङ) शंटिंग कर्मचारी रास्ते में लोगों को चेतावनी देने के लिए लगातार सीटी बजाएगा और
- (च) लोको पायलट लगातार सीटी बजाएगा और नज़र रखेगा और किसी भी रुकावट से पहले गाड़ी को रोकने के लिए तैयार रहेगा।
32. शंटिंग कर्मचारी को अपनी जगह पर खड़े रहना होगा और लोको पायलट को लगातार हाथ के इशारे दिखाने होंगे, और संचलन को सुरक्षित रूप से मॉनिटर करने के लिए डेड-एंड का भी ध्यान रखना होगा. **(संयुक्त कार्यविधि आदेश)**
33. अगर लोको पायलट / शंटर टेढ़ेपन, लंबे लोड या रुकावट की वजह से हथ सिगनल नहीं देख पा रहा है, तो हथ सिगनल / शंटिंग के अनुदेश देने के लिए वर्किंग कैब में एक और पॉइंट्समैन को तैनात किया जाना चाहिए. अनुदेशों को लगातार भेजने के लिए वॉकी-टॉकी का उपयोग किया जा सकता है. जब कम्युनिकेशन में कोई रुकावट हो, तो लोको पायलट / शंटर को कोई संचलन नहीं करना चाहिए. **(संयुक्त कार्यविधि आदेश)**
34. वॉकी-टॉकी का उपयोग करते समय, कर्मचारियों को लाइन और ट्रेन नंबर (जैसे जीएल1 बीसीएनएचएल) स्पष्ट रूप से बताना होगा और दूसरी तरफ़ बोलने वाले की पहचान भी कन्फ़र्म करनी होगी. **(संयुक्त कार्यविधि आदेश)**
35. मुख्य कर्मचारी नियंत्रक (सीसीसी) को यह सुनिश्चित करना होगा कि लोको पायलट और शंटर को नामित यार्ड में रोस्टर के हिसाब से शंटिंग ड्यूटी देने से पहले सही एलआर और हैंडलिंग इंस्ट्रक्शन दिए जाएं. मुख्य कर्मचारी नियंत्रक (सीसीसी) को यह सुनिश्चित करना होगा कि लोको पायलट और शंटर को नामित यार्ड में रोस्टर के हिसाब से शंटिंग ड्यूटी देने से पहले सही एलआर और हैंडलिंग अनुदेश दिए जाएं. **(संयुक्त कार्यविधि आदेश)**
36. मुख्य कर्मचारी नियंत्रक/स्टेशन मास्टर को यह सुनिश्चित करना चाहिए कि शंटर्स/लोको पायलट और गाड़ी प्रबंधक को दिए गए वॉकी-टॉकी पूरी तरह चार्ज हों और काम करने की हालत में हों. अगर यार्ड की किसी विशेष स्थान पर वॉकी-टॉकी काम न कर रही हो और कम्युनिकेशन/सिगनल में कोई मुश्किल हो ,तो आगे की कार्रवाई के लिए मामले को संबंधित पर्यवेक्षक के ध्यान में लाया जाना चाहिए. **(संयुक्त कार्यविधि आदेश)**
37. यात्रियों वाली गाड़ियों में हैंड शंटिंग पूरी तरह से मना है. **(सहायक नियम 5.20.1.)**
38. 400में से 1से ज्यादा ढलान वाली ढलान पर या उसके पास मौजूद स्टेशनों पर शंटिंग करते समय स्टेशन संचालन नियम में बताई गई किसी भी विशेष सावधानी का कड़ाई से अनुपालन किया जाएगा. **(सहायक नियम 20.2)**

39. रोलर बेयरिंग वाले किसी भी वाहन की हैंड शंटिंग स्टेशन यार्ड में पूरी तरह से मना है, जहाँ सबसे बाहरी पॉइंट 1 में 400 से ज़्यादा ढलान पर हों या ऐसी ढलान से 100 मीटर के अंदर हों. **(सहायक नियम 5.20.3.)**
40. रोलर बेयरिंग के अलावा किसी और चीज़ से फिट की गई किसी भी गाड़ी की शंटिंग ऐसे स्टेशन यार्ड में की जाएगी, जहाँ सबसे बाहरी पॉइंट 260 में 1 से ज़्यादा ढलान पर हों, और लोकोमोटिव ढलान के नीचे की तरफ लगा हो। **(सहायक नियम 5.20.4.)**
41. रोलर बेयरिंग के अलावा दूसरी चीज़ों से भरी गाड़ियों की हैंड शंटिंग की अनुमति स्टेशन यार्ड में 260 में 1 से ज़्यादा ढलान पर तभी दी जा सकती है, जब यार्ड का लेआउट यह सुनिश्चित करे कि कोई भी गाड़ी स्लिप साइडिंग वगैरह की व्यवस्था होने के कारण ब्लॉक सेक्शन में न जा सके, बशर्ते निम्नलिखित सावधानियां बरती जाएं-: **(सहायक नियम 5.20.5.)**
- 1) जिस दिशा में शंटिंग की जानी है, उस दिशा में स्टेशन को लाइन क्लियर नहीं दिया जाता है.
 - 2) स्टेशन मास्टर या विशेष शंटिंग कर्मचारी, जहां मौजूद हो, स्वयं शंटिंग की देखरेख करते हैं.
 - 3) एक समय में केवल एक ही गाड़ी चलाई जाती है.
 - 4) जिस गाड़ी को ले जाना है, उसमें एक हैंड-ब्रेक लगा हुआ है जो अच्छी हालत में काम कर रहा है.
 - 5) इसे योग्य रेलवे कर्मचारी चलाता है जो आवश्यकता पड़ने पर हैंड-ब्रेक लगाता है.
 - 6) गति 5 किमी प्रति घंटा से ज़्यादा नहीं होनी चाहिए।
42. "लूज़ शंटिंग" का अर्थ है गाड़ियों को इंजन से धक्का देना और उन्हें बिना जोड़े किए आगे बढ़ने देना. किसी भी गाड़ी को तब तक लूज़ शंट नहीं किया जाएगा जब तक उसमें एक अच्छा हैंड-ब्रेक न हो या जब तक वह कम से कम दूसरी गाड़ी से जुड़ी न हो जिसमें अच्छा हैंड ब्रेक लगा हो. लूज़ शंटिंग वाली गाड़ी के साथ एक रेलवे कर्मचारी होना चाहिए जो आवश्यकता पड़ने पर हैंड-ब्रेक लगा सके. **(सहायक नियम 5.21.1.)**
43. भरे हुआ या रिक्त तेल टैंकर मालडिब्बा, टिन में पेट्रोल या केरोसिन तेल वाले वाहन, भारी मशीनरी, रेल या लकड़ी से लदे ट्रक, क्रेन, विस्फोटक सामान वाली वैन, जानवरों या मिलिट्री सामान से लदे मालडिब्बे, इंडियन एक्सप्लोसिव एक्ट में बताए गए सामान, 'लूज़ शंटिंग न किए जाएं' लेबल वाले मालडिब्बे और कोचिंग गाड़ियां, भले ही रिक्त हों, उनकी लूज़ शंटिंग की मनाई है. **(सहायक नियम 5.21.2.)**
44. "फ्लाई शंटिंग" शंट संचलन है, जिसमें दो या ज़्यादा गाड़ियों को, इंजन से धक्का देने के बाद (दूसरी गाड़ियों के साथ या उनके बिना), पॉइंट पर अलग किया जाता है. इसके लिए गाड़ियों के बीच पॉइंट को तेज़ी से उल्टा किया जाता है ताकि उन्हें अलग-अलग लाइनों पर भेजा जा सके. हंप यार्ड में हंप शंटिंग को छोड़कर फ्लाई शंटिंग की पूरी तरह से मनाई है. **(सहायक नियम 5.21.3.)**
45. सभी साइडिंगों पर फॉर्मेशन लिमिट बोर्ड लगाए जाएंगे जो बाहरी सड़कों/रिहायशी क्षेत्रों/घरों/नालों/पुलों के पास हैं. ये बोर्ड बताएंगे कि मालडिब्बों/फॉर्मेशन को ज़्यादा से ज़्यादा कितनी दूर तक धकेला जा सकता है. इस संबंध में, ऐसे सभी साइडिंगों के फॉर्मेशन लिमिट बोर्ड से 20 मीटर पहले रोक और 03 किमी प्रति घंटा गति सीमा वाला बोर्ड लगाया जाएगा. यह लोको पायलट/शंटर के लिए दृश्य अनुस्मारक होगा ताकि डेड एंड के पास शंटिंग के दौरान कोई दुर्घटना न हो. **(संयुक्त कार्यविधि आदेश)**
46. पुश बैक के दौरान, शंटर/लोको पायलट को शंटिंग स्टाफ के अनुदेशों का पालन करना चाहिए, हालांकि जब शंटर/लोको पायलट को लगे कि धक्का सामान्य से ज़्यादा ज़ोर से लग रहा है, तो उसे संचलन रोक देना चाहिए. **(संयुक्त कार्यविधि आदेश)**

एक्सोल्व्यूट ब्लॉक सिस्टम में शंटिंग (एकल लाइन) (परिशिष्ट-XII)

स्टेशन सेक्शन के भीतर :

एकल लाइन मल्टीपल एस्पेक्ट सिगनल के क्षेत्र में, एक बार लाइन क्लियर मिलने के बाद उस दिशा में कोई शंटिंग (स्टेशन सेक्शन के अंदर भी नहीं) नहीं की जाएगी, सिवाय इसके कि जहाँ स्टेशन संचालन नियम में आने

वाली गाड़ी के सामने शंटिंग की अनुमति हो (अर्थात्, एक बार डाउन गाड़ी को लाइन क्लियर मिलने के बाद, अप दिशा में कोई शंट संचलन नहीं होगा).

स्टेशन सेक्शन से आगे का भाग:

एफएसएस तक शंट अप करने के लिए:

- (i) सबसे बाहरी फेसिंग पॉइंट/आखरी रोक सिगनल/शंटिंग सीमा बोर्ड के बाहर और पहले रोक सिगनल तक की लाइन तब तक ब्लॉक नहीं की जाएगी, जब तक स्टेशन मास्टर द्वारा इस काम के लिए विशेष रूप से नामित किया गया कोई रेलवे कर्मचारी ऑपरेशन का इंचार्ज न हो और जिस ब्लॉक सेक्शन में शंटिंग होनी है, वह आने वाली गाड़ी से खाली न हो.
- (ii) शंट चाबी (की) निकाल ली जाएगी और लोको पायलट को सौंप दी जाएगी. अगर शंट चाबी (की) नहीं निकाली जा सकती, तो दूसरे छोर पर मौजूद स्टेशन मास्टर से उसकी शंट चाबी (की) निकालने और उस बारे में पीएन लेने के लिए कहा जाएगा, फिर लोको पायलट को पीएन (दूसरे छोर के स्टेशन मास्टर से मिला, वही पीएन) के साथ टी.806 दिया जाएगा.

एफएसएस से आगे शंट करने के लिए :

- (i) पहले रोक सिगनल के बाहर गाड़ी को शंट करने के लिए, लाइन को वापस ब्लॉक करना पड़ता है.
- (ii) शंट चाबी (की) सहित "शंटिंग ऑर्डर" फॉर्म टी/806 लोको पायलट को अंतिम रोक सिगनल को "ऑन" पर पार करने और ब्लॉक सेक्शन में शंट करने की अनुमति देती है. वापसी संचलन की अनुमति शंट सिगनल हटाकर या पीएचएस के मार्गदर्शन में दी जाएगी, जिसमें पॉइंट की सही सेटिंग, क्लैपिंग और पैडलॉकिंग और अगर कोई समपार फाटक है, तो उसे बंद करना सुनिश्चित किया जाएगा.
- (iii) शंटिंग पूरी होने के बाद, दोनों स्टेशन मास्टर यह सुनिश्चित करेंगे कि ब्लॉक सेक्शन क्लियर है और सामान्य कार्य आरंभ करने से पहले पीएन के साथ सूचना का आदान-प्रदान करेंगे.

नोट: अगर शंट चाबी(की) नहीं निकाली जा सकती, तो दूसरे छोर पर स्टेशन मास्टर से शंट चाबी(की) निकालने और इस बारे में पीएन प्रदान करने के लिए कहा जाना चाहिए. फिर लोको पायलट को पीएन के साथ टी/806 दिया जाएगा.

एक्सोल्क्यूट ब्लॉक सिस्टम में शंटिंग (दोहरी लाइन) (परिशिष्ट-XII)

1. स्टेशन सेक्शन के अंदर शंटिंग तब की जा सकती है जब किसी गाड़ी के लिए लाइन क्लियर मिल जाए, बशर्ते ज़रूरी आगमन सिगनल ऑन रखे जाएं.
2. सबसे बाहरी फेसिंग पॉइंट/बीएलएलबी से आगे ब्लॉक बैक से शंटिंग की अनुमति टी/806 जारी करके दी जाएगी, जिसमें लोको पायलट और गार्ड को शंटिंग की पूरी जानकारी दी जाएगी. ऐसा संचलन शंट सिगनल हटाकर, जहाँ दिया गया हो, या पीएचएस द्वारा मार्गदर्शन लेकर किया जाएगा, जिसमें पॉइंट की उचित सेटिंग, क्लैपिंग और पैडलॉकिंग और अगर कोई समपार फाटक हो तो उसे बंद करना सुनिश्चित किया जाएगा. ब्लॉक उपकरण को ट्रेन ऑन लाइन पोजीशन में रखा जाएगा और लॉक किया जाएगा या एलसीबी चाबी (की) को ऑउट पोजीशन में रखा जाएगा.
3. ब्लॉक सेक्शन में पहले से शंटिंग की अनुमति तब तक नहीं दी जाएगी जब तक कि वह क्लियर और आगे ब्लॉक न हो. लोको पायलट को एडवांस ब्लॉक सेक्शन में शंटिंग करने के लिए पीएन के साथ टी/806 जारी किया जाएगा. ब्लॉक उपकरण को ट्रेन ऑन लाइन पोजीशन में रखा जाएगा और लॉक किया जाएगा या एलसीबी चाबी(की) को अग्रिम रूप में स्टेशन मास्टर द्वारा ऑउट पोजीशन में रखा जाएगा. वापसी संचलन की अनुमति शंट सिगनल हटाकर या पीएचएस के मार्गदर्शन में दी जाएगी, जिसमें पॉइंट की सही सेटिंग, क्लैपिंग और पैडलॉकिंग और अगर कोई समपार फाटक है तो उसे बंद करना सुनिश्चित किया जाएगा.

नोट : यदि स्टेशन संचालन नियम में एलएसएस से आगे शंटिंग की अनुमति है, तो स्टेशन से दूर जा रही गाड़ी के पीछे, एलएसएस के नीचे दिया गया शंट सिगनल (अगर कोई है) "ऑफ" किया जा सकता

है या लोको पायलट को पीएन के बिना टी/806 दिया जा सकता है. जैसे ही पिछली गाड़ी सेक्शन से निकल जाए, अगर शंटिंग पूरी नहीं हुई है तो आगे की लाइन को ब्लॉक कर देना चाहिए.

ऑटोमैटिक ब्लॉक सिस्टम में शंटिंग (परिशिष्ट-XII)

स्वचालित ब्लॉक प्रणाली में, मुख्य लाइनों पर या ब्लॉक सेक्शन में शंटिंग की इजाजत नहीं है, जब तक कि स्टेशन में अर्ध स्वचालित रोक सिगनल को मैनुअल मोड में न लाया जाए, ताकि ऐसे सिगनल आरंभ में "ऑन" हो जाएं.

ए. स्टेशन सेक्शन के भीतर

- (i) स्टेशन सेक्शन के अंदर सामान्यतः शंटिंग की अनुमति होती है. जब लाइन क्लियर मिल जाता है, तो स्टेशन सेक्शन के अंदर उस दिशा में शंटिंग की अनुमति नहीं होती, सिवाय इसके कि जब स्टेशन संचालन नियम में आने वाली गाड़ी के सामने शंटिंग की अनुमति हो (अर्थात् एक बार जब डाउन गाड़ी को लाइन क्लियर मिल जाता है, तो अप दिशा में कोई शंट संचलन नहीं होगा). पीएन के बिना प्राधिकारी टी/806 लोको पायलट और गार्ड को जारी की जाएगी, जब तक कि वरिष्ठ मंडल परिचालन प्रबंधक द्वारा सहायक नियम 5.14.9 में बताए अनुसार अधिसूचित न किया जाए.
- (ii) दोहरी लाइन सेक्शन पर, स्टेशन सेक्शन के भीतर शंटिंग की जा सकती है, बशर्ते आवश्यक आगमन सिगनल ऑन रखे जाएं.

बी. स्टेशन से आगे का भाग

एकल लाइन पर, यातायात की दिशा दूसरे छोर पर ब्लॉक स्टेशन के स्टेशन मास्टर को प्राइवेट नंबरों के साथ सूचना का आदान-प्रदान करके, दोनों ब्लॉक स्टेशनों के बीच के सेक्शन को एक ब्लॉक सेक्शन मानते हुए निर्धारित की जाएगी. टी/806 पीएन के साथ लोको पायलट और गाड़ी प्रबंधक को जारी किया जाएगा, जिसमें शंटिंग की पूरी जानकारी लिखी होगी.

संचलन पूरा होने के बाद, स्टेशन मास्टर यह सुनिश्चित करेगा कि गाड़ी पूरी तरह से आ गई है और दूसरे छोर पर ब्लॉक स्टेशन के स्टेशन मास्टर को प्राइवेट नंबर के साथ सूचना का आदान-प्रदान करके जानकारी देगा. प्रविष्टियां टीएसआर में लाल स्याही से की जाएंगी.

सी. सबसे बाहरी फेसिंग पॉइंट्स / बीएसबीएल के बाहर दोहरी लाइन पर शंटिंग:

1. किसी ब्लॉक स्टेशन का स्टेशन मास्टर, जो पीछे के ब्लॉक सेक्शन में शंटिंग करना चाहता है, उसे पीछे के ब्लॉक स्टेशन के स्टेशन मास्टर को सूचित करेगा और दोनों ब्लॉक स्टेशनों के बीच के पूरे सेक्शन को एक ब्लॉक सेक्शन मानना होगा, साथ ही यह भी सुनिश्चित करेगा कि पीछे वाले स्टेशन से सेक्शन में आने वाली सभी गाड़ियां उसके स्टेशन पर पूरी तरह से पहुँच गई हैं.
2. फिर स्टेशन मास्टर पीछे वाले स्टेशन मास्टर के साथ सूचना का आदान-प्रदान करके ब्लॉक बैक करेगा और प्राइवेट नंबर लेकर यह भरोसा दिलाएगा कि ब्लॉक सेक्शन में शंटिंग की इजाजत है और जब तक ब्लॉक बैक कैंसिल नहीं हो जाता, तब तक उसकी तरफ से कोई ट्रेन नहीं भेजी जाएगी।
3. पिछले स्टेशन से मिले पीएन के साथ टी/806, लोको पायलट और गाड़ी प्रबंधक को जारी किया जाएगा, जिसमें शंटिंग की पूरी जानकारी दी जाएगी.
4. ऐसा संचलन शंट सिगनल हटाकर, अगर दिया गया हो, या पीएचएस द्वारा मार्गदर्शन दिया जाएगा, जिसमें पॉइंट की सही सेटिंग, क्लैम्पिंग और पैडलॉकिंग और अगर कोई समपार फाटक हो तो उसे बंद करना सुनिश्चित किया जाएगा.
5. टीएसआर में प्रविष्टियां लाल स्याही से करनी होंगी. संचलन पूरा होने पर, दोनों स्टेशन मास्टर यह सुनिश्चित करने के बाद कि ब्लॉक सेक्शन गाड़ियों से खाली है, ब्लॉक बैक कैंसिल करने के लिए प्राइवेट नंबरों के साथ सूचना का आदान-प्रदान करेंगे.

डी. एलएसएस से आगे शंटिंग: (ब्लॉक फॉरवर्ड)

1. किसी ब्लॉक स्टेशन का स्टेशन मास्टर, जो पहले से ब्लॉक सेक्शन में शंटिंग करना चाहता है, यह सुनिश्चित करेगा कि दोनों ब्लॉक स्टेशनों के बीच की पूरी लाइन गाड़ियों से खाली हो और उसे एक ब्लॉक सेक्शन माना जाएगा।
2. फिर स्टेशन मास्टर आगे वाले स्टेशन के स्टेशन मास्टर के साथ सूचना का आदान-प्रदान करते हुए "ब्लॉक फॉरवर्ड" करेगा और यह आश्वासन देते हुए निजी नंबर प्राप्त करेगा कि ब्लॉक सेक्शन में शंटिंग की अनुमति है और "ब्लॉक फॉरवर्ड" रद्द होने तक कोई भी गाड़ी नहीं भेजी जाएगी।
3. स्टेशन मास्टर से अग्रिम रूप से प्राप्त पीएन के साथ प्राधिकरण टी/806 लोको पायलट/गार्ड को दिया जाएगा और लोको पायलट को "ऑन" स्थिति में एलएसएस पार करने के लिए प्राधिकृत किया जाएगा।
4. वापसी संचालन को शंट सिग्नल हटाकर, जहाँ दिया गया हो, या पीएचएस द्वारा मार्गदर्शन करके प्राधिकृत किया जाएगा, जिसमें पॉइंट की सही सेटिंग, क्लैम्पिंग और पैडलॉकिंग और यदि कोई समपार फाटक हो, तो उसे बंद करना सुनिश्चित किया जाएगा।
5. शंटिंग पूरी होने पर, स्टेशन मास्टर यह सुनिश्चित करेगा कि गाड़ी पूरी तरह आ गई है और प्राइवेट नंबरों से दूसरी तरफ के स्टेशन मास्टर के साथ सूचना का सही तरीके से आदान-प्रदान करके "ब्लॉक फॉरवर्ड" कैसिल कर देगा। टीएसआर में प्रविष्टि लाल स्याही से की जाएगी।

स्टेशन से दूर जा रही गाड़ी के पीछे शंटिंग करना: (परिशिष्ट- XII)

1. स्टेशन संचालन नियम में स्थानीय हालात जैसे ढलान, विज़िबिलिटी, स्पीड, वज़न और गाड़ियों के ब्रेक पावर को ध्यान में रखते हुए ऐसे संचालन की अनुमति दी जाएगी।
2. यदि अनुमति हो तो दूसरे छोर पर स्टेशन मास्टर को सूचित करें, बिना पीएन के टी/806 जारी करें तथा लोको पायलट को "ऑन" स्थिति में एलएसएस पार करने के लिए प्राधिकृत करें।
3. शंटिंग की देखरेख करने वाला गार्ड/योग्य रेलवे कर्मचारी संचालन के साथ रहेगा।
4. अगर दूर जा रही गाड़ी शंटिंग गाड़ी के लौटने से पहले स्टेशन पर आ जाती है, तो स्टेशन मास्टर गाड़ी के क्लियरेंस को नोट कर लेगा और अगर ब्लॉक सेक्शन में अभी भी रुकावट है तो आगे ब्लॉक कर देगा।
5. अगर दूर जा रही गाड़ी आगे के स्टेशन पर नहीं पहुँचती है, लेकिन शंटिंग गाड़ी स्टेशन पर वापस आ जाती है, तो स्टेशन मास्टर प्राइवेट नंबर से सूचना के आदान-प्रदान के अंतरगत शंटिंग गाड़ी के आने की जानकारी देगा। फिर गाड़ियों को सामान्य तरीके से चलाया जा सकता है।

संरक्षा संगठन

दक्षिण मध्य रेलवे

अस्वीकरण:

यह स्पष्ट किया जाता है कि इस फ्लाई लीफ में इस विषय पर उल्लिखित उपर्युक्त सामग्री विभिन्न मैनुअल, रेलवे बोर्ड के पत्रों और अन्य पत्रों के उद्धरण हैं। इसे मूल पत्र और समय-समय पर जारी दूसरे मैनुअल/पत्र के साथ पढ़ा जाना चाहिए और यह आरडीएसओ, रेलवे बोर्ड या क्षेत्रीय रेलवे द्वारा निर्धारित किसी वर्तमान प्रावधान का अधिक्रमण नहीं करती है। यह फ्लाई लीफ सिर्फ मार्ग-निर्देशन के लिए है और यह कोई वैधानिक दस्तावेज़ नहीं है।

SOUTH CENTRAL RAILWAY

Safety.387/Fly Leaf/19/2025

Fly Leaf No. 19/ 2025

Attention..... Loco Running Staff and Operating Officials.....

SHUNTING.

(Appendix-XII of G&SR, AS No.22 dated 22-09-2025, other related rules from G&SR and
SCR JPO dated 21.10.2025)

“Shunting” means the movement of a vehicle or vehicles with or without an engine or of any engine or any other self-propelled vehicle, for the purpose of attaching, detaching or transfer or for any other purpose; **(GR 1.02 (49))**

1. Shunting instructions are the instructions issued by the Station Master to the Loco Pilot, Shunter, Guard, Shunting Jamedar or any Points Man nominated for the purpose regarding the particulars of shunting to be done. Shunting operations shall be controlled by fixed signals or hand signals or by verbal directions. **(App-XII)**
2. At major stations where separate staff viz., outdoor Station Master / Yard SM / YM / Shunting Master / Shunting Jamedar are provided for supervising the shunting, Form No. T/806 need not be given within station section. Such stations shall be notified by respective Sr.DOMs and incorporated in Station working rules. **(App-XII) (SR 5.14.9)**
3. Shunting order in Form T/806 shall be issued with details of all shunt movements to be carried out with in station section and for performing shunting during block forward / block back in double line and block back in single line. The Guard /competent railway servant, supervising the shunting shall accompany the train. Closure of LC gates if any shall be ensured by SM and Loco Pilot. **(App-XII)**
4. Shunting order in Form T/806 issued shall also be duly filled with additional information regarding length of the siding. **(JPO)**
5. It is the responsibility of the LP / TMR/Shunter and shunting staff to acquaint with shunting restrictions before commencement of shunting. **(JPO)**
6. The person, who initially gives instructions for shunting operations, shall not change instructions and authorise the changing of point etc., unless he has satisfied himself that shunting operations have been stopped completely. **(JPO)**
7. Shunting staff shall have the knowledge of layout of the station, yard or line where they are operating. They should clearly understand the length of the line up to the dead end, measured in terms of meters / number of coaches or wagons it can accommodate. Before initiating push-back shunting, the Loco Pilot / Shunter / Shunting Staff shall know the number of wagons or coaches involved. **(JPO)**
8. The Station Master shall ensure that the relevant block section in the Absolute Block System, and the entire line between two block stations in the Automatic Block System, is clear of trains. The SM shall also obtain consent from the Station Master at the other end before initiating block forward or block back operations. **(App-XII)**
9. Block forward / Block back messages shall be given under exchange of Private numbers and entries shall be made in red ink in the TSR. SM shall inform the SCOR under exchange of PN. **(App-XII)**
10. All fixed signals except First stop signal and Last Stop Signal may be taken off for Shunting purposes. Where shunt movements are not governed by signals, all concerned points in the route shall be correctly set, “cotter bolted and pin inserted” where provided or “clamped and padlocked” and PHS exhibited. **(App-XII)**

11. When a fixed shunt signal on a post by itself or below a Stop signal becomes defective, T/369 (3b) shall be issued and Proceed Hand Signal should be shown from the foot of such defective signal after ensuring proper setting of points and securing by clamping and padlocking. When a Shunting Permitted Indicator (SPI) becomes defective, T/369 (3b) shall be issued and Proceed Hand Signal should be shown from its foot after ensuring proper setting of points and securing by "cotter bolt and pin insertion" or "clamping and padlocking" **(App-XII)**
12. When shunting is required to be carried out for attaching or detaching of vehicles on passenger carrying trains, the shunting engine / banking engine / train engine with or without vehicles shall first come to a halt 20 metres away from the train and thereafter perform the shunting carefully. **(App-XII) (SR 5.13.3)**
13. While pushing back in shunting movement on line terminating in Dead End, train must be stopped 20 meters before the Dead End and then shall be pushed back cautiously so that bumping with Dead end can be avoided. **(App-XII)**
14. Provision of Standard buffers and regular maintenance of buffers / dead end shall be ensured by the Supervisor concerned. Illuminated strips to be provided to dead ends / buffer stops to enable shunting staff to notice nearness of buffer stop / dead end clearly during night time. **(JPO)**
15. In station yards where grade condonation has been obtained, specific instructions that are issued along with the condonation with regard to shunting shall be adhered to. **(App-XII)**
16. The Outer, Home and the last Stop signal of a station shall not be taken "OFF" for shunting purposes. **(GR 3.46(1))**
17. When the VTP (or the prescribed VTO) provided under conditions laid down is not visible to the Station Master, no shunting should be carried out on non-isolated lines after granting Line Clear to an approaching train. **(SR 3.61.7 (3) (iii))**
18. Shunters may be allowed to perform shunting inside station limits, but, except under special instructions issued by the DRM, they shall not be allowed to work any train outside station limits. **(SR 4.20.1).**
19. When a vehicle has been detached from a train due to defect or damage, the nearest TXR shall be advised. This vehicle shall be stabled and secured separately. Unnecessary shunting with or against such vehicle shall be avoided. The vehicle shall not be accepted again for traffic use or worked away from the station until certified fit by the TXR. **(SR 4.29.6).**
20. If it is necessary to perform any shunting on the line on which the material train is stabled, the Guard shall be present throughout the period the shunting is performed. **(SR 4.64.1.2).**
21. Shunting operations shall be controlled by fixed signals or hand signals or by verbal directions. **(GR 5.13 (1))**
22. The Loco Pilot shall not, however, depend entirely on signals and shall always be vigilant and cautious. **(GR 5.13 (2))**
23. The speed during shunting operations shall not exceed 15 kilometres an hour unless otherwise authorised by special instructions. **(GR 5.13 (3))**
24. The Loco Pilot shall, before moving on the Stop signal taken "OFF" for him, observe the hand signals of the Railway servant conducting shunting, whenever necessary. The shunting staff need not accompany during shunt movements of light engine(s) on to a free line governed by fixed signals. In case of any doubt or when the line is not clear of obstruction, the engine(s) shall be accompanied and hand signalled by Shunting Staff. **(SR 5.13.1.)**
25. At stations where separate shunting staff are employed, they shall attend to all shunting operations. At all other stations, shunting operations shall be supervised personally by the Guard of the train, under the orders of Station Master. **(SR 5.14.1.)**
26. In case it is necessary to shunt a train from one line to another across the main line, the Guard shall travel in his brake-van and such shunting shall be conducted only under the supervision of Station Master. **(SR 5.14.2.)**
27. While shunting wagons loaded with petrol, kerosene oil, liquid fuel, spirit and other highly inflammable liquids, the speed should be restricted to 8 KMPH. **(SR 5.14.3.)**

28. Carriages containing passengers shall not be moved for shunting purposes without the personal orders of the Station Master and also the Guard of the train concerned, who will jointly be responsible for taking all precautions, to warn passengers and to prevent accidents either to the passengers in the carriages or to those attempting to get into or out of them under the impression that the train is being started. The Guard shall have the vacuum brake connected up and ensure that the shunting is performed safely. **(SR 5.14.4.)**
29. In case shunt movements are governed by Shunt signal/Starter signal, which detect the facing points, the Shunt/Starter shall be taken "OFF" and in all other cases, the facing points shall be clamped/cotter bolted and padlocked. **(SR 5.14.5.)**
30. Shunting of wagons containing explosives shall not be carried out except under the superintendence of an official not lower than Station Master who shall ensure that during shunting operations – **(SR 5.14.6.)**
 - (a) Wagons containing explosives shall be separated from Elec/Diesel locomotive by a minimum number of one wagon not containing explosives or other dangerous goods or articles of inflammable nature.
 - (b) The speed of all movements does not exceed 8 KMPH, and
 - (c) No rough, hump, fly or loose shunting takes place.
31. At stations where shunting movements towards points over which the incoming train is to pass, are permitted under Special Instructions, the following instructions shall be followed: **(SR 5.16.)**
 - (1) The shunting movements which are permitted under special instructions should be clearly endorsed on the Signalling & Interlocking Plan and Station Working Rule Diagram.
 - (2) The details of shunting movements that have been permitted under special instructions should be clearly mentioned in the Station Working Rules along with the list of precautions to be taken as follows:

S. No.	Signaled shunting movements permitted		Precautions to be taken
	From Signal No.	Towards Point No. (over which incoming train is to pass)	
1.			
2.			

- (3) The shunting movement shall normally be carried out with Loco in leading towards the point over which incoming train is to pass.
- (4) Shunting movement with engine pushing towards the point over which incoming train is to pass shall be done under exceptional circumstances duly observing the following precautions:
 - (a) One of the shunting staff shall travel in the leading vehicle (towards the direction of movement) of the formation. If there is no facility to travel by the leading vehicle, the shunting staff shall walk by the side of the leading vehicle;
 - (b) The shunting staff shall keep a sharp lookout and continuously exhibit Proceed Hand Signal to the Loco Pilot;
 - (c) During the pushing the Loco pilot shall continuously observe the Proceed Hand Signal that is being exhibited by the shunting staff;
 - (d) In the absence of Proceed Hand Signal from the Shunting Staff, the Loco Pilot shall stop the movement immediately.
 - (e) The Shunting staff shall continuously whistle to warn the people on the way and
 - (f) The Loco Pilot shall whistle continuously and keep a sharp look out and be prepared to stop the train short of any obstruction.
32. Shunting staff shall position themselves and continuously exhibit hand signals to the Loco Pilot and also have view of dead-end to monitor the movement safely. **(JPO)**
33. In case LP / Shunter is unable to see the hand signals due to curvature, lengthier load or obstruction, an additional Pointsman should be deputed in the working cab to relay the hand signals / shunting instructions. Walkie talkie can be used for continuous flow of

instructions. No movement is to be carried out by Loco Pilot / Shunter when there is any break in communication. **(JPO)**

34. While using walkies talkies, Staff shall clearly mention line and train number (Ex. GL1 BCNHL) and also confirm the identity of the speaker at the other end. **(JPO)**
35. The Chief Crew Controller (CCC) must ensure that Loco Pilots and Shunters are provided with proper LR and handling instructions before being assigned rostered shunting duties in the nominated yards. Additionally, Loco Inspectors (LIs) shall conduct regular checks on shunting operations and assess the driving techniques of Shunters during the course of shunting activities. TI / SM / YMs shall check the Shunting practices of the staff and educate them on safe working procedures. **(JPO)**
36. Chief Crew controller/SM should ensure that walkie- talkies supplied to Shunters/ LPs and train manager are fully charged and in working condition. In case of non-functioning and communication/signal problem at the particular location of the yard, the matter should be brought to the notice of concerned supervisors for further action. **(JPO)**
37. Hand shunting of vehicles occupied by passengers is strictly prohibited. **(SR 5.20.1.)**
38. In performing shunting at stations situated on or near a falling gradient steeper than 1 in 400, any special precautions stipulated in the SWR shall be strictly adhered to. **(SR 5.20.2.)**
39. Hand shunting of any vehicle fitted with roller bearings is strictly prohibited at a Station yard where the outermost points are on a grade steeper than 1 in 400 or situated within 100 meters of such a gradient. **(SR 5.20.3.)**
40. Shunting of any vehicle fitted with other than roller bearings shall be done at a station yard where the outermost points are on a grade steeper than 1 in 260 only with locomotive attached towards the falling side of the gradient. **(SR 5.20.4.)**
41. Hand shunting of vehicles fitted with other than roller bearings may be permitted at a station yard on a grade steeper than 1 in 260 only when the layout of the yard ensures that no vehicle can escape into the block section by provision of slip siding etc., provided the following precautions are taken :- **(SR 5.20.5.)**
 - 1) Line Clear is not granted to the station in the direction in which the shunting is to be performed.
 - 2) The Station Master or the special shunting staff, where provided, personally supervises the shunting.
 - 3) Only one vehicle is moved at a time.
 - 4) The vehicle to be moved is fitted with a hand-brake in good working order.
 - 5) It is manned by a competent railway servant to apply the hand-brake as and when necessary.
 - 6) The speed does not exceed 5 KMPH.
42. "Loose shunting" means vehicles being pushed by an engine and being allowed to run forward unattached. No vehicle shall be loose shunted unless provided with an efficient hand-brake or unless the vehicle is attached to at least another vehicle fitted with an efficient hand brake. A loose shunted vehicle shall be accompanied by a railway servant to pin down the hand-brake, when necessary. **(SR 5.21.1.)**
43. Loose shunting of or against loaded or empty oil tank wagons, vehicles containing petrol or kerosene oil in tins, trucks loaded with heavy machinery, rails or timber, cranes, loaded explosive vans, wagons loaded with live stock or military consignment, articles mentioned in the Indian Explosive Act, wagons labelled 'not to be loose shunted' and coaching vehicles, even if empty, is prohibited. **(SR 5.21.2.)**
44. "Fly shunting" is a shunt movement in which two or more vehicles to be moved, after being given an impetus by an engine (with or without other vehicles attached) are separated at the points, by the points being reversed smartly between the vehicles, in order to send them on to different lines. Fly shunting is strictly prohibited except for hump shunting in hump yards. **(SR 5.21.3.)**
45. Formation limit boards shall be provided at all sidings which are in close proximity with outside roads/ residential areas/ dwellings/nullahs /culverts indicating the maximum

permissible extent to which wagons/formation may be pushed. In this regard STOP and proceed with 03 kmph speed restriction board is to be provided at 20 metres before formation limit board of all such sidings to serve as a visible reminder for LP/Shunter to avoid any mishap during shunting near dead ends. Details and provision of such additional boards/ indicators shall be shown in SWR. **(JPO)**

46. During push back, Shunter/ LP should follow the instructions of shunting staff, however when the Shunter / LP feels pushing hard than usual, he should stop the movement. **(JPO)**

SHUNTING IN ABSOLUTE BLOCK SYSTEM (Single Line) (App-XII)

Within Station Section:

On single line multiple aspect signalling territory, no shunting (even within station section) shall be done in that direction, once Line Clear is granted except where shunting in the face of an approaching train is permitted in SWR (i.e. once Line Clear is granted to a down train, no shunt movement shall take place in up direction).

Beyond Station Section:

To shunt up to FSS:

- (i) The line outside the outermost facing point / Last stop signal / Shunting limit board and up to First Stop Signal shall not be obstructed unless a railway servant specially nominated in this behalf by the station master is in charge of operations and also the block section into which shunting is to take place is clear of an approaching train.
- (ii) Shunt key shall be extracted and handover to Loco pilot. If shunt key cannot be extracted, SM at other end should be asked to take out his shunt key and obtain PN to that effect, then LP shall be given T.806 with PN (the same PN received from other end SM).

To shunt beyond FSS:

- (i) For shunting a train outside the First stop signal, the line has to be blocked back.
- (ii) The Shunt Key together with "Shunting Order" Form T/806 authorizes the Loco Pilot to pass the Last Stop Signal at "ON" and shunt into the Block Section. Return movement shall be permitted by taking off shunt signals or guided by PHS duly ensuring proper setting, clamping and padlocking of points and closure of LC gates if any.
- (iii) After completion of the shunting, both SMs shall ensure that block section is clear and exchange messages supported by PNs before resuming normal working.

Note: If shunt key cannot be extracted, the station master at other end should be asked to take out the shunt key and to give PN to that effect. Then the loco pilot shall be given T/806 with PN.

SHUNTING IN ABSOLUTE BLOCK SYSTEM (Double Line) (App-XII)

1. Shunting *within the station section* can be carried out when line clear is granted for a train, provided the necessary reception signals are kept at ON.
2. Shunting beyond outermost facing points/BSLB by block back shall be permitted by issuing T/806 with PN to LP and Guard duly mentioning the particulars of shunting. Such movement shall be authorised by taking off shunt signal, where provided or guided by PHS duly ensuring proper setting, clamping and padlocking of points and closure of LCs if any. Block instrument shall be kept in Train on line position and locked or LCB key in OUT position.
3. Shunting in the block section in advance shall not be permitted unless it is clear and blocked forward. Loco pilot shall be issued with T/806 with PN to do the shunting in the advance block section. Block instruments shall be kept in Train on line position and locked or LCB key shall be kept in OUT position by advance SM. Return movement shall be permitted by

taking off shunt signals or guided by PHS duly ensuring proper setting, clamping and padlocking of points and closure of LC gates if any.

Note: If shunting beyond LSS is permitted in Station Working Rules behind the train travelling away from a station, the shunt signal (if any) provided below the LSS may be taken "OFF" or the Loco Pilot may be given T/ 806 without PN. As soon as the preceding train clears the section, the line should be blocked forward if the shunting is not completed.

SHUNTING IN AUTOMATIC BLOCK SYSTEM (App-XII)

In Automatic Block System, shunting on to the main lines or in to the block section is not permitted unless semi-automatic stop signals in the station are brought to manual mode, so as to bring such signals to "ON" initially.

a. Within station section

- (i) Shunting is permitted within station section generally. When Line Clear is granted, shunting within station section is not permitted in that direction, except where shunting in the face of an approaching train is permitted in Station Working Rules (i.e. once Line Clear is granted to a down train, no shunt movement shall take place in up direction). The Authority T/806 without PN shall be issued to the Loco Pilot and Guard unless notified by Sr.DOM as laid down in SR 5.14.9.
- (ii) On double line section, shunting within the station section can be carried out, provided the necessary reception signals are kept at on.

b. Beyond station section

On single line, the direction of traffic shall be established by duly intimating Station Master of the block station at the other end under exchange of messages supported by Private Numbers, treating section between both the block stations as one block section. T/806 with PN shall be issued to LP and Train Manager duly mentioning the particulars of *shunting*.

After completion of the movement, Station Master shall ensure complete arrival of the train and communicate to the Station Master of block station at the other end duly exchanging messages supported by Private Numbers. The entries shall be made in red ink in the TSR.

c. Shunting on double line outside outermost facing points / BSLB:

1. Station Master of a block station, who intends to perform shunting into block section in rear shall inform the Station Master of the block station in rear and treat entire section between the two block stations as one block section duly ensuring that all the trains, which entered into the section from the station in rear have arrived complete at his station.
2. Then the Station Master shall **block back** duly exchanging the messages with Station Master in rear and obtain private number in assurance that the shunting is permitted into the block section and no train will be despatched from his end till the **block back** is cancelled.
3. T/806 with PN obtained from station in rear shall be issued to LP and Train Manager duly mentioning the particulars of *shunting*.
4. Such movement shall be authorised by taking off shunt signal, where provided or guided by PHS duly ensuring proper setting, clamping and padlocking of points and closure of LCs if any.
5. The entries must be made in red ink in TSR. On completion of the movement, both the Station Masters shall exchange messages supported by private numbers for cancellation of **block back** after ensuring that the **block section** is clear of trains.

d. Shunting beyond LSS: (block forward)

1. Station Master of a block station, who intends to perform shunting into block section in advance, shall ensure that the entire line in advance between both the block stations is clear of trains and shall treat as one block section.

2. Then the Station Master shall “block forward” duly exchanging the messages with Station Master of the station in advance and obtain private number in assurance that the shunting is permitted into the block section and no train will be despatched until the “block forward” is cancelled.
3. The Authority T/806 with PN received from Station Master of station in advance shall be given to loco pilot/Guard and authorizing the Loco Pilot to pass LSS at “ON”.
4. Return movement shall be authorised by taking off shunt signal, where provided or guided by PHS duly ensuring proper setting, clamping and padlocking of points and closure of LCs if any.
5. On completion of shunting, the SM shall ensure complete arrival of the train and cancel “block forward” duly exchanging messages with the SM at the other end supported by Private Numbers. The entries shall be made in red ink in the TSR.

SHUNTING IN REAR OF A TRAIN TRAVELLING AWAY FROM THE STATION: (App-XII)

1. The Station Working Rules shall permit such movements duly considering the local conditions like gradient, visibility, speed, weight and brake power of trains.
2. If permitted, intimate the Station Master at other end, issue T/806 without PN and authorize the Loco Pilot to pass LSS at “ON”.
3. Guard / competent railway servant, supervising the shunting shall accompany the movement.
4. If the train traveling away clears into the station in advance, before the return of Shunting train, the Station Master shall note down the clearance of the train and block forward if the block section is still obstructed.
5. If the train travelling away does not clear into the station ahead, but the shunting train returns to the station, Station Master shall intimate about the arrival of shunting train, under exchange of messages supported by Private Numbers. Then the trains can be dealt normally.

SAFETY ORGANISATION

SOUTH CENTRAL RAILWAY

Disclaimer :

It is clarified that the above content mentioned on the subject in this FLY Leaf is an extract from different manuals, RB's letters and other letters. The same to be read in conjunction with the original letter & other manuals / letters issued from time to time and does not supersede any existing provisions laid down by RDSO, Railway Board or Zonal Railways. This FLY Leaf is for guidance only and it is not a statutory document.