

South Central Railway



Office of the DRM/T/SC,
Sanchalan Bhavan,
Secunderabad.

No.C/T/187/SC/2025/13.

Date: 12.12.2025

All TIs/SMRs/SMs and CHC/SC

OPERATING SAFETY CIRCULAR No.13/25

Sub: Occasions for conducting of GLP check -Reg.

Ref: DME/(C&W)/SC,Lr.No: CM.44.C&W.Detention dated 05.12.25.

On 24.11.25, Tr.No. BCNHL was unloaded at PNDP. During unloading, TMR has noticed metal on tyre on Wagon no. BCNHL ECR 33101010784 (19th from T.E) and informed C&W control at 08:00 hrs and TXR staff have been arrived at 09.00 hrs, attended and permitted the affected wagon.

Train was started without GDR check by crew after unloading at PNDP.

Train departed at 09.37 hrs and again stopped at BKL at 10.20 hrs as Engineering staff reported brake binding and metal on tyre on wagon no SECR 33141288136 BCNHL/Empty(24th wagon form T.E) and informed to C&W control. Further C&W staff has been deployed from DKJ and arrived BKL at 14.00 hrs.

Detachment memo was given after checking the affected wagon at 14:45 hrs (i.e 24th from TE) duly mentioning the reason that Empty/Load handle is set to loaded position on empty wagon and led to brake binding and metal on tyre on the wagon no SECR 33141288136 BCNHL/Empty (24th form T.E).

After detaching the wagon Train departed at 22.40 hrs.

As per SCR G&SR 2020, SR.4.32.10.1 GLP check is required in the following circumstances.

- (i). At every loading/Unloading point, the CC and Premium rakes, shall be checked by the Guard and the Loco Pilot, before commencement of journey;
- (ii). After a rake is unloaded in a tippler, where C&W staff are not available GLP check shall be done by the Guard and the Loco Pilot.
- (iii). For end to end BPC rakes, if the unloading point is not a train examination point, then the rake shall be cleared with GLP check to the next examination point in the direction of movement.
- (iv). For end to end rakes, In case where back loading is done at a non-train examination point, such trains shall be moved on GLP check upto first nominated train examination yard in the direction of movement.
- (v). While clearing a rake stabled for more than 24 hours at a station enroute.
- (vi). If BPC is invalid.

All TIs/SMRs to counsel the staff in this regard and ensure strict compliance.


(Mithun Raja Beri)
DOM/Genl./SC

Copy to: DRM/SC for kind information
ADRM/O/SC for kind information
Sr.DOM/SC for kind information
Sr.DSO/SC for kind information
All DOMs &AOMs/AOs for information