

To
All Traffic Inspectors (TIs), All SMRs and SSs (Station In-charges)

Sub: Repeated Unusual Incidents due to failure of Optg Staff – Serious Concern- reg

It has been observed with grave concern that during the recent past, multiple unusual incidents have occurred in SC Division purely due to utter negligence, lack of alertness and failure to adhere to prescribed Operating Rules and procedures by on-duty Operating Staff.

These lapses have resulted in detention of trains, loss of punctuality, SPAD-related incidents and severe embarrassment to the Division attracting adverse remarks from higher authorities.

Despite repeated instructions and counselling, such incidents continue to occur, indicating a serious deterioration in safety consciousness and discipline among some Operating Staff.

The details of the unusual incidents are furnished below for ready reference:

Unusual Incident No. 1

Date:05-12-25 Time: 19:48 Station: Cherlapalli (CHZ), SC-KZJ section
LP of Train No. 12758 Express reported in CMS that while approaching CHZ, UP Home signal was taken OFF to main line (non-PF line) even though the train had a scheduled halt.
On being informed by LP, the Dy.SS/CHZ put back the Home signal and subsequently taken OFF to PF-4 / Road-7.
D&AR: Charge sheet issued to on-duty Dy.SS/CHZ.

Unusual Incident No. 2

Date:07-12-25 Time:17:30 Station: Jangaon (ZN), SC-KZJ section
LP of Train No. 12714 Express reported that while approaching ZN station, DN Home signal was showing 'Proceed' aspect despite the train having a scheduled halt. On being informed by LP, Dy.SS/ZN put back the signal and later taken OFF Home signal to the platform line.
D&AR: Charge sheet issued to on-duty Dy.SS/ZN.

Unusual Incident No. 3

Date:10-12-25 Time:06:16 Station: Maula-Ali 'C' Cabin (MLY), SC-KZJ section
LP of Train No. 12775 Express reported that the UP-Home signal was taken OFF towards Ammuguda direction instead of SC direction.
The same was rectified after information to Dy.SS/MLY 'C' Cabin.
D&AR: Charge sheet issued to on-duty Dy.SS.

Unusual Incident No. 4

Date:14-12-25 Time:22:50 Station: Jangaon (ZN), SC-KZJ section
On-duty Dy.SS obtained Line Clear for Train No. 12252 Express and took OFF LSS and Starter. Due to improper operation of LSS before LCPR pick-up, the LSS was not obeyed, which was not noticed by Dy.SS. The LP passed the Starter at OFF and the LSS at ON, resulting in a SPAD. The train was later restarted on PLCT and Restarting Memo.
The Dy.SS further committed incorrectly in writing that LSS was normalized by mistake, whereas in fact the signal had not obeyed at all, showing complete lack of knowledge and observation.
Initial enquiry: Dy.SS/ZN held responsible with secondary responsibility for the SPAD

Unusual Incident No. 5

Date: 15-12-25 Time: 22:40 Station: Ramagundam (RDM), KZJ-BPQ section
Down BNHT Goods train passed DN ML Starter and Intermediate Starter in OFF condition. Subsequently, DN LSS S-24 was wrongly normalized by on-duty Dy.SS/RDM (Centre), causing the LSS to put back to ON while approaching the Train. LP stopped the train after passing the LSS and informed the SM. Train was restarted after issuing T/D-1425 and Restart Memo.

Unusual Incident No. 6

Date: 29-09-2025 Time 10:20 Station: Secunderabad Yard (Washing Siding)
While performing Shunting at Washing Siding/ SC, Shunting staff have failed to ensure correct setting of Points while allowing forward shunt movement. This has resulted in Trail through of Points. Further without noticing the Trail through of Points, reverse movement allowed on same point resulted in Derailment of Coaching Stock.

Unusual Incident No. 7

Date: 10-11-2025 Time: 05:58 Station: Cherlapalli (Coaching Yard)
While performing Shunting at CHZ Coaching Yard, Shunting staff failed to ensure correct setting of Points while allowing forward shunt movement. This has resulted in Trail through of Points. Further without noticing the Trail through of Points, reverse movement allowed on same point resulted in Derailment of Coaching Stock.

All the above incidents clearly establish gross negligence, lack of concentration, poor situational awareness and casual approach towards train operations on the part of on-duty Station Masters & Shunting Staff.

Hence, the following instructions are reiterated.

- All TIs, SMRs and Station In-charges shall immediately conduct intensive and documented counselling sessions for all Operating Staff under their control, with special emphasis on:
 - Correct operation of Signals
 - Route setting and verification
 - LSS/LCPR working
 - Observance of schedule halts
 - Correct setting of Points during Shunting
 - Ensuring the points while allowing forward shunting movements.
 - Stabling precautions.
 - Strict compliance with G& SR, SWR and Safety circulars
- Zero tolerance shall be exercised towards negligence in train operations.
- **It is once again reiterated that any unusual incident occurring due to negligence or violation of rules by Operating Staff will invite very severe disciplinary action, including major penalty proceedings without any leniency.**

Supervisors will also be held accountable for failure to ensure proper counselling and monitoring of staff.

This circular shall be explained and acknowledged by all Operating Staff, compliance shall be ensured in TRUE SPIRIT. **Strict compliance is mandatory.**


MITHUN RAJA YADAV B
DOM/Gen/SC