

SOUTH CENTRAL RAILWAY



Office of the
Divisional Railway Manager/Safety
Fourth Floor, Sanchalan Bhavan
SECUNDERABAD
E-mail: srdsosecunderabad@gmail.com
Mob No.9701371750

No. C/SFY-5/SD-38/September-2/2025

Date 05.09.2025

SAFETY DRIVE SEPTEMBER - 2/2025

Sub: Rly. Board's Safety Calendar Drive for the month of September' 2025.

Ref: 1.Rly. Board Lr. No.2025/Safety(Imp)/3/Safety Calendar dt 13.03.25

2.PCSO/SCR Ltr No.safety.387/safety Drive/RB Vol.XIII dt 04.09.25

Railway Board vide letter cited under reference, advised that a Safety drive for one week period starting from **08.09.2025 to 14.09.2025** to be conducted on the following aspects for the month of SEPTEMBER'25.


ELECTRICAL	TRD: Drive for cantilever assembly such as rusted/damaged fittings, tubes, Height and stagger of contact and catenary wire etc. TRACTION: ESMON working drive CREW: Abnormalities pending in section and noted by crew drive
MECHANICAL	• Fitment of side frame key, shackle lock, centre pivot washer in wagons CBC Including APMs, Knuckle, lock lifter assembly, knuckle pin, anti rotation lug, coupler heads etc. • Also to check the availability and quality of secondary locking pin in coaching CBC, where required to be provided. • Shim heights in coaching couplers. • Operating handle including bends, wear of bolts, corrosion in brackets, • groove in bore of bracket, supporting device including springs • Gauges for checking of CBC including their calibration • Side buffers for drooping, condition of bolts, cracks in casting. Also to check the availability and quality of tertiary locking pin in coaching CBC, where required to be provided. • Maintenance of draft gear in workshops including loose bolts, external damage, seating in pocket, condition of buff plate and application of grease, pre-load value, condition of spring column.
S&T	• To check and ensure whether all axle counters used for BPAC working are functional, their resetting unit is also in working order and proper procedure is being followed by ASM/SM for resetting of BPAC after its failure. • Obstruction test on all Points as per SEM

OPERATING	• Observance of Rules during abnormal working. • Proper filling of paper line clear ticket/form • Proper message has been exchanged between Station Master and Loco Pilot / Guard. • Proper filling of forms to operate the train during Total Failure of Communication (TFC)
ENGINEERING	• Drive of checking of USFD Testing including ADEN/Sr.DEN

After completion of the drive, a consolidate report from each branch item wise checks, deficiencies noticed and no of staff counselled to be **submitted to this office by 15.09.2025 as per the Annexure-A, B & C** for appraising to DRM and PCSO office.

Encl: Annexure-A, B & C

Note: All BOs are requested to ensure that details of deficiencies noticed and its attention particulars with photos to be submitted both hard & soft copy for appraising to PCSO office as advised.


[A SURESH]
Sr. DSO/SC

Copy: DRM/SC for kind information.
ADRM/O & ADRM/I for kind information.
Sr DEN/Co, Sr DEN/N,W&S, Sr DME/Co, Sr CDO/SC &HYB, Sr DEE/M,
Sr DOM, Sr DSTE, Sr DEE/TRSO, Sr DEE/TrD, Sr DEE/ELS/LGD, Sr DEE/
ELS/KZJ, Sr DME/DLS/KZJ & all DENs for information and necessary
action pl.

Format for the week long safety drive for the month of September'25
(08.09.2025 to 14.09.2025)

Annexure - A

Week long safety drive for the Month of September'25

S No.	Dept	Elec (TRD+ TRSO+ TRS)	Mech	S&T	Optg	Engg	Total
1	No. of inspections done by officers						
2	No. of inspections done by supervisors						
3	Total No. of inspections done.						
4	Total No. of Checks conducted						
5	Total No of staff counseled						
6	No. deficiencies found						
7	Total No. of compliances done.						
8	TDC for balance deficiencies.						

Annexure- B

List of items to be checked during the Safety drive

1. ELECTRICAL

Dept	Observations to be done on	Total No. of checks done	Total No. of staff counseled	Total No. of deficiencies observed	No. of deficiencies attended	Balance	Action taken / (TDC)
TRD	Drive for cantilever assembly such as rusted/damaged fittings, tubes, Height and stagger of contact and catenary wire etc.						
TRACTI ON	ESMON working drive						
Crew	Abnormalities pending in section and noted by crew drive.						
Grand Total							

2. Mechanical:

Observations to be done on	Total No. of checks done	Total No. of staff counseled	Total No. of deficiencies observed	No. of deficiencies attended	Balance	Action taken/ /TDC
Fitment of side frame key, shackle lock, center pivot washer in wagons CBC Including APMs, Knuckle, lock lifter assembly, knuckle pin, anti rotation lug, coupler heads etc.						
check the availability and quality of secondary locking pin in coaching CBC, where required to be provided						
Shim heights in coaching couplers.						
Operating handle including bends, wear of bolts, corrosion in brackets, groove in bore of bracket, supporting device including springs						
Gauges for checking of CBC including their calibration						
Side buffers for drooping, condition of bolts, cracks in casting. Also to check the availability and quality of tertiary locking pin in coaching CBC, where required to be provided						
Maintenance of draft gear in workshops including loose bolts, external damage, seating in pocket, condition of buff plate and application of grease, pre-load value, condition of spring column.						
Grand Total						

3. S & T

Observations to be done on	Total No. of checks done	Total No. of staff counseled	Total No. of deficiencies observed	No. of deficiencies attended	Balance	Action taken/ planned/ TDC
----------------------------	--------------------------	------------------------------	------------------------------------	------------------------------	---------	----------------------------

To check and ensure whether all axle counters used for BPAC working are functional, their resetting unit is also in working order and proper procedure is being followed by ASM/SM for resetting of BPAC after its failure						
Obstruction test on all Points as per SEM						
Grand Total						

4. Operating

Observations to be done on	Total No. of checks done	Total No. of staff counseled	Total No. of deficiencies observed	No. of deficiencies attended	Balance	Action taken / planned /TDC
Observance of Rules during abnormal working.						
Proper filling of paper line clear ticket/form						
Proper message has been exchanged between Station Master and Loco Pilot / Guard						
Proper filling of forms to operate the train during Total Failure of Communication (TFC)						
Grand Total						

5. Engineering:

Observations to be done on	Total No. of checks done	Total No. of staff counseled	Total No. of deficiencies observed	No. of deficiencies attended	Balance	Action taken / planned /TDC
Drive of checking of USFD Testing including ADEN/ Sr.DEN						
Grand Total						

Annexure-C

- 1) Details of depart-wise major deficiencies noticed and attended are as mentioned below (important photograph should be attached / included in report):
- 2) Details of depart-wise major deficiencies noticed and yet to be attended with TDC are as mentioned below (important photograph should be attached / included in report):

S. S. 27
Sr.DSO/SC