

Home Again Emergency Services & Restoration Inc. 550 State Road Suite 114A
Bensalem PA 19020
215-888-1488

Client: Lucia Kamara
Property: 179 Blackburn Ave

Lansdowne, PA 19050

Operator: TRISTATE

Estimator: S. Bryant Business: (215) 758-1967

Company: Home Again Emergency Services & Restoration Inc

Business: 550 State Road Suite 114A

Bensalem, PA 19020

Type of Estimate: Other

Date Entered: 2/28/2021 Date Assigned:

Price List: PAWC8X_JAN21


Labor Efficiency: Restoration/Service/Remodel

Estimate: KAMARA-ES File Number: 3815M580N



Home Again Emergency Services & Restoration Inc. 550 State Road Suite 114A
Bensalem PA 19020
215-888-1488

KAMARA-ES Main Level



Living Room


Height: 8'

384.00 SF Walls 528.00 SF Walls & Ceiling 16.00 SY Flooring 48.00 LF Ceil. Perimeter

144.00 SF Floor48.00 LF Floor Perimeter

144.00 SF Ceiling

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
Content Manipulation charge - per hour	2.00 HR	0.00	43.22	0.00	86.44
2. Protect contents - Cover with plastic	200.00 SF	0.00	0.19	0.72	38.72
3. Tear out baseboard and bag for disposal - up to Cat 3	12.00 LF	0.88	0.00	0.13	10.69
4. Tear out wet plaster, cleanup, bag for disposal	64.00 SF	2.06	0.00	0.77	132.61
5. Lift carpet for drying	75.00 SF	0.00	0.36	1.62	28.62
6. Tear out wet carpet pad and bag for disposal	50.00 SF	0.52	0.00	0.18	26.18
7. Apply plant-based anti-microbial agent to the surface area	140.00 SF	0.00	0.27	2.71	40.51
8. Air mover axial fan (per 24 hour period) - No monitoring	6.00 EA	0.00	29.84	10.74	189.78
2 for 3 days					
9. Cleaning Technician - incl. cleaning agent - per hour	2.00 HR	0.00	40.37	4.99	85.73
post cleaning					
Totals: Living Room				21.86	639.28



Dining Room

Height: 8'

384.00 SF Walls 528.00 SF Walls & Ceiling 16.00 SY Flooring 48.00 LF Ceil. Perimeter

144.00 SF Floor48.00 LF Floor Perimeter

144.00 SF Ceiling


DESCRIPTION QTY REMOVE REPLACE TAX TOTAL



Home Again Emergency Services & Restoration Inc. 550 State Road Suite 114A
Bensalem PA 19020
215-888-1488

CONTINUED - Dining Room

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
10. Content Manipulation charge - per hour	2.00 HR	0.00	43.22	0.00	86.44
11. Protect contents - Cover with plastic	200.00 SF	0.00	0.19	0.72	38.72
12. Tear out baseboard and bag for disposal - up to Cat 3	10.00 LF	0.88	0.00	0.11	8.91
13. Tear out wet plaster, cleanup, bag for disposal	32.00 SF	2.06	0.00	0.38	66.30
14. Lift carpet for drying	75.00 SF	0.00	0.36	1.62	28.62
15. Tear out wet carpet pad and bag for disposal	50.00 SF	0.52	0.00	0.18	26.18
16. Apply plant-based anti-microbial agent to the surface area	140.00 SF	0.00	0.27	2.71	40.51
17. Dehumidifier (per 24 hour period) - Large - No monitoring	3.00 EA	0.00	72.50	13.05	230.55
1 for 3 day					
18. Air mover axial fan (per 24 hour period) - No monitoring	6.00 EA	0.00	29.84	10.74	189.78
2 for 3 days					
19. Cleaning Technician - incl. cleaning agent - per hour	2.00 HR	0.00	40.37	4.99	85.73
post cleaning					
Totals: Dining Room				34.50	801.74



Basement Height: 8'

384.00 SF Walls 528.00 SF Walls & Ceiling 16.00 SY Flooring 48.00 LF Ceil. Perimeter

144.00 SF Floor 48.00 LF Floor Perimeter

144.00 SF Ceiling

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
20. Content Manipulation charge - per hour	1.50 HR	0.00	43.22	0.00	64.83
21. Protect contents - Cover with plastic	200.00 SF	0.00	0.19	0.72	38.72
22. Tear out wet plaster, cleanup, bag for disposal	32.00 SF	2.06	0.00	0.38	66.30
23. Apply plant-based anti-microbial agent to the surface area	90.00 SF	0.00	0.27	1.74	26.04
AMARA-ES				3/10/2021	Page: 3



Home Again Emergency Services & Restoration Inc. 550 State Road Suite 114A
Bensalem PA 19020
215-888-1488

CONTINUED - Basement

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
24. Dehumidifier (per 24 hour period) - Large - No monitoring	3.00 EA	0.00	72.50	13.05	230.55
1 for 3 day					
25. Air mover axial fan (per 24 hour period) - No monitoring	6.00 EA	0.00	29.84	10.74	189.78
2 for 3 days					
26. Cleaning Technician - incl. cleaning agent - per hour	1.00 HR	0.00	40.37	2.50	42.87
post cleaning					
Totals: Basement				29.13	659.09
Total: Main Level				85.49	2,100.11

General

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
27. Emergency service call - during business hours	1.00 EA	0.00	160.96	9.66	170.62
28. Haul debris - per pickup truck load - including dump fees	1.00 EA	153.74	0.00	0.00	153.74
29. Equipment setup, take down, and monitoring (hourly charge)	3.00 HR	0.00	55.62	10.01	176.87
30. Equipment decontamination charge - per piece of equipment	8.00 EA	0.00	32.84	18.32	281.04
31. Add for personal protective equipment (hazardous cleanup)	5.00 EA	0.00	13.43	8.30	75.45
Pandemic PPE					
Totals: General				46.29	857.72
Line Item Totals: KAMARA-ES				131.78	2,957.83



Home Again Emergency Services & Restoration Inc. 550 State Road Suite 114A
Bensalem PA 19020
215-888-1488

Grand Total Areas:

SF Walls	432.00	SF Ceiling	1,584.00	SF Walls and Ceiling
SF Floor	48.00	SY Flooring	144.00	LF Floor Perimeter
SF Long Wall	0.00	SF Short Wall	144.00	LF Ceil. Perimeter
Floor Area	481.33	Total Area	1,152.00	Interior Wall Area
Exterior Wall Area	152.00	Exterior Perimeter of		
		Walls		
~ .				
Surface Area	0.00	Number of Squares	0.00	Total Perimeter Length
Total Ridge Length	0.00	Total Hip Length		
	SF Walls SF Floor SF Long Wall Floor Area Exterior Wall Area Surface Area Total Ridge Length	SF Floor 48.00 SF Long Wall 0.00 Floor Area 481.33 Exterior Wall Area 152.00 Surface Area 0.00	SF Floor SF Long Wall O.00 SF Short Wall Floor Area Exterior Wall Area Exterior Wall Area O.00 Number of Squares	SF Floor 48.00 SY Flooring 144.00 SF Long Wall 0.00 SF Short Wall 144.00 Floor Area 481.33 Total Area 1,152.00 Exterior Wall Area 152.00 Exterior Perimeter of Walls Surface Area 0.00 Number of Squares 0.00



Home Again Emergency Services & Restoration Inc. 550 State Road Suite 114A
Bensalem PA 19020
215-888-1488

Summary

Line Item Total	2,826.05
Material Sales Tax	4.29
Cleaning Mtl Tax	7.90
Subtotal	2,838.24
Cleaning Sales Tax	119.59
Replacement Cost Value	\$2,957.83
Net Claim	\$2,957.83

S. Bryant



Home Again Emergency Services & Restoration Inc. 550 State Road Suite 114A
Bensalem PA 19020
215-888-1488

Recap of Taxes

Ma	nterial Sales Tax (6%)	Cleaning Mtl Tax (6%)	Cleaning Sales Tax (6%)	Clothing Acc Tax (6%)	Manuf. Home Tax (6%)	Storage Rental Tax (6%)	Dryclean/Laundry Tax (6%)
Line Items							
	4.29	7.90	119.59	0.00	0.00	0.00	0.00
Total							
	4.29	7.90	119.59	0.00	0.00	0.00	0.00



Home Again Emergency Services & Restoration Inc. 550 State Road Suite 114A
Bensalem PA 19020
215-888-1488

Recap by Room

Estimate: KAMARA-ES


Area: Main Level		
Living Room	617.42	21.85%
Dining Room	767.24	27.15%
Basement	629.96	22.29%
Area Subtotal: Main Level	2,014.62	71.29%
General	811.43	28.71%
Subtotal of Areas	2,826.05	100.00%
Total	2,826.05	100.00%





Home Again Emergency Services & Restoration Inc. 550 State Road Suite 114A
Bensalem PA 19020
215-888-1488

Recap by Category

Items	Total	%
CLEANING	201.85	6.82%
CONTENT MANIPULATION	351.71	11.89%
GENERAL DEMOLITION	488.78	16.52%
HAZARDOUS MATERIAL REMEDIATION	67.15	2.27%
WATER EXTRACTION & REMEDIATION	1,716.56	58.03%
Subtotal	2,826.05	95.54%
Material Sales Tax	4.29	0.15%
Cleaning Mtl Tax	7.90	0.27%
Cleaning Sales Tax	119.59	4.04%
Total	2,957.83	100.00%









Main Level