

## MDL RESTORATION MDL Restoration Inc

606 WM Leigh Drive Tullytown PA 19007 215-943-3382

Client: Jocelyn & Michael Rivells Home: (410) 258-4717

Property: 12 Greenway Circle

Fairless Hills, PA 19030

Operator: TRISTATE

(215) 943-3382 Estimator: Gary Poltonowicz **Business:** 

Company: MDL Restoration Inc E-mail: Gary@mdlrestorationinc.com

**Business:** 606 WM Leigh Drive

Tullytown, PA 19007

Type of Estimate: Fire

> Date Entered: 8/11/2021 Date Assigned:

Price List: PAPH8X\_AUG21

Labor Efficiency: Restoration/Service/Remodel

> Estimate: RIVELLS-REBUILD

A00003519321 File Number:



**Left Side Patio** 

### RIVELLS-REBUILD

### **Main Level**



96.00 SF Walls 238.00 SF Walls & Ceiling 15.78 SY Flooring

142.00 SF Ceiling142.00 SF Floor12.00 LF Floor Perimeter

Height: 8'

Missing Wall

11' 10" X 8'

Opens into Exterior

Missing Wall

12' X 8'

Opens into Exterior

Missing Wall

11' 10" X 8'

Opens into RIGHT\_SIDE\_P

12.00 LF Ceil. Perimeter

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	O&P	TOTAL
Content Manipulation charge - per hour	1.00 HR	0.00	46.80	0.00	9.36	56.16
2. General Demolition - per hour	1.50 HR	53.40	0.00	0.00	16.02	96.12
Hand scraping bulk of burnt debris off	of concrete					
3. Floor protection - cardboard and tape	48.00 SF	0.54	0.00	0.69	5.32	31.93
Protect face of house						
4. Soda blasting - Heavy	25.00 SF	0.00	2.96	6.73	15.06	95.79
5. Soda blasting	117.00 SF	0.00	2.40	25.41	57.12	363.33
6. General clean - up	2.00 HR	0.00	44.52	6.41	17.80	113.25
Soda Cleanup						
7. Concrete grinding	142.00 SF	0.00	2.67	0.00	75.82	454.96
8. Add for sandblasted finish	142.00 SF	0.00	1.09	2.56	31.48	188.82
9. Epoxy finish - two coats over concrete floor - non-slip	142.00 SF	0.00	3.52	5.11	100.98	605.93
10. Final cleaning - construction - Residential	142.00 SF	0.00	0.28	2.87	7.96	50.59
Totals: Left Side Patio				49.78	336.92	2,056.88



### MDL RESTORATION MDL Restoration Inc

606 WM Leigh Drive Tullytown PA 19007 215-943-3382

 9' 10" —	
Right Side Patio	

**Right Side Patio** 

Height: 8'

78.67 SF Walls 195.03 SF Walls & Ceiling 12.93 SY Flooring 9.83 LF Ceil. Perimeter

116.36 SF Ceiling 116.36 SF Floor 9.83 LF Floor Perimeter

**Missing Wall Missing Wall Missing Wall**  11' 10" X 8' 11' 10" X 8' 9' 10" X 8'

Opens into LEFT\_SIDE\_PA **Opens into Exterior Opens into Exterior** 

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	O&P	TOTAL
11. Content Manipulation charge - per hour	1.00 HR	0.00	46.80	0.00	9.36	56.16
12. Floor protection - cardboard and tape	39.33 SF	0.54	0.00	0.57	4.36	26.17
Protect face of house						
13. Soda blasting	116.36 SF	0.00	2.40	25.27	56.82	361.35
14. General clean - up	2.00 HR	0.00	44.52	6.41	17.80	113.25
Soda Cleanup						
15. Concrete grinding	116.36 SF	0.00	2.67	0.00	62.14	372.82
16. Add for sandblasted finish	116.36 SF	0.00	1.09	2.09	25.78	154.70
17. Epoxy finish - two coats over concrete floor - non-slip	116.36 SF	0.00	3.52	4.19	82.76	496.54
18. Final cleaning - construction - Residential	116.36 SF	0.00	0.28	2.34	6.52	41.44
Totals: Right Side Patio				40.87	265.54	1,622.43
Total: Main Level				90.65	602.46	3,679.31

### General

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	O&P	TOTAL
19. Haul debris - per pickup truck load - including dump fees	1.00 EA	187.65	0.00	0.00	37.54	225.19
20. Taxes, insurance, permits & fees (Bid Item)	1.00 EA	0.00	0.00	0.00	0.00	0.00
If permits are needed will bill as incurred.						
21. Lead Paint Safety (Bid Item)	1.00 EA	0.00	0.00	0.00	0.00	0.00
Totals: General				0.00	37.54	225.19

RIVELLS-REBUILD Page: 3 8/11/2021



Line Item Totals: RIVELLS-REBUILD 90.65 640.00 3,904.50

### **Grand Total Areas:**

iiu I Uta	ii Ai cas.				
174.67	SF Walls	258.36	SF Ceiling	433.03	SF Walls and Ceiling
258.36	SF Floor	28.71	SY Flooring	21.83	LF Floor Perimeter
0.00	SF Long Wall	0.00	SF Short Wall	21.83	LF Ceil. Perimeter
258.36	Floor Area	265.64	Total Area	174.67	Interior Wall Area
242.00	Exterior Wall Area	67.33	Exterior Perimeter of		
			Walls		
0.00		0.00		0.00	T. 15
0.00	Surface Area	0.00	Number of Squares	0.00	Total Perimeter Length
0.00	Total Ridge Length	0.00	Total Hip Length		



### **Summary**

Line Item Total	3,173.85
Material Sales Tax	15.21
Cleaning Mtl Tax	10.97
Subtotal	3,200.03
Overhead	320.00
Profit	320.00
Cleaning Sales Tax	64.47
Replacement Cost Value	\$3,904.50
Net Claim	\$3,904.50

Gary Poltonowicz

Page: 5 RIVELLS-REBUILD 8/11/2021

# MDL Restoration Inc



606 WM Leigh Drive Tullytown PA 19007 215-943-3382

### Recap of Taxes, Overhead and Profit

	Overhead (10%)	<b>Profit</b> (10%)	Material Sales Tax (6%)	Cleaning Mtl Tax (6%)	Cleaning Sales Tax (6%)	Clothing Acc Tax (6%)	Manuf. Home Tax (6%)	U	Dryclean/Laun dry Tax (6%)
Line I	tems								
	320.00	320.00	15.21	10.97	64.47	0.00	0.00	0.00	0.00
Total									
	320.00	320.00	15.21	10.97	64.47	0.00	0.00	0.00	0.00



### **Recap by Room**

**Estimate: RIVELLS-REBUILD** 

Area: Main Level Left Side Patio Right Side Patio	1,670.18 1,316.02	52.62% 41.46%
Area Subtotal: Main Level General	2,986.20 187.65	94.09% 5.91%
Subtotal of Areas	3,173.85	100.00%
Total	3,173.85	100.00%



### **Recap by Category**

O&P Items	Total	%
CLEANING	884.48	22.65%
CONCRETE & ASPHALT	971.43	24.88%
CONTENT MANIPULATION	93.60	2.40%
GENERAL DEMOLITION	314.91	8.07%
PAINTING	909.43	23.29%
O&P Items Subtotal	3,173.85	81.29%
Material Sales Tax	15.21	0.39%
Cleaning Mtl Tax	10.97	0.28%
Overhead	320.00	8.20%
Profit	320.00	8.20%
Cleaning Sales Tax	64.47	1.65%
Total	3,904.50	100.00%

RIVELLS-REBUILD Page: 8 8/11/2021





1-Address Date Taken: 8/10/2021





2-Deck (1) Date Taken: 8/10/2021 2

RIVELLS-REBUILD Page: 10 8/11/2021





3-Deck (2) Date Taken: 8/10/2021

RIVELLS-REBUILD Page: 11 8/11/2021





RIVELLS-REBUILD Page: 12 8/11/2021





5-Deck (4) Date Taken: 8/10/2021

RIVELLS-REBUILD Page: 13 8/11/2021





6-Deck (5) Date Taken: 8/10/2021





7-Deck (6) Date Taken: 8/10/2021

RIVELLS-REBUILD Page: 15 8/11/2021






8-Deck (7) Date Taken: 8/10/2021

RIVELLS-REBUILD Page: 16 8/11/2021





9-Deck (8) Date Taken: 8/10/2021

RIVELLS-REBUILD Page: 17 8/11/2021






10-Deck (9) 10 Date Taken: 8/10/2021

RIVELLS-REBUILD Page: 18 8/11/2021






Date Taken: 8/10/2021 11 11-Deck (10)

RIVELLS-REBUILD Page: 19 8/11/2021






12-Deck (11) 12 Date Taken: 8/10/2021

RIVELLS-REBUILD Page: 20 8/11/2021





13-Deck (12) 13 Date Taken: 8/10/2021

RIVELLS-REBUILD Page: 21 8/11/2021





14-Deck (13) Date Taken: 8/10/2021 14


RIVELLS-REBUILD Page: 22 8/11/2021





15-Deck (14) Date Taken: 8/10/2021 15






16-Deck (15) Date Taken: 8/10/2021 16

RIVELLS-REBUILD Page: 24 8/11/2021

# MDL Restoration Inc



606 WM Leigh Drive Tullytown PA 19007 215-943-3382



17-Deck (16) Date Taken: 8/10/2021 17






18-Deck (17) 18 Date Taken: 8/10/2021

# MDL Restoration Inc




606 WM Leigh Drive Tullytown PA 19007 215-943-3382



Date Taken: 8/10/2021 19 19-Deck (18)

RIVELLS-REBUILD Page: 27 8/11/2021





20-Deck (19) Date Taken: 8/10/2021 20

RIVELLS-REBUILD Page: 28 8/11/2021





21-Deck (20) Date Taken: 8/10/2021 21





22-Deck (21) Date Taken: 8/10/2021 22

RIVELLS-REBUILD Page: 30 8/11/2021





23-Deck (22) Date Taken: 8/10/2021 23

RIVELLS-REBUILD Page: 31 8/11/2021





24-Deck (23) Date Taken: 8/10/2021





25-Deck (24) Date Taken: 8/10/2021 25

# MDL RESTORATION MDL Restoration Inc



606 WM Leigh Drive Tullytown PA 19007 215-943-3382




26-Deck (25) 26 Date Taken: 8/10/2021

# MDL RESTORATION MDL Restoration Inc



606 WM Leigh Drive Tullytown PA 19007 215-943-3382




27-Deck (26) 27 Date Taken: 8/10/2021









29-Deck (28) Date Taken: 8/10/2021 29

# MDL Restoration Inc



606 WM Leigh Drive Tullytown PA 19007 215-943-3382




30-Deck (29) Date Taken: 8/10/2021 30





31-Deck (30) Date Taken: 8/10/2021 31






32-Deck (31) 32 Date Taken: 8/10/2021

# MDL RESTORATION MDL Restoration Inc



606 WM Leigh Drive Tullytown PA 19007 215-943-3382



33 33-Front of House Date Taken: 8/10/2021

