36 Merry Turn Road Levittown PA 19056 267-609-4279 TriStatePropertyClaims@gmail.com

Client: Isik Mehmet Home: (267) 784-2161

Property: 526 S Olds Blvd

Fairless Hills, PA 19030

Operator: TRISTATE

Estimator: Gary Poltonowicz Business: (267) 609-4279

Company: Tri-State Property Claims Business: 36 Merry Turn Road

Levittown, PA 19056

Type of Estimate: Water Damage

Date Entered: 7/23/2021 Date Assigned:


Price List: PAPH8X_JUL21

Labor Efficiency: Restoration/Service/Remodel

Estimate: ISIK-REBUILD-1 File Number: 7003105989

36 Merry Turn Road Levittown PA 19056 267-609-4279 TriStatePropertyClaims@gmail.com

ISIK-REBUILD-1 Main Level



Door

Office

214.33 SF Walls
270.92 SF Walls & Ceiling
6.29 SY Flooring

30.17 LF Ceil. Perimeter

56.58 SF Ceiling56.58 SF Floor27.67 LF Floor Perimeter

Height: 8'

2' 7" X 4' 2' 6" X 6' 8" Opens into Exterior
Opens into ENTRY_FOYER

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1. Contents - move out then reset	1.00 EA		0.00	68.69	0.00	13.74	82.43
2. Detach & Reset Interior door - Colonist - slab only	1.00 EA	21.16	0.00	0.00	0.00	4.24	25.40
3. Window blind - horizontal or vertical - Detach & reset	1.00 EA		0.00	39.26	0.00	7.86	47.12
4. Window drapery - remove and rehang - per hour	0.50 HR		0.00	65.91	0.00	6.60	39.56
5. 1/2" drywall - hung, taped, floated, ready for paint	121.25 SF		0.00	2.95	4.22	72.38	434.29
6. Additional cost for gluing drywall	121.25 SF		0.00	0.35	0.36	8.56	51.36
7. Batt insulation - 6" - R21 - paper / foil faced	56.58 SF		0.00	1.46	3.36	17.20	103.17
8. Remove Baseboard - 3 1/4"	13.83 LF		0.54	0.00	0.00	1.50	8.97
9. Baseboard - 3 1/4"	27.67 LF		0.00	3.30	2.34	18.72	112.37
10. Quarter round - 3/4"	27.67 LF		0.00	1.56	1.18	8.88	53.23
11. Remove Vinyl floor covering (sheet goods)	56.58 SF		1.09	0.00	0.00	12.34	74.01
12. Floor preparation for resilient flooring	56.58 SF		0.00	0.69	0.34	7.86	47.24
13. Snaplock Laminate - simulated wood flooring - High grade	56.58 SF		0.00	7.87	16.97	92.46	554.71
14. Vapor barrier - visqueen - 6mil	56.58 SF		0.00	0.32	0.17	3.66	21.94
15. R&R End molding - for wood flooring	2.50 LF		0.45	6.40	0.84	3.58	21.55
16. Light fixture	1.00 EA		0.00	81.58	2.16	16.76	100.50
17. Mask the floor per square foot - plastic and tape - 4 mil	56.58 SF		0.00	0.22	0.17	2.54	15.16
18. Seal/prime then paint the walls and ceiling twice (3 coats)	270.92 SF		0.00	1.18	4.39	64.82	388.90

36 Merry Turn Road Levittown PA 19056 267-609-4279 TriStatePropertyClaims@gmail.com

Coat Closet

CONTINUED - Office

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
19. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	17.34	0.00	3.46	20.80
20. Prime & paint heat register	1.00 EA		0.00	17.28	0.13	3.48	20.89
21. Seal & paint door or window opening (per side)	2.00 EA		0.00	28.48	0.55	11.52	69.03
22. Seal & paint window sill	3.00 LF		0.00	2.32	0.04	1.40	8.40
23. Seal & paint baseboard - two coats	27.67 LF		0.00	1.35	0.18	7.52	45.05
24. Seal & paint base shoe or quarter round	27.67 LF		0.00	0.73	0.17	4.08	24.45
25. Seal & paint door slab only (per side)	1.00 EA		0.00	34.28	0.46	6.96	41.70
26. Final cleaning - construction - Residential	56.58 SF		0.00	0.28	1.14	3.16	20.14
Totals: Office					39.17	405.28	2,432.37

Coat Closety

The state of the

122.00 SF Walls 140.72 SF Walls & Ceiling 2.08 SY Flooring

17.33 LF Ceil. Perimeter

Height: 8'

18.72 SF Floor

14.83 LF Floor Perimeter

Door 2' 6" X 6' 8"	Opens into ENTRY_FOYER
--------------------	-------------------------------

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
27. Content Manipulation charge - per hour	2.00 HR		0.00	46.80	0.00	18.72	112.32
28. Provide box, packing paper & tape - medium size	4.00 EA		0.00	3.90	2.01	3.28	20.89
29. Detach & Reset Interior door - Colonist - slab only	1.00 EA	21.16	0.00	0.00	0.00	4.24	25.40
30. Detach & Reset Closet shelf and rod package	8.08 LF	10.33	0.00	0.00	0.00	16.70	100.17
31. Detach & Reset Shelving - wire (vinyl coated)	28.00 LF	8.96	0.00	0.00	0.00	50.18	301.06
32. 1/2" drywall - hung, taped, floated, ready for paint	18.72 SF		0.00	2.95	0.65	11.18	67.05
33. Additional cost for gluing drywall	18.72 SF		0.00	0.35	0.06	1.34	7.95
34. Batt insulation - 6" - R21 - paper / foil faced	18.72 SF		0.00	1.46	1.11	5.68	34.12
35. R&R Quarter round - 3/4"	14.83 LF		0.20	1.56	0.63	5.34	32.07
SIK-REBUILD-1					7/26	/2021	Page: 3

36 Merry Turn Road Levittown PA 19056 267-609-4279 TriStatePropertyClaims@gmail.com

CONTINUED - Coat Closet

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
36. R&R Snaplock Laminate - simulated wood flooring - High grade	18.72 SF		1.38	7.87	5.62	35.74	214.52
37. R&R Vapor barrier - visqueen - 6mil	18.72 SF		0.10	0.32	0.06	1.60	9.52
38. R&R End molding - for wood flooring	2.50 LF		0.45	6.40	0.84	3.58	21.55
39. R&R Porcelain light fixture	1.00 EA		9.82	35.50	0.33	9.12	54.77
40. Mask the floor per square foot - plastic and tape - 4 mil	18.72 SF		0.00	0.22	0.06	0.84	5.02
41. Seal/prime then paint the walls and ceiling twice (3 coats)	140.72 SF		0.00	1.18	2.28	33.68	202.01
42. Seal & paint door or window opening (per side)	1.00 EA		0.00	28.48	0.27	5.76	34.51
43. Seal & paint baseboard - two coats	14.83 LF		0.00	1.35	0.10	4.02	24.14
44. Seal & paint base shoe or quarter round	14.83 LF		0.00	0.73	0.09	2.18	13.10
45. Seal & paint door slab only (per side)	1.00 EA		0.00	34.28	0.46	6.96	41.70
46. Seal & paint closet shelving - single shelf	1.00 EA		0.00	46.61	0.24	9.36	56.21
47. Final cleaning - construction - Residential	18.72 SF		0.00	0.28	0.37	1.04	6.65
Totals: Coat Closet					15.18	230.54	1,384.73

ffice Coat Close 4' - 3' 9" - 1 12' 6" 11-3' - 3' - 8"	Entry/Foyer	Height: 8'
Entrateboxes & 4	196.44 SF Walls	73.11 SF Ceiling
——4'—	269.56 SF Walls & Ceiling	73.11 SF Floor
	8.12 SY Flooring	21.50 LF Floor Perimeter
amily Room To 17 70 70 70 70 70 70 70	39.83 LF Ceil. Perimeter	
Door	2' 6" X 6' 8"	Opens into OFFICE
Door	2' 6" X 6' 8"	Opens into COAT_CLOSET
Door	3' X 6' 8''	Opens into Exterior
Door	3' X 6' 8''	Opens into Exterior
Missing Wall - Goes to Floor	4' 5" X 6' 8"	Opens into Exterior
Missing Wall - Goes to Floor	2' 11" X 6' 8"	Opens into Exterior
Missing Wall	3' 2" X 8'	Opens into Exterior
Missing Wall	4' X 8'	Opens into FAMILY_ROOM

36 Merry Turn Road Levittown PA 19056 267-609-4279 TriStatePropertyClaims@gmail.com

CONTINUED - Entry/Foyer

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
48. Contents - move out then reset - Small room	1.00 EA		0.00	51.56	0.00	10.32	61.88
49. 1/2" drywall - hung, taped, floated, ready for paint	12.33 SF		0.00	2.95	0.43	7.36	44.16
50. Additional cost for gluing drywall	12.33 SF		0.00	0.35	0.04	0.86	5.22
51. Crown molding - 4 1/4"	10.17 LF		0.00	5.10	1.44	10.66	63.97
52. Mask the floor per square foot - plastic and tape - 4 mil	73.11 SF		0.00	0.22	0.22	3.26	19.56
53. Detach & Reset Light fixture	1.00 EA	64.23	0.00	0.00	0.00	12.84	77.07
54. Seal/prime then paint the walls and ceiling twice (3 coats)	269.56 SF		0.00	1.18	4.37	64.50	386.95
55. Seal & paint crown molding - two coats	10.17 LF		0.00	1.36	0.08	2.78	16.69
56. Seal & paint door or window opening (per side)	5.00 EA		0.00	28.48	1.37	28.76	172.53
57. Seal & paint baseboard - two coats	21.50 LF		0.00	1.35	0.14	5.82	34.99
58. Seal & paint door slab only (per side)	4.00 EA		0.00	34.28	1.86	27.80	166.78
59. Final cleaning - construction - Residential	73.11 SF		0.00	0.28	1.48	4.10	26.05
Totals: Entry/Foyer					11.43	179.06	1,075.85

7' Entry/Foy	Family Room	Height: 8'
100.	395.56 SF Walls	248.11 SF Ceiling
t Family Room	643.67 SF Walls & Ceiling	248.11 SF Floor
	27.57 SY Flooring	46.83 LF Floor Perimeter
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	62.50 LF Ceil. Perimeter	


Door	2' 6" X 6' 8"	Opens into HALLWAY
Missing Wall	4' X 8'	Opens into ENTRY_FOYER
Missing Wall - Goes to Floor	2' 2" X 6' 8"	Opens into Exterior
Missing Wall - Goes to Floor	5' X 6' 8''	Opens into Exterior
Door	6' X 6' 8''	Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
60. Contents - move out then reset	1.00 EA		0.00	68.69	0.00	13.74	82.43
61. Tape joint for new to existing drywall - per LF	4.00 LF		0.00	10.85	0.08	8.70	52.18

36 Merry Turn Road Levittown PA 19056 267-609-4279 TriStatePropertyClaims@gmail.com

#### **CONTINUED - Family Room**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
62. R&R Crown molding - 4 1/4"	62.50 LF		0.79	5.10	8.85	75.42	452.40
63. Mask the floor per square foot - plastic and tape - 4 mil	248.11 SF		0.00	0.22	0.74	11.06	66.38
64. Detach & Reset Light fixture	1.00 EA	64.23	0.00	0.00	0.00	12.84	77.07
65. Recessed light fixture - Detach & reset trim only	6.00 EA		0.00	3.61	0.00	4.34	26.00
66. Seal/prime then paint the walls and ceiling twice (3 coats)	643.67 SF		0.00	1.18	10.43	153.98	923.94
67. Seal & paint crown molding - two coats	10.17 LF		0.00	1.36	0.08	2.78	16.69
68. Seal & paint door or window opening (per side)	4.00 EA		0.00	28.48	1.10	23.00	138.02
69. Seal & paint baseboard - two coats	46.83 LF		0.00	1.35	0.31	12.70	76.23
70. Seal & paint base shoe or quarter round	46.83 LF		0.00	0.73	0.28	6.90	41.37
71. Seal & paint door slab only (per side)	1.00 EA		0.00	34.28	0.46	6.96	41.70
72. Final cleaning - construction - Residential	248.11 SF		0.00	0.28	5.00	13.90	88.37
Totals: Family Room					27.33	346.32	2,082.78



**TOTAL** 

25.40

136.74

16.17

Page: 6

Door Door	2' 6	'' X 6' 8'' '' X 6' 8''		Opens into BATHROOM Opens into FAMILY_ROOM			
Door DESCRIPTION	2' 6 QTY	" X 6' 8" RESET	REMOVE	Opens into	BEDROOM TAX	O&P	
73. Detach & Reset Interior door - Colonist - slab only	1.00 EA	21.16	0.00	0.00	0.00	4.24	

38.18 SF

38.18 SF

74. 1/2" drywall - hung, taped, floated,

75. Additional cost for gluing drywall

ready for paint

ISIK-REBUILD-1

76. Batt insulation - 6" - R21 - paper /	30.43 SF	0.00	1.46	1.81	9.24	55.48
foil faced						

0.00

0.00

2.95

0.35

1.33

0.11

7/26/2021


22.78

2.70

36 Merry Turn Road Levittown PA 19056 267-609-4279 TriStatePropertyClaims@gmail.com

#### **CONTINUED - Hallway**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
77. Light fixture	1.00 EA		0.00	81.58	2.16	16.76	100.50
78. Mask the floor per square foot - plastic and tape - 4 mil	30.43 SF		0.00	0.22	0.09	1.36	8.14
79. Seal/prime then paint the walls and ceiling twice (3 coats)	189.47 SF		0.00	1.18	3.07	45.34	271.98
80. Seal & paint door or window opening (per side)	3.00 EA		0.00	28.48	0.82	17.24	103.50
81. Seal & paint baseboard - two coats	18.63 LF		0.00	1.35	0.12	5.06	30.33
82. Seal & paint door slab only (per side)	3.00 EA		0.00	34.28	1.39	20.84	125.07
83. Final cleaning - construction - Residential	30.43 SF		0.00	0.28	0.61	1.70	10.83
Totals: Hallway					11.51	147.26	884.14



**Bathroom** Height: 7' 2"

186.49 SF Walls 231.63 SF Walls & Ceiling 5.02 SY Flooring 29.46 LF Ceil. Perimeter

45.15 SF Ceiling 45.15 SF Floor 26.96 LF Floor Perimeter

Window	2' X	2' X 4'		Opens into Exterior				
Door	2' 6	5" X 6' 8"		Opens into HALLWAY				
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL	
84. Contents - move out then reset - Small room	1.00 EA		0.00	51.56	0.00	10.32	61.88	
85. Detach & Reset Interior door - Colonist - slab only	1.00 EA	21.16	0.00	0.00	0.00	4.24	25.40	
86. Window blind - horizontal or vertical - Detach & reset	1.00 EA		0.00	39.26	0.00	7.86	47.12	
87. Window drapery - remove and rehang - per hour	0.25 HR		0.00	65.91	0.00	3.30	19.78	
88. Detach & Reset Window blind - PVC - 3.5" - 7.1 to 14 SF	1.00 EA	39.26	0.00	0.00	0.00	7.86	47.12	
89. R&R Casing - 3 1/4"	32.00 LF		0.59	2.99	3.86	23.70	142.12	
90. Detach & Reset Mirror - 1/4" plate glass	8.00 SF	7.06	0.00	0.00	0.00	11.30	67.78	
91. Vanity - Detach & reset	3.00 LF		0.00	55.25	0.00	33.16	198.91	
92. Detach & Reset Sink faucet - Bathroom	1.00 EA	139.16	0.00	0.00	0.00	27.84	167.00	
SIK-REBUILD-1					7/26	5/2021	Page: 7	

36 Merry Turn Road Levittown PA 19056 267-609-4279 TriStatePropertyClaims@gmail.com

#### **CONTINUED - Bathroom**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
93. Sink - single - Detach & reset	1.00 EA		0.00	173.93	0.02	34.78	208.73
94. P-trap assembly - Detach & reset	1.00 EA		0.00	69.36	0.00	13.88	83.24
95. Toilet - Detach & reset	1.00 EA		0.00	280.96	0.36	56.28	337.60
96. R&R Ceramic/porcelain tile	186.49 SF		2.11	13.77	52.14	602.72	3,616.32
97. R&R Tile - soap dish	2.00 EA		5.89	31.53	1.23	15.22	91.29
98. R&R Tile - towel bar	1.00 EA		5.89	41.00	0.76	9.54	57.19
99. R&R Tile - toilet paper holder	1.00 EA		5.89	34.65	0.80	8.28	49.62
100. Tile/stone sealer	186.49 SF		0.00	1.02	3.47	38.74	232.43
101. Remove 1/2" drywall - hung, taped, floated, ready for paint	186.49 SF		0.49	0.00	0.00	18.28	109.66
102. 1/2" drywall - hung, taped, floated, ready for paint	231.63 SF		0.00	2.95	8.06	138.28	829.65
103. Additional cost for gluing drywall	231.63 SF		0.00	0.35	0.69	16.36	98.12
104. Batt insulation - 6" - R21 - paper / foil faced	45.15 SF		0.00	1.46	2.68	13.72	82.32
105. Light fixture	1.00 EA		0.00	81.58	2.16	16.76	100.50
106. R&R Bathroom ventilation fan	1.00 EA		20.74	103.61	2.98	25.46	152.79
107. Mask the floor per square foot - plastic and tape - 4 mil	45.15 SF		0.00	0.22	0.14	2.00	12.07
108. Seal/prime then paint the walls and ceiling twice (3 coats)	231.63 SF		0.00	1.18	3.75	55.42	332.49
109. Seal & paint door or window opening (per side)	2.00 EA		0.00	28.48	0.55	11.52	69.03
110. Seal & paint window sill	3.00 LF		0.00	2.32	0.04	1.40	8.40
111. Seal & paint door slab only (per side)	1.00 EA		0.00	34.28	0.46	6.96	41.70
112. Final cleaning - construction - Residential	45.15 SF		0.00	0.28	0.91	2.52	16.07
Totals: Bathroom					85.06	1,217.70	7,306.33

36 Merry Turn Road Levittown PA 19056 267-609-4279 TriStatePropertyClaims@gmail.com

**Bedroom** 

<u>4' 1" 3' 11"</u>
3 9" 3' 9"
Of &
5' 10"
15' 10"
Bedroom
<u> </u>
, i light
edro m Closet 2' 6'4' 5' Far
¹ Hallway

454.33 SF Walls

663.47 SF Walls & Ceiling

23.24 SY Flooring

64.33 LF Ceil. Perimeter

Height: 8'

209.13 SF Ceiling 209.13 SF Floor

56.83 LF Floor Perimeter


Window Door Door 2' 7" X 4' 2' 6" X 6' 8" 5' X 6' 8" Opens into Exterior
Opens into HALLWAY
Opens into BEDROOM_CLOS

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
113. Content Manipulation charge - per hour	4.00 HR		0.00	46.80	0.00	37.44	224.64
114. Protect contents - Cover with plastic	300.00 SF		0.00	0.38	1.08	23.02	138.10
115. Window blind - horizontal or vertical - Detach & reset	1.00 EA		0.00	39.26	0.00	7.86	47.12
116. Window drapery - remove and rehang - per hour	1.00 HR		0.00	65.91	0.00	13.18	79.09
117. 1/2" drywall - hung, taped, floated, ready for paint	100.00 SF		0.00	2.95	3.48	59.70	358.18
118. Additional cost for gluing drywall	100.00 SF		0.00	0.35	0.30	7.06	42.36
119. Drywall tape joint/repair - per LF	10.08 LF		0.00	10.03	0.20	20.26	121.56
120. Batt insulation - 6" - R21 - paper / foil faced	100.00 SF		0.00	1.46	5.94	30.38	182.32
121. Light fixture	1.00 EA		0.00	81.58	2.16	16.76	100.50
122. Casing - 3 1/4"	16.00 LF		0.00	2.99	1.93	9.94	59.71
Attic stairs casing							
123. Detach & Reset Interior door - Colonist - slab only	1.00 EA	21.16	0.00	0.00	0.00	4.24	25.40
124. Remove Carpet - High grade	109.13 SF		0.32	0.00	0.00	6.98	41.90
125. Carpet - High grade	240.50 SF		0.00	5.44	64.65	274.60	1,647.57
15 % waste added for Carpet - High grade	<b>.</b> .						
126. Remove Carpet pad	109.13 SF		0.14	0.00	0.00	3.06	18.34
127. Carpet pad	209.13 SF		0.00	0.62	6.15	27.18	162.99
128. Mask the floor per square foot - plastic and tape - 4 mil	209.13 SF		0.00	0.22	0.63	9.32	55.96
129. Seal/prime then paint the walls and ceiling twice (3 coats)	663.47 SF		0.00	1.18	10.75	158.74	952.38
130. Detach & Reset Light fixture	1.00 EA	64.23	0.00	0.00	0.00	12.84	77.07

36 Merry Turn Road Levittown PA 19056 267-609-4279 TriStatePropertyClaims@gmail.com

#### **CONTINUED - Bedroom**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
131. Seal & paint door or window opening (per side)	3.00 EA		0.00	28.48	0.82	17.24	103.50
132. Seal & paint window sill	3.00 LF		0.00	2.32	0.04	1.40	8.40
133. Seal & paint baseboard - two coats	56.83 LF		0.00	1.35	0.38	15.42	92.52
134. Seal & paint door slab only (per side)	1.00 EA		0.00	34.28	0.46	6.96	41.70
135. Seal/Paint bypass door set - slab only- 2 coats (per side)	1.00 EA		0.00	41.47	0.71	8.44	50.62
136. Final cleaning - construction - Residential	209.13 SF		0.00	0.28	4.21	11.72	74.49
Totals: Bedroom					103.89	783.74	4,706.42



#### **Bedroom Closet**

Height: 8'

90.67 SF Walls 101.51 SF Walls & Ceiling 1.21 SY Flooring 15.50 LF Ceil. Perimeter 10.85 SF Ceiling 10.85 SF Floor


g 10.50 LF Floor Perimeter

Door	5' X	5' X 6' 8''		Opens into BEDROOM			
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
137. Content Manipulation charge - per hour	1.50 HR		0.00	46.80	0.00	14.04	84.24
138. Bypass (sliding) door set - slabs only - Detach & reset	1.00 EA		0.00	29.89	0.00	5.98	35.87
139. Remove Carpet - High grade	10.85 SF		0.32	0.00	0.00	0.70	4.17
140. Carpet - High grade	12.47 SF		0.00	5.44	3.35	14.24	85.43
15 % waste added for Carpet - High grad	le.						
141. Remove Carpet pad	10.85 SF		0.14	0.00	0.00	0.30	1.82
142. Carpet pad	10.85 SF		0.00	0.62	0.32	1.40	8.45
143. Mask the floor per square foot - plastic and tape - 4 mil	10.85 SF		0.00	0.22	0.03	0.48	2.90
144. Seal/prime then paint the walls and ceiling twice (3 coats)	101.51 SF		0.00	1.18	1.64	24.28	145.70
145. Seal & paint door or window opening (per side)	1.00 EA		0.00	28.48	0.27	5.76	34.51
146. Seal & paint baseboard - two coats	10.50 LF		0.00	1.35	0.07	2.86	17.11
SIK-REBUILD-1					7/26	5/2021	Page: 1

36 Merry Turn Road Levittown PA 19056 267-609-4279 TriStatePropertyClaims@gmail.com

#### **CONTINUED - Bedroom Closet**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
147. Seal/Paint bypass door set - slab only- 2 coats (per side)	1.00 EA		0.00	41.47	0.71	8.44	50.62
148. Seal & paint closet shelving - single shelf	1.00 EA		0.00	46.61	0.24	9.36	56.21
149. Final cleaning - construction - Residential	10.85 SF		0.00	0.28	0.22	0.60	3.86
Totals: Bedroom Closet					6.85	88.44	530.89



#### 1st to 2nd Floor Stairs

312.41 SF Walls
39.86 SF Ceiling
352.27 SF Walls & Ceiling
70.84 SF Floor
7.87 SY Flooring
27.48 LF Floor Perimeter

Missing Wall 2' 11" X 17' 4 7/16" Opens into Exterior Missing Wall - Goes to Floor 2' 2" X 6' 8" Opens into Exterior Missing Wall 2' 11" X 17' 4 7/16" Opens into Exterior Missing Wall - Goes to Floor 2' 6" X 6' 8" Opens into Exterior

27.33 LF Ceil. Perimeter

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
150. Floor protection - cloth - skid resistant, leak proof	70.84 SF		0.94	0.00	1.49	13.62	81.70
151. Seal/prime then paint the walls twice (3 coats)	312.41 SF		0.00	1.18	5.06	74.74	448.44
152. Final cleaning - construction - Residential	70.84 SF		0.00	0.28	1.43	3.96	25.23
Totals: 1st to 2nd Floor Stairs					7.98	92.32	555.37



Attic

254.17 SF Walls 627.18 SF Walls & Ceiling 38.33 SY Flooring 87.87 LF Ceil. Perimeter Height: Peaked

Height: 17' 4"

345.00 SF Floor 83.00 LF Floor Perimeter

373.02 SF Ceiling

33 SY Flooring 83.00 LF Floor Perimeter

DESCRIPTION QTY RESET REMOVE REPLACE TAX O&P TOTAL

36 Merry Turn Road Levittown PA 19056 267-609-4279 TriStatePropertyClaims@gmail.com

#### **CONTINUED - Attic**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
153. R&R Porcelain light fixture	1.00 EA		9.82	35.50	0.33	9.12	54.77
154. Final cleaning - construction - Residential	345.00 SF		0.00	0.28	6.96	19.32	122.88
Totals: Attic					7.29	28.44	177.65
Total: Main Level					315.69	3,519.10	21,136.53

### Level 2


	er Bedroom					П	eight: 7' 9''	
101 4	509.5	4 SF Walls			230.68 SF C	Ceiling		
faster Bedroom	740.2	2 SF Walls	& Ceiling		230.68 SF F			
14' 5 T		3 SY Floori	•		67.83 LF I	Floor Perime	ter	
MacCales 4 3"1	77.8	3 LF Ceil. P	erimeter					
Door	2' 6	'' X 6' 8''		Opens into	MB_CLOSE	ET		
Window	2' 3	'' X 4'		Opens into	Exterior			
Door	2' 6	'' X 6' 8''		Opens into	Exterior			
Door	2' 6	'' X 6' 8''		Opens into Exterior				
Door	2' 6	'' X 6' 8''		Opens into HALLWAY				
Window	2' 3" X 4'			Opens into	Exterior			
Window	2' 3	2' 3" X 4'			Exterior			
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL	
155. Content Manipulation charge - per hour	4.00 HR		0.00	46.80	0.00	37.44	224.64	
156. Protect contents - Cover with plastic	300.00 SF		0.00	0.38	1.08	23.02	138.10	
157. Window blind - horizontal or vertical - Detach & reset	3.00 EA		0.00	39.26	0.00	23.56	141.34	
158. Window drapery - remove and rehang - per hour	2.00 HR		0.00	65.91	0.00	26.36	158.18	
159. Remove 1/2" drywall - hung, taped, floated, ready for paint	96.00 SF		0.49	0.00	0.00	9.40	56.44	
More has to be removed due to sagging f	rom water loss an	d cutting back	to joists.					
160. 1/2" drywall - hung, taped, floated, ready for paint	132.00 SF		0.00	2.95	4.59	78.80	472.79	
161. Additional cost for gluing drywall	132.00 SF		0.00	0.35	0.40	9.32	55.92	
162. Drywall tape joint/repair - per LF	11.33 LF		0.00	10.03	0.22	22.76	136.62	

36 Merry Turn Road Levittown PA 19056 267-609-4279 TriStatePropertyClaims@gmail.com

#### **CONTINUED - Master Bedroom**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
163. Remove Blown-in insulation - 10" depth - R26	96.00 SF		1.02	0.00	0.00	19.58	117.50
164. Blown-in insulation - 10" depth - R26	132.00 SF		0.00	1.07	5.31	29.30	175.85
165. Detach & Reset Interior door - Colonist - slab only	2.00 EA	21.16	0.00	0.00	0.00	8.46	50.78
166. Remove Carpet - High grade	201.37 SF		0.32	0.00	0.00	12.88	77.32
167. Carpet - High grade	265.28 SF		0.00	5.44	71.31	302.88	1,817.31
15 % waste added for Carpet - High grade	e.						
168. Remove Carpet pad	201.37 SF		0.14	0.00	0.00	5.64	33.83
169. Carpet pad	230.68 SF		0.00	0.62	6.78	29.96	179.76
170. R&R Quarter round - 3/4"	67.83 LF		0.20	1.56	2.89	24.46	146.73
171. Remove Oak flooring - #1 common - no finish	32.00 SF		2.76	0.00	0.00	17.66	105.98
172. Oak flooring - #1 common - no finish	61.31 SF		0.00	9.20	20.97	117.02	702.04
173. Vapor barrier - 15# felt	32.00 SF		0.00	0.29	0.12	1.88	11.28
174. Sand, stain, and finish wood floor	230.68 SF		0.00	4.51	12.73	210.62	1,263.72
175. Add for dustless floor sanding	230.68 SF		0.00	1.00	0.00	46.14	276.82
176. Mask the floor per square foot - plastic and tape - 4 mil	230.68 SF		0.00	0.22	0.69	10.30	61.74
177. Seal/prime then paint the walls and ceiling twice (3 coats)	740.22 SF		0.00	1.18	11.99	177.10	1,062.55
178. Cold air return cover - Detach & reset	1.00 EA		0.00	23.67	0.00	4.74	28.41
179. Prime & paint cold air return (cover)	1.00 EA		0.00	15.46	0.26	3.16	18.88
180. Detach & Reset Light fixture	1.00 EA	64.23	0.00	0.00	0.00	12.84	77.07
181. Seal & paint door or window opening (per side)	8.00 EA		0.00	28.48	2.19	46.00	276.03
182. Seal & paint window sill	9.00 LF		0.00	2.32	0.13	4.20	25.21
183. Seal & paint baseboard - two coats	67.83 LF		0.00	1.35	0.45	18.42	110.44
184. Seal & paint base shoe or quarter round	67.83 LF		0.00	0.73	0.41	9.98	59.91
185. Seal & paint door slab only (per side)	4.00 EA		0.00	34.28	1.86	27.80	166.78
186. Final cleaning - construction - Residential	230.68 SF		0.00	0.28	4.66	12.92	82.17
Totals: Master Bedroom					149.04	1,384.60	8,312.14

36 Merry Turn Road Levittown PA 19056 267-609-4279 TriStatePropertyClaims@gmail.com



Door	2' 6" X 6' 8"			Opens into			
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
187. Contents - move out then reset - Small room	1.00 EA		0.00	51.56	0.00	10.32	61.88
188. Detach & Reset Interior door - Colonist - slab only	1.00 EA	21.16	0.00	0.00	0.00	4.24	25.40
189. R&R Quarter round - 3/4"	8.33 LF		0.20	1.56	0.35	3.02	18.03
190. Sand, stain, and finish wood floor	6.57 SF		0.00	4.51	0.36	6.00	35.99
191. Add for dustless floor sanding	6.57 SF		0.00	1.00	0.00	1.32	7.89
192. Mask the floor per square foot - plastic and tape - 4 mil	6.57 SF		0.00	0.22	0.02	0.30	1.77
193. Seal & paint door or window opening (per side)	1.00 EA		0.00	28.48	0.27	5.76	34.51
194. Seal & paint baseboard - two coats	8.33 LF		0.00	1.35	0.06	2.28	13.59
195. Seal & paint base shoe or quarter round	8.33 LF		0.00	0.73	0.05	1.24	7.37
196. Final cleaning - construction - Residential	6.57 SF		0.00	0.28	0.13	0.36	2.33
Totals: MB Closet					1.24	34.84	208.76

36 Merry Turn Road Levittown PA 19056 267-609-4279 TriStatePropertyClaims@gmail.com

	Hallway					He	eight: 7' 9''			
droom 2'.6"	208.1	208.18 SF Walls				54.58 SF Ceiling				
2'11" 10'10" 2" 2" 5" Hallyay" 5'9"	262.7	6 SF Walls	& Ceiling	54.58 SF Floor						
2'6" 3 7" 2 0 3 3"	6.0	6 SY Floori	ng		25.11 LF F	Floor Perimet	ter			
· ·	37.6	1 LF Ceil. P	erimeter							
Door	2' 6	'' X 6' 8''		Opens into	MASTER_B	EDRO				
Missing Wall	2' 1	1" X 7' 9"		Opens into	Exterior					
Missing Wall	4" 2	4" X 7' 9" 2' 6" X 6' 8" 2' 6" X 6' 8"			Opens into Exterior Opens into FRONT_LEFT_B Opens into Exterior					
Door	2' 6									
Door	2' 6									
Door	2' 6	'' X 6' 8''		Opens into Exterior						
Door	2' 6	'' X 6' 8''		Opens into Exterior						
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL			
197. Floor protection - cloth - skid resistant, leak proof	54.58 SF		0.94	0.00	1.15	10.50	62.96			
198. Final cleaning - construction - Residential	54.58 SF		0.00	0.28	1.10	3.06	19.44			
Totals: Hallway					2.25	13.56	82.40			

8'3" 6'7" = 6'7" = 1	Front Left Bedroom					Не	eight: 7' 9''	
7'11" 6'3"	339.82	2 SF Walls		185.56 SF Ceiling				
Front Left Bedroom	525.38	SF Walls	& Ceiling		185.56 SF F	loor		
Ĩ∥Ĩ 1Ų1	20.62	2 SY Floori	ng		46.17 LF F	loor Perime	ter	
3'5"⊢4'7"→5'10"→	54.50	) LF Ceil. P	erimeter					
4" 21-4'5" - 10"								
Door	2' 6'	' X 6' 8''		Opens into	HALLWAY			
Door	5' 10	)'' X 6' 8''		Opens into	Exterior			
Window	2' 3'	' X 4'		Opens into Exterior				
Window	2' 3'	' X 4'		Opens into Exterior				
Window	2' 3'	' X 4'		Opens into Exterior				
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL	
199. Content Manipulation charge per hour	e- 2.00 HR		0.00	46.80	0.00	18.72	112.32	
200. Protect contents - Cover with plastic	200.00 SF		0.00	0.38	0.72	15.34	92.06	

36 Merry Turn Road Levittown PA 19056 267-609-4279 TriStatePropertyClaims@gmail.com

#### **CONTINUED - Front Left Bedroom**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
201. Window blind - horizontal or vertical - Detach & reset	2.00 EA		0.00	39.26	0.00	15.70	94.22
202. Window drapery - remove and rehang - per hour	1.00 HR		0.00	65.91	0.00	13.18	79.09
203. Remove 1/2" drywall - hung, taped, floated, ready for paint	96.00 SF		0.49	0.00	0.00	9.40	56.44
More has to be removed due to sagging j	from water loss an	d cutting back	to joists.				
204. 1/2" drywall - hung, taped, floated, ready for paint	112.88 SF		0.00	2.95	3.93	67.38	404.31
205. Additional cost for gluing drywall	112.88 SF		0.00	0.35	0.34	7.96	47.81
206. Drywall tape joint/repair - per LF	13.92 LF		0.00	10.03	0.28	27.98	167.88
207. Remove Blown-in insulation - 10" depth - R26	96.00 SF		1.02	0.00	0.00	19.58	117.50
208. Blown-in insulation - 10" depth - R26	112.88 SF		0.00	1.07	4.54	25.06	150.38
209. Mask the floor per square foot - plastic and tape - 4 mil	185.56 SF		0.00	0.22	0.56	8.28	49.66
210. R&R Wallpaper	339.82 SF		0.94	2.37	20.59	229.08	1,374.47
Textured wallpaper on walls. Due to tape	ing along wall, wa	llpaper will be	affected.				
211. Prep wall for wallpaper	339.82 SF		0.00	0.62	0.00	42.14	252.83
212. Seal/prime then paint the walls and ceiling twice (3 coats)	525.38 SF		0.00	1.18	8.51	125.70	754.16
213. Cold air return cover - Detach & reset	1.00 EA		0.00	23.67	0.00	4.74	28.41
214. Prime & paint cold air return (cover)	1.00 EA		0.00	15.46	0.26	3.16	18.88
215. Seal & paint door or window opening (per side)	5.00 EA		0.00	28.48	1.37	28.76	172.53
216. Seal & paint window sill	9.00 LF		0.00	2.32	0.13	4.20	25.21
217. Seal & paint baseboard - two coats	46.17 LF		0.00	1.35	0.30	12.52	75.15
218. Seal & paint door slab only (per side)	1.00 EA		0.00	34.28	0.46	6.96	41.70
219. Seal/Paint bypass door set - slab only- 2 coats (per side)	1.00 EA		0.00	41.47	0.71	8.44	50.62
220. Final cleaning - construction - Residential	185.56 SF		0.00	0.28	3.74	10.40	66.10
221. Clean and deodorize carpet	185.56 SF		0.00	0.49	6.66	18.20	115.78
Totals: Front Left Bedroom					53.10	722.88	4,347.51
Total: Level 2					205.63	2,155.88	12,950.81

36 Merry Turn Road Levittown PA 19056 267-609-4279 TriStatePropertyClaims@gmail.com

#### General

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
222. Dumpster load - Approx. 20 yards, 4 tons of debris	1.00 EA		593.00	0.00	0.00	118.60	711.60
223. Taxes, insurance, permits & fees (Bid Item)	1.00 EA		0.00	0.00	0.00	0.00	0.00
If permits are needed will bill as incurred.							
224. Lead Paint Safety (Bid Item)	1.00 EA		0.00	0.00	0.00	0.00	0.00
Totals: General					0.00	118.60	711.60
Labor Minimums Applied							
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
225. Heat, vent, & air cond. labor minimum	1.00 EA		0.00	225.05	0.00	45.02	270.07
226. Floor cleaning labor minimum	1.00 EA		0.00	65.50	4.72	13.10	83.32
227. Vinyl floor covering labor minimum	1.00 EA		0.00	166.78	0.00	33.36	200.14
228. Mirror/shower door labor minimum	1.00 EA		0.00	108.30	0.00	21.66	129.96
229. Cabinetry labor minimum	1.00 EA		0.00	12.83	0.00	2.56	15.39
Totals: Labor Minimums Applied					4.72	115.70	698.88
Line Item Totals: ISIK-REBUILD-1					526.04	5,909.28	35,497.82

### **Grand Total Areas:**

3,510.26	SF Walls	1,582.35	SF Ceiling	5,092.61	SF Walls and Ceiling
1,585.31	SF Floor	176.15	SY Flooring	481.69	LF Floor Perimeter
0.00	SF Long Wall	0.00	SF Short Wall	581.25	LF Ceil. Perimeter
1,585.31	Floor Area	1,718.69	Total Area	3,197.86	Interior Wall Area
2,531.46	Exterior Wall Area	383.17	Exterior Perimeter of		
			Walls		
0.00	Surface Area	0.00	Number of Squares	0.00	Total Perimeter Length
0.00	Total Ridge Length	0.00	Total Hip Length		

36 Merry Turn Road Levittown PA 19056 267-609-4279 TriStatePropertyClaims@gmail.com

## **Summary**

Line Item Total	29,062.50
Material Sales Tax	480.69
Cleaning Mtl Tax	0.93
Subtotal	29,544.12
Overhead	2,954.64
Profit	2,954.64
Cleaning Sales Tax	44.42
Replacement Cost Value	\$35,497.82
Net Claim	\$35,497.82

Gary Poltonowicz

36 Merry Turn Road Levittown PA 19056 267-609-4279 TriStatePropertyClaims@gmail.com

## Recap of Taxes, Overhead and Profit

Overhead (10%)	Profit (10%)	Material Sales Tax (6%)	Cleaning Mtl Tax (6%)	Cleaning Sales Tax (6%)	Clothing Acc Tax (6%)	Manuf. Home Tax (6%)	0	Dryclean/Laun dry Tax (6%)
Line Items								
2,954.64	2,954.64	480.69	0.93	44.42	0.00	0.00	0.00	0.00
Total								
2,954.64	2,954.64	480.69	0.93	44.42	0.00	0.00	0.00	0.00

36 Merry Turn Road Levittown PA 19056 267-609-4279 TriStatePropertyClaims@gmail.com

## **Recap by Room**


**Estimate: ISIK-REBUILD-1** 

Area	: Main Level		
	Office	1,987.92	6.84%
	Coat Closet	1,139.01	3.92%
	Entry/Foyer	885.36	3.05%
	Family Room	1,709.13	5.88%
	Hallway	725.37	2.50%
	Bathroom	6,003.57	20.66%
	Bedroom	3,818.79	13.14%
	Bedroom Closet	435.60	1.50%
	1st to 2nd Floor Stairs	455.07	1.57%
	Attic	141.92	0.49%
	Area Subtotal: Main Level	17,301.74	59.53%
Area	: Level 2		
	Master Bedroom	6,778.50	23.32%
	MB Closet	172.68	0.59%
	Hallway	66.59	0.23%
	Front Left Bedroom	3,571.53	12.29%
	Area Subtotal: Level 2	10,589.30	36.44%
	General	593.00	2.04%
	Labor Minimums Applied	578.46	1.99%
Subto	otal of Areas	29,062.50	100.00%
Total		29,062.50	100.00%

36 Merry Turn Road Levittown PA 19056 267-609-4279 TriStatePropertyClaims@gmail.com


## **Recap by Category**

O&P Items	Total	%
CABINETRY	178.58	0.50%
CLEANING	600.31	1.69%
CONTENT MANIPULATION	1,227.86	3.46%
CONT: PACKING,HANDLNG,STORAGE	15.60	0.04%
GENERAL DEMOLITION	2,290.77	6.45%
DOORS	199.17	0.56%
DRYWALL	2,928.83	8.25%
ELECTRICAL	103.61	0.29%
FLOOR COVERING - CARPET	3,098.69	8.73%
FLOOR COVERING - VINYL	205.82	0.58%
FLOOR COVERING - WOOD	2,529.29	7.13%
FINISH CARPENTRY / TRIMWORK	1,124.90	3.17%
HEAT, VENT & AIR CONDITIONING	289.73	0.82%
INSULATION	628.31	1.77%
LIGHT FIXTURES	675.90	1.90%
MIRRORS & SHOWER DOORS	164.78	0.46%
PLUMBING	663.41	1.87%
PAINTING	7,557.56	21.29%
TILE	2,896.90	8.16%
WINDOW TREATMENT	666.42	1.88%
WALLPAPER	1,016.06	2.86%
O&P Items Subtotal	29,062.50	81.87%
Material Sales Tax	480.69	1.35%
Cleaning Mtl Tax	0.93	0.00%
Overhead	2,954.64	8.32%
Profit	2,954.64	8.32%
Cleaning Sales Tax	44.42	0.13%
Total	35,497.82	100.00%





ISIK-REBUILD-1 Page: 22



Level 2

ISIK-REBUILD-1 Page: 23