

Home Again Emergency Services & Restoration Inc. 550 State Road Suite 114A
Bensalem PA 19020
215-888-1488

Client: Shannon McCarthy Property: 74 Roundwood

Collegeville, PA 19426

Operator: TRISTATE

Estimator: S. Bryant Business: (215) 758-1967

Company: Home Again Emergency Services & Restoration Inc

Business: 550 State Road Suite 114A

Bensalem, PA 19020

Type of Estimate: Other

Date Entered: 9/3/2021 Date Assigned:

Price List: PAPH8X\_SEP21

Labor Efficiency: Restoration/Service/Remodel

Estimate: MCCARTHY-ES
File Number: Metlife H7991957810




Home Again Emergency Services & Restoration Inc. 550 State Road Suite 114A
Bensalem PA 19020
215-888-1488

**Basement** 

#### **MCCARTHY-ES**

#### Main Level



1,152.00 SF Walls
2,140.00 SF Walls & Ceiling
109.78 SY Flooring
128.00 LF Ceil. Perimeter

988.00 SF Ceiling 988.00 SF Floor 128.00 LF Floor Perimeter

Height: 9'

DESCRIPTION **QTY** REMOVE TOTAL REPLACE TAX 24.00 SF 1. Containment Barrier/Airlock/Decon. 0.00 1.39 2.21 35.57 Chamber - after hours 2. Content Manipulation charge - per 4.00 HR 0.00 70.33 0.00 281.32 hour - after hours 3. Tear out wet non-salvage cpt, 494.00 SF 0.96 0.00 1.78 476.02 cut/bag - after hours 4. Tear out wet carpet pad, cut/bag -494.00 SF 0.91 0.00 1.78 451.32 after hours 5. Tear out non-salv floating floor & 30.00 SF 3.09 0.00 0.1492.84 bag - after hrs 6. Apply plant-based anti-microbial 1,142.00 SF 0.44 33.78 0.00 536.26 agent to more than the floor - after hrs 7. Tear out wet drywall, cleanup, bag, 0.00 77.00 LF 5.91 1.52 456.59 per LF - 2' aft hrs 8. Axial fan air mover - 1 HP (per 24 15.00 EA 0.00 36.75 33.08 584.33 hr period)-No monit. 5 for 3 days 9. Dehumidifier (per 24 hour period) -3.00 EA 0.00 108.75 19.58 345.83 XLarge - No monitoring 1 for 3 days Totals: Basement 93.87 3,260.08 Total: Main Level 93.87 3,260.08

#### General

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
10. Equip. setup, take down & monitoring - after hrs	1.50 HR	0.00	93.35	8.40	148.43
11. Equipment setup, take down, and monitoring (hourly charge)	1.50 HR	0.00	62.17	5.60	98.86

MCCARTHY-ES 9/26/2021 Page: 2



Home Again Emergency Services & Restoration Inc. 550 State Road Suite 114A
Bensalem PA 19020
215-888-1488

#### **CONTINUED - General**

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
12. Water Extraction & Remediation Technician - after hours	4.00 HR	0.00	93.35	22.40	395.80
13. Emergency service call - after business hours	1.00 EA	0.00	268.72	16.12	284.84
14. Single axle dump truck - per load - including dump fees	1.00 EA	366.56	0.00	0.00	366.56
Totals: General				52.52	1,294.49
Line Item Totals: MCCARTHY-ES				146.39	4,554.57

### **Grand Total Areas:**

1,152.00	SF Walls	988.00	SF Ceiling	2,140.00	SF Walls and Ceiling
988.00	SF Floor	109.78	SY Flooring	128.00	LF Floor Perimeter
0.00	SF Long Wall	0.00	SF Short Wall	128.00	LF Ceil. Perimeter
988.00	Floor Area	1,031.11	Total Area	1,152.00	Interior Wall Area
1,306.67	Exterior Wall Area	130.67	Exterior Perimeter of Walls		
0.00	Surface Area	0.00	Number of Squares	0.00	Total Perimeter Length
0.00	Total Ridge Length	0.00	Total Hip Length		

MCCARTHY-ES 9/26/2021 Page: 3



Home Again Emergency Services & Restoration Inc. 550 State Road Suite 114A
Bensalem PA 19020
215-888-1488

# **Summary**

Net Claim	\$4,554.57 
Replacement Cost Value	\$4,554.57
Subtotal Cleaning Sales Tax	4,417.03 137.54
Line Item Total  Material Sales Tax  Cleaning Mtl Tax	4,408.18 5.22 3.63

S. Bryant

MCCARTHY-ES 9/26/2021 Page: 4