

### Home Again Emergency Services & Restoration Inc.

Home Again Emergency Services & Restoration Inc. 550 State Road Suite 114A
Bensalem PA 19020
215-888-1488

Client: Tom Nguyen
Property: 5201 Tabor Road

Philadelphia, PA 19120

Operator: TRISTATE

Estimator: S. Bryant Business: (215) 758-1967

Company: Home Again Emergency Services & Restoration Inc

Business: 550 State Road Suite 114A

Bensalem, PA 19020

Type of Estimate: Other

Date Entered: 4/20/2021 Date Assigned:

Price List: PAPH8X\_APR21

Labor Efficiency: Restoration/Service/Remodel

Estimate: NGUYEN-ES File Number: 7002748245-1



# **Home Again Emergency Services & Restoration Inc.**

Home Again Emergency Services & Restoration Inc. 550 State Road Suite 114A
Bensalem PA 19020
215-888-1488

#### **NGUYEN-ES**

#### **Equipment**

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
Emergency service call - after business hours	1.00 EA	0.00	243.64	19.49	263.13
2. Equip. setup, take down & monitoring - after hrs	2.00 HR	0.00	84.58	13.53	182.69
3. Equipment setup, take down, and monitoring (hourly charge)	2.00 HR	0.00	56.33	9.01	121.67
4. Neg. air fan/Air scrubLarge (per 24 hr period)-No monit.	12.00 DA	0.00	121.73	116.86	1,577.62
4 for 3 days					
5. Add for HEPA filter (for neg. air machine/vacuum - Large)	1.00 EA	0.00	294.97	47.88	342.85
.25 filter per air scrubber					
6. Carbon vapor filter (for air scrubber)	4.00 EA	0.00	103.97	64.37	480.25
7. Equipment decontamination charge - per piece of equipment	4.00 EA	0.00	39.37	14.34	171.82
8. Deodorization	1.00 EA	0.00	280.00	22.40	302.40
Totals: Equipment				307.88	3,442.43
Line Item Totals: NGUYEN-ES				307.88	3,442.43

NGUYEN-ES 5/10/2021 Page: 2



## Home Again Emergency Services & Restoration Inc.

Home Again Emergency Services & Restoration Inc. 550 State Road Suite 114A
Bensalem PA 19020
215-888-1488

## **Summary**

Line Item Total	3,134.55
Cleaning Mtl Tax	52.89
Subtotal	3,187.44
Cleaning Sales Tax	254.99
Replacement Cost Value	\$3,442.43
Replacement Cost value	1-7
Net Claim	\$3,442.43
-	

S. Bryant

NGUYEN-ES 5/10/2021 Page: 3